

End-of-Sale and End-of-Life Announcement for the Cisco 12000 Series OC12c/STM-4 DPT Line Cards

EOL6283

Cisco® announces the end-of-sale and end-of life dates for the Cisco 12000 Series OC12c/STM-4 DPT Line Cards. The last day to order the affected product(s) is February 1, 2001. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

On February 1, 2001, the OC-12/SRP line cards having part numbers OC12/SRP-MM-SC(=), OC12/SRP-IR-SC(=), and OC12/SRP-LR-SC(=) will no longer be offered by Cisco. These products are being superseded by line cards with part numbers OC12/SRP-MM-SC-B(=), OC12/SRP-IR-SC-B(=), and OC12/SRP-LR-SC-B(=), which have identical functionality. The new part numbers have error-correcting code (ECC), and the memory options will be the same as the original parts. The new OC-12/SRP line cards require a minimum Cisco IOS Software version of 12.0(10)S or higher and 11.2(19)GS4 or higher. List price for the replacement line cards is the same as for the non-ECC versions. The new OC-12/SRP line cards are currently orderable. This end-of-life product bulletin is a re-creation of the original bulletin published on August 1, 2000.

Table 1. End-of-Life Milestones and Dates for the Cisco 12000 Series OC12c/STM-4 DPT Line Cards

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	August 1, 2000
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	February 1, 2001
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	October 31, 2004
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	November 20, 2005

HW = Hardware OS SW = Operating System Software App. SW = Application Software

- This product will no longer be orderable after February 1, 2001. All last-time-buy orders by customers must be received on or before this date.
- Service contracts on these products will not be renewed after October 31, 2004.
- These products will no longer be supported by Cisco after November 20, 2005.

For more information on the ECC upgrade and Increasing Network Availability plans, please review these links:

- <http://www.cisco.com/warp/public/779/largeent/learn/technologies/ina/>
- <http://www.cisco.com/warp/public/779/largeent/learn/technologies/ina/upgrade.html>

Contacts: If you have questions or need more information, please contact gsr-pm@cisco.com.
Bernard Lee Product Manager 12000 Series DPT Line Cards 408 525-7219

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
OC12/SRP-IR-SC	SRP Single Ring OC12 Linecard—SingleMode, IR optics	OC12/SRP-IR-SC-B	OC12 SRP IR line card
OC12/SRP-IR-SC=	OC12 SRP single ring linecard, single mode, IR, spare	OC12/SRP-IR-SC-B=	OC12 SRP IR line card
OC12/SRP-LR-SC	SRP Single Ring OC12 Linecard—SingleMode, LR optics	OC12/SRP-LR-SC-B	OC12 SRP LR line card
OC12/SRP-LR-SC=	OC12 SRP single ring linecard, single mode, LR, spare	OC12/SRP-LR-SC-B=	OC12 SRP LR line card
OC12/SRP-MM-SC	SRP Single Ring OC12 Linecard—multimode optics	OC12/SRP-MM-SC-B	OC12 SRP MM line card
OC12/SRP-MM-SC=	OC12 SRP single ring linecard, multimode, spare	OC12/SRP-MM-SC-B=	OC12 SRP MM line card

Product Migration Options

Customers are encouraged to migrate to the Cisco 12000 Series OC12c/STM-4 DPT Line Cards—Model B, with Error-Correcting Code (ECC). Information about this product can be found at: <http://www.cisco.com/en/US/products/hw/routers/ps167/index.html>.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through the Cisco Certified Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to: <http://cisco.com/go/remarketing>.

For More Information

For more information about the Cisco 12000 Series OC12c/STM-4 DPT Line Cards—Model B, with Error-Correcting Code, visit: <http://www.cisco.com/en/US/products/hw/routers/ps167/index.html>, or contact your local account representative.

To request information about the Cisco 12000 Series OC12c/STM-4 DPT Line Cards—Model B, with Error-Correcting Code, send an e-mail to ask-gsr-pm@cisco.com.

For more information about the Cisco End-of-Life Policy, go to:
http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive end-of-life/end-of-sale information, go to:
<http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.



Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Europe Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: +31 0 800 020 0791
Fax: +31 0 20 357 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

©2007 Cisco Systems, Inc. All rights reserved. CCVP, the Cisco logo, and Welcome to the Human Network are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, IP/TV, IQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, LightStream, Linksys, MeetingPlace, MGX, Networkers, Networking Academy, Network Registrar, PIX, ProConnect, ScriptShare, SMARTnet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0710R)