



**END-OF-LIFE NOTICE, NO. 2289**

## END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR THE CISCO MWR 1900 MOBILE WIRELESS EDGE ROUTER

Cisco Systems® announces the End-of-Life of the Cisco® MWR 1900 Mobile Wireless Edge Router. This router has been replaced by the Cisco MWR 1941-DC Mobile Wireless Edge Router, which provides a universal DC power supply. The last day to order the Cisco MWR 1900 Mobile Wireless Edge Router is March 5, 2004. Customers will continue to receive support from the Cisco Technical Assistance Center (TAC) until March 5, 2009.

Table 1 describes End-of-Life milestones, definitions, and important dates for the Cisco MWR 1900 Mobile Wireless Edge Router. Table 2 lists the products and associated part numbers that will no longer be available as of March 5, 2004. Table 3 lists the replacement products and associated part numbers.

**Table 1.** End-of-Life Milestones and Dates for the Cisco MWR 1900 Mobile Wireless Edge Router

Milestone	Definition	Date
End-of-Life Announcement Date	The date that the document announcing the End-of-Sale and End-of-Life of a product is distributed to the general public.	September 5, 2003
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	March 5, 2004
Last Shipment Date	The last-possible shipping date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead-time.	June 5, 2004
End of Software Maintenance Release Date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	March 5, 2005
End of Routine Failure Analysis Date	The last possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	March 5, 2005
End of New Service Attachment Date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and- support contract or add the equipment and/or software to an existing service-and-support contract.	March 5, 2005
End of Service Contract Renewal Date	The last date to extend or renew a service contract for the product. The extension or renewal period cannot extend beyond the last date of support.	December 5, 2008
Last Date of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	March 5, 2009

**Table 2.** Product Part Numbers Affected by this Announcement

End-of-Sale Product Part Number	Product Description
MWR-1900-27	High-performance, 10/100 dual Ethernet mobile wireless edge router with extended temperature, 27V DC, PXF, 3 WIC slots, 1 network module slot
MWR-1900-27-2T1	Bundle: (1) MWR-1900-27 and (1) VWIC-2MFT-T1-DIR
MWR-1900-27-2E1	Bundle: (1) MWR-1900-27 and (1) VWIC-2MFT-E1-DIR

**Table 3.** Replacement Product and Part Numbers

Replacement Product Part Number	Product Description
MWR-1941-DC	High-performance, 10/100 dual Ethernet mobile wireless edge router with extended temperature, 20-60V DC, PXF, 3 WIC slots, 1 network module slot
MWR-1941-DC-2T1	Bundle: (1) MWR-1941-DC and (1) VWIC-2MFT-T1-DIR
MWR-1941-DC-2E1	Bundle: (1) MWR-1941-DC and (1) VWIC-2MFT-E1-DIR

For more information about Cisco products, please contact your Cisco account manager and/or Cisco Channel Partner.

For more information about the Cisco End-of-Life Policy, go to: [http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html)

To subscribe to receive End-of-Life/End-of-Sale information, please go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>

**Corporate Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

**European Headquarters**

Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www-europe.cisco.com  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

**Americas Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

**Asia Pacific Headquarters**

Cisco Systems, Inc.  
168 Robinson Road  
#28-01 Capital Tower  
Singapore 068912  
www.cisco.com  
Tel: +65 6317 7777  
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica  
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR  
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico  
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia  
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan  
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2005 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StrataView Plus, TeleRouter, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R) VS/LW8343 04/05

