



## END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR THE ORIGINAL LOW-SPEED FAN MODULES FOR USE WITH THE CISCO 7603 AND 7606 ROUTERS

Cisco Systems® announces the end-of-sale and end-of-life dates for the original low-speed fan modules for use with the Cisco® 7603 Router and Cisco 7606 Router. Customers are encouraged to use the latest variable high-speed fan modules with the Cisco 7603 and 7606 routers. The new variable high-speed fan modules offer better system cooling, which is required by the Supervisor Engine 720. The last day to order the low-speed fan modules is September 14, 2005. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until September 14, 2010. Table 1 describes the end-of-life milestones, definitions, and dates for the affected products. Table 2 lists the product numbers affected by this announcement. Table 3 provides relevant information for migrating to high-speed fan modules.

Table 1. End-of-Life Milestones and Dates for the Low-Speed Fan Modules for Cisco 7603 and 7606 Routers

Milestone	Definition	Date
End-of-life announcement date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	March 14, 2005
End-of-sale date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	September 14, 2005
Last shipment date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	December 14, 2005
End of software maintenance releases date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	September 14, 2006
End of routine failure analysis date	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	September 14, 2006
End of new service attachment date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	September 14, 2006
End of service contract renewal date	The last date to extend or renew a service contract for the product. The extension or renewal period cannot extend beyond the last date of support.	June 14, 2010
Last date of support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	September 14, 2010

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
FAN-MOD-3=	Spare Standard Fan Mod for Cisco 7603 Cisco Catalyst® 6503 Chassis
PICK-FAN-MOD-3	Standard Fan Module (Sup2 version) for Cisco 7603 Chassis
FAN-MOD-6	Fan Module for Cisco 7606 Chassis
FAN-MOD-6=	Fan Module for Cisco 7606 Chassis

**Table 3.** Product Migration Options

End-of-Sale Product Part Number	Replacement Product Part Number	Replacement Product Description
FAN-MOD-3=	FAN-MOD-3HS	High Speed Fan Module for Cisco 7603/Catalyst 6503
PICK-FAN-MOD-3	PICK-FAN-MOD-3HS	High Speed Fan Module for Cisco 7603, for SUP720 or Sup2
FAN-MOD-6	FAN-MOD-6HS	High Speed Fan Module for Cisco 7606 Chassis
FAN-MOD-6=	FAN-MOD-6HS=	High Speed Fan Module for Cisco 7606 Chassis

For more information, visit:

[http://www.cisco.com/en/US/prod/collateral/switches/ps5718/ps708/product\\_data\\_sheet09186a0080159856.html](http://www.cisco.com/en/US/prod/collateral/switches/ps5718/ps708/product_data_sheet09186a0080159856.html).

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

## FOR MORE INFORMATION

For more information about the Cisco 7600 Series Router, visit: <http://cisco.com/en/US/products/hw/routers/ps368/index.html> or contact your local account representative or [ask-osr-pm@cisco.com](mailto:ask-osr-pm@cisco.com).

For more information about the Cisco End-of-Life Policy, go to [http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html).

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.

**Corporate Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

**European Headquarters**

Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www-europe.cisco.com  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

**Americas Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

**Asia Pacific Headquarters**

Cisco Systems, Inc.  
168 Robinson Road  
#28-01 Capital Tower  
Singapore 068912  
www.cisco.com  
Tel: +65 6317 7777  
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica  
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR  
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico  
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia  
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan  
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2005 Cisco Systems, Inc. All rights reserved. Catalyst, Cisco, Cisco Systems, and the Cisco Systems logo are registered trademarks or trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0501R) Pa/LW7821 02/05