

End-of-Sale and End-of-Life Announcement for the Cisco IPS 4250 SX and XL Sensors and Additional Supporting Hardware

EOL4103, Amended

Cisco® announces the end-of-sale and end-of life dates for the Cisco IPS 4250 SX and XL Sensors and Additional Supporting Hardware. The last day to order the affected product(s) is May 24, 2006. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the Cisco IPS 4250 SX and XL Sensors and Additional Supporting Hardware

Milestone	Definition	Date
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 24, 2006
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	June 1, 2006
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	August 25, 2007
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	August 25, 2007
End of Signature Update and Support	The last date to receive new signature updates and signature support for the product. After this date, new signature updates are unavailable.	May 24, 2009
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	November 21, 2010
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	August 24, 2011

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
IDS-4210-MEM-U	256MB RAM upgrade	There is currently no replacement product available for this product.	
IDS-4210-MEM-U=	256MB memory Upgrade for IDS-4210 Appliance Sensor	There is currently no replacement product available for this product.	
IDS-4230-PKG=	IDS 4230 Packing for Upgrade Program	There is currently no replacement product available for this product.	

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
IDS-4250-SX-K9	4250 Sensor (chassis, s/w, SSH, 1000BaseSX w/ SC connector)	See Product Migration Options section for details.	IPS 4255, IPS 4260
IDS-4250-XL-K9	IDS 4250 chassis, s/w, IDS Accelerated 1000BaseSX w/ MT-RJ	See Product Migration Options section for details.	IPS 4255, IPS 4260
IDS-PWR	Spare Power Supply for the IDS 4235/4250 Appliance Sensors	There is currently no replacement product available for this product.	
IDS-PWR=	Spare Power Supply for the IDS 4235/4250 Appliance Sensors	There is currently no replacement product available for this product.	
IDS-RAIL-2	2 post Rail Kits for the IDS 4235/4250 Sensor Platforms	There is currently no replacement product available for this product.	
IDS-RAIL-2=	2 post Rail Kits for the IDS 4235/4250 Sensor Platforms	There is currently no replacement product available for this product.	
IDS-RAIL-4	4 post Rail Kits for the IDS 4235/4250 Sensor Platforms	There is currently no replacement product available for this product.	
IDS-RAIL-4=	4 post Rail Kits for the IDS 4235/4250 Sensor Platforms	There is currently no replacement product available for this product.	
IDS-SCSI=	Spare SCSI Hard Disk Drive for IDS 4250 Appliance Sensor	There is currently no replacement product available for this product.	

Product Migration Options

Cisco IDS 4250 customers are encouraged to migrate to Cisco IPS 4255. Cisco IPS 4260 is ideal for customers with fiber or higher performance requirements. For information about the Cisco IPS 4255 and IPS 4260 Sensors, visit

<http://www.cisco.com/en/US/products/hw/vpndevc/ps4077/index.html>.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the Cisco IPS 4250 SX and XL Sensors and Additional Supporting Hardware through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to <http://www.cisco.com/go/eos>

Service prices for Cisco products are subject to change after the product End of Sale date.

For More Information

For more information about the Cisco IPS 4255 and IPS 4260 Sensors, visit <http://www.cisco.com/en/US/products/hw/vpndevc/ps4077/index.html>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life/end-of-sale information, go to <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV
Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

CCDE, CCENT, Cisco Eos, Cisco Lumin, Cisco Nexus, Cisco StadiumVision, Cisco TelePresence, the Cisco logo, DCE, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn and Cisco Store are service marks; and Access Registrar, Aironet, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, EtherFast, EtherSwitch, Event Center, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MeetingPlace Chime Sound, MGX, Networkers, Networking Academy, Network Registrar, PCNow, PIX, PowerPanels, ProConnect, ScriptShare, SenderBase, SMARTnet, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0807R)

Printed in USA

C51-496224-00 0 9/08