

# End-of-Sale and End-of-Life Announcement for the Cisco Fabric Interconnect 6400 Series

---

# Contents

Overview	3
End-of-life milestones	3
Product part numbers	4
Product Migration Options	8
For more information	9

## Overview

### EOL15931 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Cisco Fabric Interconnect 6400 Series. The last day to order the affected product(s) is December 22, 2026. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

### End-of-life milestones

**Table 1.** End-of-life milestones and dates for the Cisco Fabric Interconnect 6400 Series

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	June 23, 2026
<b>End-of-Sale Date: HW</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	December 22, 2026
<b>Last Ship Date: HW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	March 22, 2027
<b>End of SW Maintenance Releases Date: HW</b>	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	December 22, 2027
<b>End of Vulnerability/Security Support: HW</b>	The last date that Cisco Engineering may release a planned maintenance release or scheduled software remedy for a security vulnerability issue.	December 31, 2031
<b>End of Routine Failure Analysis Date: HW</b>	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	December 22, 2027
<b>End of New Service Attachment Date: HW</b>	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	December 22, 2027
<b>End of Service Contract Renewal Date: HW</b>	The last date to extend or renew a service contract for the product.	March 19, 2031
<b>Last Date of Support: HW</b>	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	December 31, 2031

HW = Hardware      OS SW = Operating System Software      App. SW = Application Software

## Product part numbers

**Table 2.** Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description	Migration Product Part Number	Migration Product Description	Additional Information
<b>HCI-FI-64108</b>	Cisco Compute Hyperconverged Fabric Interconnect 64108	HCI-FI-6652	6th Generation UCS Fabric Interconnect 1RU 25G Eth, 64G FC	-
<b>HCI-FI-64108</b>	Cisco Compute Hyperconverged Fabric Interconnect 64108	HCI-FI-6664	6th Generation UCS Fabric Interconnect 2RU 100G Eth, 64G FC	-
<b>HCI-FI-6454</b>	Cisco Compute Hyperconverged Fabric Interconnect 6454	HCI-FI-6652	6th Generation UCS Fabric Interconnect 1RU 25G Eth, 64G FC	-
<b>HCI-FI-6454</b>	Cisco Compute Hyperconverged Fabric Interconnect 6454	HCI-FI-6664	6th Generation UCS Fabric Interconnect 2RU 100G Eth, 64G FC	-
<b>HCIX-FI-64108</b>	Cisco Compute Hyperconverged X Fabric Interconnect 64108	There is currently no migration product available for this product.	-	-
<b>HCIX-FI-6454</b>	Cisco Compute Hyperconverged X Fabric Interconnect 6454	HCI-FI-6652	6th Generation UCS Fabric Interconnect 1RU 25G Eth, 64G FC	-
<b>HCIX-FI-6454</b>	Cisco Compute Hyperconverged X Fabric Interconnect 6454	HCI-FI-6664	6th Generation UCS Fabric Interconnect 2RU 100G Eth, 64G FC	-
<b>HCIX-FI-6454-FRE</b>	XCellerate offer for Fabric Interconnect 6454	There is currently no migration product available for this product.	-	-
<b>UCS-FI-64108+ +=</b>	UCS Fabric Interconnect 64108 with 3 Fans, TAA	There is currently no migration product available for this product.	-	-
<b>UCS-FI-64108-CH</b>	DISTI-UCS Fabric Interconnect 64108	UCS-FI-6652-U	6th GEN UCS Fabric Interconnect 1RU 10/25/50G Eth, 64G FC	-
<b>UCS-FI-64108-CH</b>	DISTI-UCS Fabric Interconnect 64108	UCS-FI-6664-U	6th Generation UCS Fabric Interconnect 2RU 100G Eth, 64G FC	-
<b>UCS-FI-64108-D-CH</b>	DISTI-UCS Fabric Interconnect 64108	There is currently no migration product available for this product.	-	-
<b>UCS-FI-64108-D-</b>	UCS Fabric Interconnect	UCS-FI-6652-U	6th GEN UCS Fabric	-

End-of-Sale Product Part Number	Product Description	Migration Product Part Number	Migration Product Description	Additional Information
<b>U</b>	64108		Interconnect 1RU 10/25/50G Eth, 64G FC	
<b>UCS-FI-64108-D-U</b>	UCS Fabric Interconnect 64108	UCS-FI-6664-U	6th Generation UCS Fabric Interconnect 2RU 100G Eth, 64G FC	-
<b>UCS-FI-64108-D=</b>	UCS Fabric Interconnect 64108	UCS-FI-6652-U	6th GEN UCS Fabric Interconnect 1RU 10/25/50G Eth, 64G FC	-
<b>UCS-FI-64108-D=</b>	UCS Fabric Interconnect 64108	UCS-FI-6664-U	6th Generation UCS Fabric Interconnect 2RU 100G Eth, 64G FC	-
<b>UCS-FI-64108-U</b>	UCS Fabric Interconnect 64108	UCS-FI-6652-U	6th GEN UCS Fabric Interconnect 1RU 10/25/50G Eth, 64G FC	-
<b>UCS-FI-64108-U</b>	UCS Fabric Interconnect 64108	UCS-FI-6664-U	6th Generation UCS Fabric Interconnect 2RU 100G Eth, 64G FC	-
<b>UCS-FI-64108=</b>	UCS Fabric Interconnect 64108	There is currently no migration product available for this product.	-	-
<b>UCS-FI-6454</b>	UCS Fabric Interconnect 6454	UCS-FI-6652-U	6th GEN UCS Fabric Interconnect 1RU 10/25/50G Eth, 64G FC	-
<b>UCS-FI-6454</b>	UCS Fabric Interconnect 6454	UCS-FI-6664-U	6th Generation UCS Fabric Interconnect 2RU 100G Eth, 64G FC	-
<b>UCS-FI-6454++=</b>	UCS Fabric Interconnect 6454 with 4 Fans, TAA	There is currently no migration product available for this product.	-	-
<b>UCS-FI-6454-CH</b>	DISTI-UCS Fabric Interconnect 6454	UCS-FI-6652-U	6th GEN UCS Fabric Interconnect 1RU 10/25/50G Eth, 64G FC	-
<b>UCS-FI-6454-CH</b>	DISTI-UCS Fabric Interconnect 6454	UCS-FI-6664-U	6th Generation UCS Fabric Interconnect 2RU 100G Eth, 64G FC	-
<b>UCS-FI-6454-D-CH</b>	DISTI-UCS Fabric Interconnect 6454	There is currently no migration product available for this product.	-	-
<b>UCS-FI-6454-D-U</b>	UCS Fabric Interconnect 6454	UCS-FI-6652-U	6th GEN UCS Fabric Interconnect 1RU 10/25/50G Eth, 64G FC	-

End-of-Sale Product Part Number	Product Description	Migration Product Part Number	Migration Product Description	Additional Information
<b>UCS-FI-6454-D-U</b>	UCS Fabric Interconnect 6454	UCS-FI-6664-U	6th Generation UCS Fabric Interconnect 2RU 100G Eth, 64G FC	-
<b>UCS-FI-6454-D=</b>	UCS Fabric Interconnect 6454	There is currently no migration product available for this product.	-	-
<b>UCS-FI-6454-U</b>	UCS Fabric Interconnect 6454	UCS-FI-6652-U	6th GEN UCS Fabric Interconnect 1RU 10/25/50G Eth, 64G FC	-
<b>UCS-FI-6454-U</b>	UCS Fabric Interconnect 6454	UCS-FI-6664-U	6th Generation UCS Fabric Interconnect 2RU 100G Eth, 64G FC	-
<b>UCS-FI-6454=</b>	UCS Fabric Interconnect 6454	UCS-FI-6652-U	6th GEN UCS Fabric Interconnect 1RU 10/25/50G Eth, 64G FC	-
<b>UCS-FI-6454=</b>	UCS Fabric Interconnect 6454	UCS-FI-6664-U	6th Generation UCS Fabric Interconnect 2RU 100G Eth, 64G FC	-
<b>UCSX-FI-64108</b>	UCS Fabric Interconnect 64108	There is currently no migration product available for this product.	-	-
<b>UCSX-FI-64108-CH</b>	DISTI-UCS Fabric Interconnect 64108	There is currently no migration product available for this product.	-	-
<b>UCSX-FI-64108-D-CH</b>	DISTI-UCS Fabric Interconnect 64108	There is currently no migration product available for this product.	-	-
<b>UCSX-FI-64108-D-U</b>	UCS Fabric Interconnect 64108	UCS-FI-6652-U	6th GEN UCS Fabric Interconnect 1RU 10/25/50G Eth, 64G FC	-
<b>UCSX-FI-64108-D-U</b>	UCS Fabric Interconnect 64108	UCS-FI-6664-U	6th Generation UCS Fabric Interconnect 2RU 100G Eth, 64G FC	-
<b>UCSX-FI-64108-U</b>	UCS Fabric Interconnect 64108	UCS-FI-6652-U	6th GEN UCS Fabric Interconnect 1RU 10/25/50G Eth, 64G FC	-
<b>UCSX-FI-64108-U</b>	UCS Fabric Interconnect 64108	UCS-FI-6664-U	6th Generation UCS Fabric Interconnect 2RU 100G Eth, 64G FC	-

End-of-Sale Product Part Number	Product Description	Migration Product Part Number	Migration Product Description	Additional Information
<b>UCSX-FI-64108=</b>	UCS Fabric Interconnect 64108	There is currently no migration product available for this product.	-	-
<b>UCSX-FI-6454</b>	UCS Fabric Interconnect 6454	There is currently no migration product available for this product.	-	-
<b>UCSX-FI-6454-CH</b>	DISTI-UCS Fabric Interconnect 6454	There is currently no migration product available for this product.	-	-
<b>UCSX-FI-6454-D-CH</b>	DISTI-UCS Fabric Interconnect 6454	There is currently no migration product available for this product.	-	-
<b>UCSX-FI-6454-D-U</b>	UCS Fabric Interconnect 6454	UCS-FI-6652-U	6th GEN UCS Fabric Interconnect 1RU 10/25/50G Eth, 64G FC	-
<b>UCSX-FI-6454-D-U</b>	UCS Fabric Interconnect 6454	UCS-FI-6664-U	6th Generation UCS Fabric Interconnect 2RU 100G Eth, 64G FC	-
<b>UCSX-FI-6454-NEW-D</b>	XCellerate offer for Fabric Interconnect 6454	UCS-FI-6652-U	6th GEN UCS Fabric Interconnect 1RU 10/25/50G Eth, 64G FC	-
<b>UCSX-FI-6454-NEW-D</b>	XCellerate offer for Fabric Interconnect 6454	UCS-FI-6664-U	6th Generation UCS Fabric Interconnect 2RU 100G Eth, 64G FC	-
<b>UCSX-FI-6454-U</b>	UCS Fabric Interconnect 6454	UCS-FI-6652-U	6th GEN UCS Fabric Interconnect 1RU 10/25/50G Eth, 64G FC	-
<b>UCSX-FI-6454-U</b>	UCS Fabric Interconnect 6454	UCS-FI-6664-U	6th Generation UCS Fabric Interconnect 2RU 100G Eth, 64G FC	-

End-of-Sale Product Part Number	Product Description	Migration Product Part Number	Migration Product Description	Additional Information
<b>UCSX-FI-6454=</b>	UCS Fabric Interconnect 6454	There is currently no migration product available for this product.	-	-
<b>UCS-FI-64108</b>	UCS Fabric Interconnect 64108	There is currently no migration product available for this product.	-	-
<b>UCS-FI-64108-U-BR</b>	UCS Fabric Interconnect 64108 for Brazil	There is currently no migration product available for this product.	-	-
<b>UCS-FI-6454-U-BR</b>	UCS Fabric Interconnect 6454 for Brazil	There is currently no migration product available for this product.	-	-

## Product Migration Options

Customers may be able to use the Cisco Takeback and Reuse Program where applicable to return hardware that has reached end-of-use, at no cost. Returned products are put to their next best use, whether reused, remanufactured, or recycled by one of Cisco's certified contracted recyclers. For more information, go to: <https://www.cisco.com/c/en/us/about/takeback-and-reuse.html>.

Customers may be able to continue to purchase the Cisco Fabric Interconnect 6400 Series through the Cisco Refresh (certified remanufactured) program. Remanufactured units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Refresh program, go to: <https://www.cisco.com/c/en/us/products/remanufactured.html>.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to: <https://www.cisco.com/c/en/us/about/takeback-and-reuse/product-recycling.html>.

---

## For more information

For more information about the Cisco End-of-Life Policy, go to: <https://www.cisco.com/c/en/us/products/eos-eol-policy.html>.

For more information about the Cisco Product Warranties, go to: <https://www.cisco.com/c/en/us/products/warranty-listing.html>.

To subscribe to receive end-of-life/end-of-sale information, go to: <https://cway.cisco.com/mynotifications>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)