

End-of-Sale and End-of-Life Announcement for the Cisco Select UCS accessories

Contents

| | |
|---------------------------|---|
| Overview | 3 |
| End-of-life milestones | 3 |
| Product part numbers | 3 |
| Product migration options | 9 |
| For more information | 9 |

Overview

EOL15235

Cisco announces the end-of-sale and end-of life dates for the Cisco Select UCS accessories. The last day to order the affected product(s) is April 25, 2024. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

End-of-life milestones

Table 1. End-of-life milestones and dates for the Cisco Select UCS accessories

| Milestone | Definition | Date |
|--------------------------------------|---|------------------|
| End-of-Life Announcement Date | The date the document that announces the end of sale and end of life of a product is distributed to the general public. | January 25, 2024 |
| End-of-Sale Date Accessory | The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date. | April 25, 2024 |
| Last Ship Date Accessory | The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time. | July 24, 2024 |

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Product part numbers

Table 2. Product Part Numbers Affected by This Announcement

| Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|--|---|---------------------------------|------------------------|
| 2.0GHz 7251/120W 8C/32MB DDR4 2400MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.0GHz 7251/120W 8C/32MB DDR4 2400MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |

| Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|--|---|---------------------------------|------------------------|
| DISTI: 2.0GHz 7251/120W 8C/32MB DDR4 2400MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.5GHz 7261/170W 8C/64 MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.5GHz 7261/170W 8C/64 MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| DISTI: 2.5GHz 7261/170W 8C/64 MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.1GHz 7281/170W 16C/32MB DDR4 2667MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.1GHz 7281/170W 16C/32MB DDR4 2667MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| DISTI: 2.1GHz 7281/170W 16C/32MB DDR4 2667MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.2GHz 7301/170W 16C/64MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.2GHz 7301/170W 16C/64MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |

| Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---|---|---------------------------------|------------------------|
| DISTI: 2.2GHz 7301/170W 16C/64MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.4GHz 7351/170W 16C/64MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.4GHz 7351/170W 16C/64MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| DISTI: 2.4GHz 7351/170W 16C/64MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.4GHz 7351P/170W 16C/64MB DDR4 2667MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.4GHz 7351P/170W 16C/64MB DDR4 2667MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| DISTI: 2.4GHz 7351P/170W 16C/64MB DDR4 2667MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.0GHz 7401/170W 24C/64MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.0GHz 7401/170W 24C/64MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |

| Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---|---|---------------------------------|------------------------|
| DISTI: 2.0GHz 7401/170W 24C/64MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.0GHz 7401P/170W 24C/64MB DDR4 2667MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.0GHz 7401P/170W 24C/64MB DDR4 2667MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| DISTI: 2.0GHz 7401P/170W 24C/64MB DDR4 2667MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.3GHz 7451/180W 24C/64MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.3GHz 7451/180W 24C/64MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| DISTI: 2.3GHz 7451/180W 24C/64MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.0GHz 7501/170W 32C/64MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.0GHz 7501/170W 32C/64MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |

| Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---|---|---------------------------------|------------------------|
| DISTI: 2.0GHz 7501/170W 32C/64MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.0GHz 7551/180W 32C/64MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.0GHz 7551/180W 32C/64MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| DISTI: 2.0GHz 7551/180W 32C/64MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.0GHz 7551P/180W 32C/64MB DDR4 2667MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.0GHz 7551P/180W 32C/64MB DDR4 2667MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| DISTI: 2.0GHz 7551P/180W 32C/64MB DDR4 2667MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.2GHz 7601/180W 32C/64MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 2.2GHz 7601/180W 32C/64MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |

| Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---|---|---|------------------------|
| DISTI: 2.2GHz 7601/180W 32C/64MB DDR4 2666MHz | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| 3.2TB 2.5in U.2 WD SN840 NVMe Extreme Perf. High Endurance | UCS-NVME4-3200 | 3.2TB 2.5in U.2 15mm P5620 Hg Perf Hg End NVMe (3X) | - |
| 3.2TB 2.5in U.2 WD SN840 NVMe Extreme Perf. High Endurance | UCS-NVMEG4-M3200 | 3.2TB 2.5in U.3 15mm P7450 Hg Perf Hg End NVMe (3X) | - |
| 3.2TB 2.5in U.2 WD SN840 NVMe Extreme Perf. High Endurance | UCS-NVME4-3200= | 3.2TB 2.5in U.2 15mm P5620 Hg Perf Hg End NVMe (3X) | - |
| 3.2TB 2.5in U.2 WD SN840 NVMe Extreme Perf. High Endurance | UCS-NVMEG4-M3200= | 3.2TB 2.5in U.3 15mm P7450 Hg Perf Hg End NVMe (3X) | - |
| 3.2TB 2.5in U.2 WD SN840 NVMe Extreme Perf. High Endurance | UCSX-NVME4-3200-D | 3.2TB 2.5in U.2 15mm P5620 Hg Perf Hg End NVMe (3X) | - |
| 3.2TB 2.5in U.2 WD SN840 NVMe Extreme Perf. High Endurance | UCSX-NVMEG4M3200D | 3.2TB 2.5in U.3 15mm P7450 Hg Perf Hg End NVMe (3X) | - |
| 3.2TB 2.5in U.2 WD SN840 NVMe Extreme Perf. High Endurance | UCSX-NVME4-3200-D= | 3.2TB 2.5in U.2 15mm P5620 Hg Perf Hg End NVMe (3X) | - |
| 3.2TB 2.5in U.2 WD SN840 NVMe Extreme Perf. High Endurance | UCSX-NVMEG4M3200D= | 3.2TB 2.5in U.3 15mm P7450 Hg Perf Hg End NVMe (3X) | - |
| 3.2TB 2.5in U.2 WD SN840 NVMe Extreme Perf. High Endurance | UCSX-NVME4-3200 | 3.2TB 2.5in U.2 15mm P5620 Hg Perf Hg End NVMe (3X) | - |
| 3.2TB 2.5in U.2 WD SN840 NVMe Extreme Perf. High Endurance | UCSX-NVMEG4-M3200 | 3.2TB 2.5in U.3 15mm P7450 Hg Perf Hg End NVMe (3X) | - |
| 3.2TB 2.5in U.2 WD SN840 NVMe Extreme Perf. High Endurance | UCSX-NVME4-3200= | 3.2TB 2.5in U.2 15mm P5620 Hg Perf Hg End NVMe (3X) | - |
| 3.2TB 2.5in U.2 WD SN840 NVMe Extreme Perf. High Endurance | UCSX-NVMEG4-M3200= | 3.2TB 2.5in U.3 15mm P7450 Hg Perf Hg End NVMe (3X) | - |
| 3.2TB 2.5in U.2 WD SN840 NVMe Extreme Perf. High Endurance | UCSB-NVME4-3200 | 3.2TB 2.5in U.2 Intel P5620 NVMe High Perf High Endurance | - |

| Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---|---------------------------------|---|------------------------|
| 3.2TB 2.5in U.2 WD SN840 NVMe Extreme Perf. High Endurance | UCSB-NVME4-3200= | 3.2TB 2.5in U.2 Intel P5620 NVMe High Perf High Endurance | - |
| 3.2TB 3.5in U.2 WD SN840 NVMe Extreme Perf. High Endurance | UCS-NVME4-1600 | 1.6TB 2.5in U.2 15mm P5620 Hg Perf Hg End NVMe (3X) | - |
| 3.2TB 3.5in U.2 WD SN840 NVMe Extreme Perf. High Endurance | UCS-NVME4-1600= | 1.6TB 2.5in U.2 15mm P5620 Hg Perf Hg End NVMe (3X) | - |

Product migration options

Customers For UCS-CPU PIDs there is no direct replacement. Consider the 7xx2 and 7xx3 CPU generations.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For more information

For more information about the Cisco End-of-Life Policy, go to:

<https://www.cisco.com/c/en/us/products/eos-eol-policy.html>.

For more information about the Cisco Product Warranties, go to:

<https://www.cisco.com/c/en/us/products/warranty-listing.html>.

To subscribe to receive end-of-life/end-of-sale information, go to:

<https://cway.cisco.com/mynotifications>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.\

Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)