

End-of-Sale and End-of-Life Announcement for the Cisco UCS Fabric Interconnect (FI 6332, FI 6332-16UP)

Contents

Overview	3
End-of-life milestones	3
Product part numbers	4
Product migration options	4
For more information	5

Overview

EOL15063 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Cisco UCS Fabric Interconnect (FI 6332, FI 6332-16UP). The last day to order the affected product(s) is October 30, 2023. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

End-of-life milestones

Table 1. End-of-Life Milestones and Dates for the Cisco UCS Fabric Interconnect (FI 6332, FI 6332-16UP)

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	May 1, 2023
End-of-Sale Date : HW	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	October 30, 2023
Last Ship Date : HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	January 28, 2024
End of Routine Failure Analysis Date : HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	October 29, 2024
End of New Service Attachment Date : HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	October 29, 2024
End of Service Contract Renewal Date : HW	The last date to extend or renew a service contract for the product.	January 25, 2028
Last Date of Support : HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	October 31, 2028

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Cisco goes through a very rigorous process to ensure that customers receive support. However in rare occasions, due to component supplier limitations, there may be a need for customer to migrate to a part that is an upgrade of something comparable or better than what they previously bought. This may require customer to upgrade to a different Software and OS version or even the closest generation of an equivalent server that may be currently shipping at the time.

Product part numbers

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
UCS-FI-6332	UCS 6332 1RU Fabric Interconnect/No PSU/32 QSFP+ports/8p Lic
UCS-FI-6332-16-CH	DISTI-UCS 6332-16UP FI/No PSU/24QSFP+16UP/4x40G Lic/8xUP Lic
UCS-FI-6332-16UP	UCS 6332-16UP 1RU FI/No PSU/24 QSFP+ 16UP/4x40G Lic/8xUP Lic
UCS-FI-6332-16UP-U	UCS 6332-16UP 1RU FI/No PSU/24 QSFP+ 16UP/4x40G Lic/8xUP Lic
UCS-FI-6332-16UP=	UCS 6332-16UP 1RU FI/No PSU/24 QSFP+ 16UP/4x40G Lic/8xUP Lic
UCS-FI-6332-CH	DISTI-UCS 6332 1RU FI/No PSU/32 QSFP+ports/8p Lic
UCS-FI-6332-U	UCS 6332 1RU Fabric Interconnect/No PSU/32 QSFP+ports/8p Lic
UCS-FI-6332=	UCS 6332 1RU Fabric Interconnect/No PSU/32 QSFP+ports/8p Lic
UCS-MAFI-6332	Microsoft Azure Stack FI 6332/32 QSFP+/8p Lic included
UCS-PSU-6332-NAC	UCS 6332 NEBS 650W V2 AC Power Supply (100-240V)
UCS-PSU-6332-NAC=	UCS 6332 NEBS 650W V2 AC Power Supply (100-240V)
UCS-PSU-6332-NDC	UCS 6332 NEBS DC Power Supply
UCS-PSU-6332-NDC=	UCS 6332 NEBS DC Power Supply
HX-C480-CM	UCS C480 M5 CPU Module w/o CPU, mem
HX-C480-CM=	UCS C480 M5 CPU Module w/o CPU, mem

Product migration options

There is no replacement available for the Cisco UCS Fabric Interconnect (FI 6332, FI 6332-16UP) at this time.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

https://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco UCS Fabric Interconnect (FI 6332, FI 6332-16UP) through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to:

<https://www.cisco.com/go/eos>.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For more information

For more information about the Cisco End-of-Life Policy, go to: <https://www.cisco.com/c/en/us/products/eos-eol-policy.html>.

For more information about the Cisco Product Warranties, go to: <https://www.cisco.com/c/en/us/products/warranty-listing.html>.

To subscribe to receive end-of-life/end-of-sale information, go to: <https://cway.cisco.com/mynotifications>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)