



PRODUCT BULLETIN, NO. 2552

NEW CISCO IOS SOFTWARE RELEASE 12.2(20)SE1 FOR CISCO CATALYST 3750, 3560, AND 2970 SERIES SWITCHES

OVERVIEW

Cisco Systems® announces Cisco IOS® Software updates for the Cisco® Catalyst® 3750, 3560, and 2970 series Intelligent Ethernet switches. This new release furthers Cisco leadership in providing secure, reliable, and easily managed LAN switching solutions.

This product bulletin describes the content and delivery information concerning Cisco IOS Software Release 12.2(20)SE1. For more information about the Cisco IOS Software release process, see Product Bulletin 537.

The **Speed Autonegotiate** enhancement allows users to enter specific values associated with the ability to autonegotiate speed and duplex settings of switch ports. For example, a network manager can limit 10/100/1000-Mbps capable ports to 10/100-Mbps speeds. This capability can be used when the network core has not yet been scaled to support users at 1000 Mbps. Table 1 shows the speed and duplex settings that the Speed Autonegotiate feature supports.

Table 1

Speed, Duplex, and Autonegotiation Settings Supported in Release 12.2(20)SE1

10/100 Ethernet Ports	10/100/100 Ethernet Ports	Fiber SFP, GBIC, and XENPAK Uplink Interfaces	Duplex Settings
speed <10 100 auto [10 100]> Users can configure the following combinations: speed 10 speed 100 speed auto speed auto 10 speed auto 100 speed auto 10 100	speed <10 100 1000 auto [10 100 1000]> Users can configure the following combinations: speed 10 speed 100 speed 1000 speed auto speed auto 10 speed auto 100 speed auto 1000 speed auto 10 100 speed auto 10 1000 speed auto 100 1000 speed auto 10 100 1000	Only one speed is supported on most types of interfaces; refer to the Release Notes for more information.	The duplex command will not change. (Note—half-duplex is not supported on 1000-Mbps or 10000-Mbps interfaces.)

The configured status for these speed and duplex commands is displayed through a new command: `show interface transceiver properties`.

NEW FEATURES IN CISCO IOS SOFTWARE RELEASE 12.2(20)SE1

The features shown in Table 2 will be delivered in Cisco IOS Software Release 12.2(20)SE1.

Table 2

Cisco IOS Software Release 12.2(20)SE1 New Features

Feature	Cisco Catalyst 3750-EMI	Cisco Catalyst 3750-SMI	Cisco Catalyst 3560 EMI	Cisco Catalyst 3560 SMI	Cisco Catalyst 2970
Speed Autonegotiate Enhancement	X	X	X	X	X
Show Interface Transceiver Properties	X	X	X	X	X

SMI—Standard Multilayer Image EMI—Enhanced Multilayer Image

Table 3 lists the fixed configuration Catalyst switches supported with this software release.

Table 3

Catalyst Switches Supported with Release 12.2(20)SE1

Cisco Catalyst 3750 Series Enhanced Multilayer Software Image Models	Cisco Catalyst 3750 Series Standard Multilayer Software Image Models	Cisco Catalyst 3560 Series Enhanced Multilayer Software Image Models	Cisco Catalyst 3560 Series Standard Multilayer Software Image Models	Cisco Catalyst 2970 Series Software Models
3750-48TS-E	3750-48TS-S	3560-48PS	3560-48PS	2970G-24T-E
3750-24TS-E	3750-24TS-S	3560-24PS	3560-24PS	2970G-24TS-E
3750G-24T-E	3750G-24T-S			
3750G-24TS-E	3750G-24TS-S			
3750G-12S-E	3750G-12S-S			
3750G-16TD	3750G-16TD			
3750-48PS	3750-48PS			
3750-24PS	3750-24PS			

ADDITIONAL RESOURCES

Software Download—Software available now.

Cisco Catalyst 3750 Series software download—<http://www.cisco.com/cgi-bin/tablebuild.pl/cat3750>

Cisco Catalyst 3560 Series software download—<http://www.cisco.com/cgi-bin/tablebuild.pl/cat3560>

Cisco Catalyst 2970 Series software download—<http://www.cisco.com/cgi-bin/tablebuild.pl/cat2970>

Due to export restrictions on strong cryptography software, a separate image is required for the cryptographic features (Secure Shell Protocol, Simple Network Management Protocol Version 3, and Kerberos Protocol). These software images can be downloaded from the corresponding 3DES area of the links provided above.

Additional product information is available at the following Websites:

Catalyst 3750 Series product information:

<http://www.cisco.com/go/catalyst3750>

Catalyst 3560 Series product information:

<http://www.cisco.com/go/catalyst3560>

Catalyst 2970 Series product information:

<http://www.cisco.com/go/catalyst2970>

Catalyst 3750, 3560, and 2970 release notes:

http://www.cisco.com/en/US/products/hw/switches/ps5023/prod_release_notes_list.html

http://www.cisco.com/en/US/products/hw/switches/ps5528/prod_release_notes_list.html

http://www.cisco.com/en/US/products/hw/switches/ps5206/prod_release_notes_list.html

Support

Cisco IOS Software Release 12.2(20)SE1 follows the standard Cisco support policy as indicated at


http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

Software Image Migration Guide

Table 4 displays Cisco IOS Software Release 12.2(20)SE1 functions relative to the 12.2S and 12.2SE releases. This diagram identifies the recommended migration path. For more information about the Cisco IOS Software release process, please see Product Bulletin 537.

Table 4

Cisco IOS Software Release 12.2 Release Train



**Corporate Headquarters**

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International
BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on **the Cisco Web site at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2004 Cisco Systems, Inc. All rights reserved. Cisco, Cisco Systems, the Cisco Systems logo, Catalyst, and Cisco IOS are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0402R) 204064_ETMG_CC_07.04

Printed in the USA