

End-of-Sale and End-of-Life Announcement for the Cisco IOS Software Release 15.3(3)S for Cisco ME 3800X Series Carrier Ethernet Switch Routers

EOL10307

Cisco announces the end-of-sale and end-of-life dates for the Cisco IOS Software Release 15.3(3)S for Cisco ME 3800X Series Carrier Ethernet Switch Routers. The last day to order the affected product(s) is September 21, 2015. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s).

Table 1. End-of-Life Milestones and Dates for the Cisco IOS Software Release 15.3(3)S for Cisco ME 3800X Series Carrier Ethernet Switch Routers

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	March 23, 2015
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	September 21, 2015
Last Ship Date: OS SW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	September 21, 2015
End of SW Maintenance Releases Date: OS SW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes for IOS 15.3(3)S. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software. The only exception is Vulnerability/Security issues that will be addressed as shown in the End of Vulnerability/Security Support milestone below.	September 20, 2016
End of Vulnerability/Security Support: OS SW	The last date that Cisco Engineering may release bug fixes for Vulnerability or Security issues for IOS 15.3(3)S. After this date, bug fixes for Vulnerability or Security issues identified in IOS 15.3(3)S may be provided through later supported software releases. Note that there will be no rebuild releases of IOS 15.3(3)S provided after this End of Vulnerability/Security Support milestone date.	September 20, 2017
Last Date of Support: OS SW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	September 30, 2020

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Product Migration Options

Customers are encouraged to migrate to the Cisco IOS Software Release 15.5(3)S. Information about this product can be found at: <http://www.cisco.com/en/US/products/ps10965/index.html>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For More Information Cisco IOS Software Release 15.5(3)S, visit <http://www.cisco.com/en/US/products/ps10965/index.html>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cisco/support/notifications.html>.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.




Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

 Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)