



## END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR THE CISCO MEDIA CONVERGENCE SERVER 7865I-1500

Cisco Systems® announces the end-of-sale and end-of-life dates for the Cisco® Media Convergence Server 7865I-1500. The last day to order this product is February 16, 2005. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until February 16, 2010. Table 1 describes the end-of-life milestones, definitions, and dates for the product. Table 2 lists the product part numbers affected by this announcement.

**Table 1.** End-of-Life Milestones and Dates for Cisco MCS 7865I-1500

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	November 16, 2004
<b>End-of-Sale Date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	February 16, 2005
<b>Last Shipment Date</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	May 16, 2005
<b>End of Software Maintenance Releases Date</b>	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	February 16, 2006
<b>End of Routine Failure Analysis Date</b>	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	February 16, 2006
<b>End of New Service Attachment Date</b>	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	February 16, 2006
<b>End of Service Contract Renewal Date</b>	The last date to extend or renew a service contract for the product. The extension or renewal period cannot extend beyond the last date of support.	November 16, 2009
<b>Last Date of Support</b>	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	February 16, 2010

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
MCS-7865I-1.5-ECS1	Cisco MCS 7865I-1500 With 4 Gallatin Xeon 1.5 GHz processors, 4 GB RAM, 4 x 36 GB hard drives, 4 x 72GB hard drives, and Windows 2000 Advanced Server
MCS-7865I-1.5-ECS2	Cisco MCS 7865I-1500 with 4 Gallatin Xeon 1.5 GHz processors, 4 GB RAM, 4 x 36 GB hard drives, and Windows 2000 Advanced Server

### PRODUCT MIGRATION OPTIONS

The recommended replacement for the Cisco MCS 7865I-1500 is the Cisco MCS 7845-I1 or the Cisco MCS 7845-H1.

The new Cisco MCS 7845-I1 and Cisco MCS 7845-H1 media convergence servers have two Xeon 3.4 GHz processors with an 800 MHz front side bus and 4 GB RAM in a 2-rack unit (2RU) form factor. These servers offer a more space-efficient and cost-effective server while still supporting the same number of Cisco Unity™ ports and voice-mail boxes as the Cisco MCS 7865I-1500 servers they replace. (Refer to Table 3.)

**Table 3.** Replacement Product Part Numbers

Feature	Current MCS Product Part Number	Replacement MCS Product Part Number
<b>Cisco Unity Server Hardware</b>	Cisco MCS 7865I-1.5-ECS1	Cisco MCS 7845-I1-ECS1
		or Cisco MCS 7845-H1-ECS1
<b>Cisco Unity Server Hardware</b>	Cisco MCS 7865I-1.5-ECS2	Cisco MCS 7845-I1-ECS2
		or Cisco MCS 7845-H1-ECS2

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to:

<http://www.cisco.com/go/tradein/>

The Cisco TMP application requires all users to have a Cisco.com user ID.

### FOR MORE INFORMATION

For more information about the Cisco MCS 7865I-1500, contact your local Cisco account representative or visit:

<http://www.cisco.com/en/US/products/hw/voiceapp/ps378/index.html>

For more information about the Cisco End-of-Life Policy, go to:

[http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html)

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>



#### **Corporate Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

#### **European Headquarters**

Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www-europe.cisco.com  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

#### **Americas Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

#### **Asia Pacific Headquarters**

Cisco Systems, Inc.  
168 Robinson Road  
#28-01 Capital Tower  
Singapore 068912  
www.cisco.com  
Tel: +65 6317 7777  
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on **the Cisco Web site at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2004 Cisco Systems, Inc. All rights reserved. CCIP, CCSP, the Cisco *Powered* Network mark, Cisco Unity, Follow Me Browsing, FormShare, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, Fast Step, GigaStack, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MGX, MICA, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, ScriptShare, SlideCast, SMARTnet, StrataView Plus, Stratum, SwitchProbe, TeleRouter, The Fastest Way to Increase Your Internet Quotient, TransPath, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0402R) 204121.66\_ETMG\_SK\_11.04

