



END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR THE CISCO MEDIA CONVERGENCE SERVER 7825I-3000

Cisco Systems® announces the end-of-sale and end-of-life dates for the Cisco® Media Convergence Server (MCS) 7825I-3000. The last day to order the affected product is August 2, 2005. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until May 2, 2010. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product. Table 2 lists the product part numbers affected by this announcement, and Table 3 compares the features of the end-of-life product with its suggested replacement product.

Table 1. End-of-Life Milestones and Dates for Cisco MCS 7825I-3000.

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	May 2, 2005
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	August 2, 2005
Last Shipment Date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	September 2, 2005
End of Software Maintenance Releases Date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	May 2, 2006
End of Routine Failure Analysis Date	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	May 2, 2006
End of New Service Attachment Date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	May 2, 2006
End of Service-Contract Renewal Date	The last date to extend or renew a service contract for the product. The extension or renewal period cannot extend beyond the last date of support.	February 2, 2010
Last Date of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	May 2, 2010

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
MCS-7825I-3.0-CC1	Hardware-only Cisco MCS 7825I-3000 with Pentium 4 3060MHz processor, 1GB RAM, and 40GB hard drive
MCS-7825I-3.0-IPC1	Hardware-only Cisco MCS 7825I-3000 with Pentium 4 3060MHz processor, 1GB RAM, and 40GB hard drive
MCS-7825I-3.0-IPC2	Hardware-only Cisco MCS 7825I-3000 with Pentium 4 3060MHz processor, 1GB RAM, and 40GB hard drive

PRODUCT MIGRATION OPTIONS

The recommended replacement for the Cisco MCS 7825I-3000 is the Cisco MCS 7825-I1 or Cisco MCS 7825-H1.

The new Cisco MCS-7825-I1 provides a faster processor, doubled memory, and doubled hard-disk space compared to the Cisco MCS-7825I-3000 server. The new Cisco MCS 7825-I1 provides Redundant Array of Independent Disks (RAID) 1 capability to improve the survivability if a hard disk fails.

Table 3. Product Comparisons

Feature	Cisco MCS 7825I-3000	Cisco MCS 7825-I1
Cisco Call Center Server Hardware	MCS-7825I-3.0-CC1	MCS-7825-I1-CC1
Cisco CallManager Server Hardware	MCS-7825I-3.0-IPC1 MCS-7825I-3.0-IPC2	MCS-7825-I1-IPC1 MCS-7825-I1-IPC1

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires users to have a Cisco.com user ID.

FOR MORE INFORMATION

For more information about the Cisco MCS 7825-I1, visit <http://www.cisco.com/en/US/partner/products/hw/voiceapp/ps378/index.html> or contact your local Cisco account representative.

For more information about the Cisco End-of-Life Policy, go to http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive end-of-life/end-of-sale information, go to <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.

**Corporate Headquarters**

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on **the Cisco Website at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel
Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal
Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2005 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StrataView Plus, TeleRouter, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R) 205215.CM_ETMG_SK_5.05

