

End-of-Sale and End-of-Life Announcement for the Cisco D9887B HDTV Modular Receiver

EOL9999

Cisco announces the end-of-sale and end-of-life dates for the Cisco D9887B HDTV Modular Receiver. The last day to order the affected product(s) is May 1, 2015. Customers with active service contracts or active warranties will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active service contracts or active product warranties, support will be available for the shown dates as stated in the applicable service contracts or product warranty terms and conditions, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the Cisco D9887B HDTV Modular Receiver

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	October 31, 2014
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 1, 2015
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	July 30, 2015
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	April 30, 2016
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	April 30, 2016
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	July 27, 2017
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete **. Warranty duration is based on product ship dates; refer to warranty terms and conditions for details.	April 30, 2018

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
403355110660001	D9887B 4:2:0 MP2/4, HD/SD, DBE, 2IP, ASI, 8VSB	See Product Migration Options section for details.	DCM 9902 with 8VSB card	-
403355120010001	D9887B 4:2:0 MP2/4, HD/SD-SDI, DS2	See Product Migration Options section for details.	D9896	-
403355120060001	D9887B 4:2:0 MP2/4, HD/SD-SDI, ASI, 8VSB	See Product Migration Options section for details.	DCM 9902 with 8VSB card	-
403355120200001	D9887B 4:2:0 +h.264, HD/SD-SDI, DuIP	See Product Migration Options section for details.	D9896	-
403355120440001	D9887B 4:2:0 MP2/4, HD/SD-SDI, DB-E ASI	See Product Migration Options section for details.	D9896	-
403355120450001	D9887B 4:2:0 +h.264, HD/SD-SDI, DB-E ASI DVB-S2	See Product Migration Options section for details.	D9896	-
403355120460001	D9887B 4:2:0 MP2/4, HD/SD-SDI, DB-E ASI 8VSB	See Product Migration Options section for details.	DCM 9902 with 8VSB card	-
403355120600001	D9887B 4:2:0 +h.264, HD/SD-SDI, DB-E DuIP	See Product Migration Options section for details.	D9896	-
403355120640001	D9887B 4:2:0 +h.264, HD/SD-SDI, DB-E DuIP ASI	See Product Migration Options section for details.	D9896	-
403355120650001	D9887B 4:2:0 +h.264, HD/SD-SDI, DB-E DuIP ASI DVB-S2	See Product Migration Options section for details.	D9896	-
403355120680001	D9887B 4:2:0 MP2/4, HD/SD-SDI, DB-E DuIP DVB-T	There is currently no replacement product available for this product.	-	-
403355120810001	D9887B 4:2:0 MP2/4, HD/SD-SDI, BISS-1/E DVB-S2	See Product Migration Options section for details.	D9896	-
403355120840001	D9887B 4:2:0 MP2/4, HD/SD-SDI, BISS-1/E ASI	See Product Migration Options section for details.	D9896	-
403355120A00001	D9887B 4:2:0 MP2/4, HD/SD-SDI, BISS-1/E DuIP	See Product Migration Options section for details.	D9896	-
403355120E50001	D9887B 4:2:0 +h.264, HD/SD-SDI BIS-1E DB-E DuIP ASI DVB-S2	See Product Migration Options section for details.	D9896	-
403355120E80001	D9887B 4:2:0 MP2/4, HD/SD-S, BISS, DBE, 2IP, DT	There is currently no replacement product available for this product.	-	-
403355220080001	D9887B 4:2:0 Dual MP2/4, HD/SD-SDI, DVB-T	There is currently no replacement product available for this product.	-	-
403355220600401	D9887B 4:2:0 Dual+h.264, HD/SD-SDI, DB-E DuIP DB-E	See Product Migration Options section for details.	D9896	-
403355220E50401	D9887B 4:2:0 2xMP2/4, HD/SD-SDI, BISS-1/E, DB-E 2IP, DVB-S2, DB-E	See Product Migration Options section for details.	D9896	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
403355240460001	D9887B 4:2:0 2/MP2/4, 2/HD/SD-SDI, DBE, ASI, 8VSB	See Product Migration Options section for details.	DCM 9902 with 8VSB card	-
403355330420421	D9887B 4:2:0 Dual MP2/4, 2xHD/SD, DB-E 8VSB Spl, DB-E 8VSB	See Product Migration Options section for details.	D9896	-
403355340200201	D9887B 4:2:0 Dual MP2/4, 2xHD/SD-SDI, DuIP Spl, DuIP	See Product Migration Options section for details.	D9896	-
403355340460461	D9887B 4:2:0 2/MP2/4, 2/HD/SD-S, 2/DBE, 2/A, 2/8VSB	See Product Migration Options section for details.	DCM 9902 with 8VSB card	-
403355340620621	D9887B 4:2:0 2/MP2/4, 2/HD/SD-S, 2/DBE, 2/2IP, 2/8VSB	See Product Migration Options section for details.	DCM 9902 with 8VSB card	-
403355342A02201	D9887B 4:2:0 2xMP2/4, 2HD/SD-S, BISS, 2XDS2	There is currently no replacement product available for this product.	-	-
403355400200001	D9887B 4:2:2 MP2, HD/SD-SDI, DuIP	See Product Migration Options section for details.	D9896	-
403355400440401	D9887B 4:2:2 MP2, HD/SD-SDI, DB-E ASI DB-E	See Product Migration Options section for details.	D9896	-
403355400600401	D9887B 4:2:2 MP2, HD/SD-SDI, DB-E DuIP DB-E	See Product Migration Options section for details.	D9896	-
403355400640401	D9887B 4:2:2 MP2, HD/SD-SDI, DB-E DuIP ASI DB-E	See Product Migration Options section for details.	D9896	-
403355400C10401	D9887B 4:2:2 MP2, HD/SD-SDI, BISS-1/E DB-E DVB-S2 DB-E	See Product Migration Options section for details.	D9896	-
403355400E40401	D9887B 4:2:2 MP2, HD/SD-SDI, BISS-1/E DB-E DuIP ASI DB-E	See Product Migration Options section for details.	D9896	-
403355400E50401	D9887B 4:2:2 MP2, HD/SD-SDI, BISS-1/E, DB-E 2IP, ASI, DVB-S2, DB-E	See Product Migration Options section for details.	D9896	-
403443400A80001	D9887B NDEC, BISS, 2IP, DT	There is currently no replacement product available for this product.	-	-
403443401A00001	D9887B NDEC, T8PSK, BISS, 2IP	There is currently no replacement product available for this product.	-	-
403443500280281	D9887B NDEC, 22IP, 2DT, Split	There is currently no replacement product available for this product.	-	-
4037816	D9887B Dual IP Output Module	There is currently no replacement product available for this product.	-	-
403979720460001	D9887B 4:2:0 MP2/4+G, HD/SD-SDI, DB-E ASI 8VSB	See Product Migration Options section for details.	DCM 9902 with 8VSB card	-
403979720E50001	D9887B HDTV Modular Receiver w/Genlock, IP, ASI, DVB-S2 Inputs	See Product Migration Options section for details.	D9896	-

Product Migration Options

Customers are encouraged to migrate to the DCM 9902 Digital Content Manager (for 8VSB applications) or the D9896 (for advanced decode applications). Information about these products can be found at:

<http://www.cisco.com/c/en/us/products/video/multiplexers/index.html> and

http://www.cisco.com/c/en/us/products/collateral/video/digital-encoders/data_sheet_c78-727758.html.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase Cisco D9887B HDTV Modular Receiver through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <http://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

** For more information about the Cisco Product Warranties, go to:

http://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cisco/support/notifications.html>.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:

http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.




Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

 Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)