



End-of-Sale and End-of-Life Announcement for the 2:1 bdr Products (Node Non-Integrated and PII)

EOL8188

Cisco announces the end-of-sale and end-of-life dates for the 2:1 bdr Products (Node non-integrated and PII). The last day to order the affected product(s) is August 17, 2012. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the 2:1 bdr Products (Node Non-Integrated and PII)

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	February 17, 2012
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	August 17, 2012
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	November 15, 2012
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	August 17, 2013
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	August 17, 2013
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	November 12, 2016
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	August 31, 2017

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
4003219	Node 2:1 bdr, 5-42MHz HG Multiplexing UPG Kit, 0dBm,1310LM
4003219.01	Node 2:1 bdr, 5-42MHz HG Multiplexing UPG Kit, 0dBm,1550LM
4013561	GS7000, 2:1 bdr Dgtl Module, 5-40MHz UPG Kit
738967	(P2-BDR-RP-2D) 2:1 Receive Proc, Dual (Not for use w/ Int 2:1)
738969	(P2-BDR-TP-2D) 2:1 Transmit Proc, Dual

End-of-Sale Product Part Number	Product Description
741244	(P2-BDR-RSM-ER-SA) Rx Module, XR, SA (Not for use w/ Int 2:1)
741278	Node 2:1 bdr, 5-42MHz Multiplexing UPG Kit, 0dBm, 1310LM
741278.01	Node 2:1 bdr, 5-42MHz Multiplexing UPG Kit, 0dBm, 1550LM
741278.21	ASSY, BDR NODE 2:1E UPGRADE KIT ITU2
741278.23	Node 2:1 bdr, 5-42MHz Multiplexing U
741278.25	Node 2:1 bdr, 5-42MHz Multiplexing U
741278.27	Node 2:1 bdr, 5-42MHz Multiplexing U
741278.29	Node 2:1 bdr, 5-42MHz Multiplexing U
741278.31	Node 2:1 bdr, 5-42MHz Multiplexing U
741278.33	Node 2:1 bdr, 5-42MHz Multiplexing U
741278.35	Node 2:1 bdr, 5-42MHz Multiplexing U
741278.37	ASSY, BDR NODE 2:1E UPGRADE KIT ITU3
741278.39	ASSY, BDR NODE 2:1E UPGRADE KIT ITU3
741278.41	ASSY, BDR NODE 2:1E UPGRADE KIT ITU4
741278.43	ASSY, BDR NODE 2:1E UPGRADE KIT ITU4
741278.45	ASSY, BDR NODE 2:1E UPGRADE KIT ITU4
741278.59	ASSY, BDR NODE 2:1E UPGRADE KIT ITU5
741279.21	ASSY, BDR 6940 NODE 2:1E ITU21
741279.23	ASSY, BDR 6940 NODE 2:1E ITU23
741279.25	ASSY, BDR 6940 NODE 2:1E ITU25
741279.29	ASSY, BDR 6940 NODE 2:1E ITU29
741279.31	ASSY, BDR 6940 NODE 2:1E ITU31
741279.53	ASSY, BDR 6940 NODE 2:1E ITU53
741279.55	ASSY, BDR 6940 NODE 2:1E ITU55

Product Migration Options

There is no replacement available for the 2:1 bdr Products (Node non-integrated and PII) at this time.

There is no direct replacement for this older non-integrated bdr product family. However for our currently offered node products (GainMaker and GS7000) we do offer the Integrated bdr products. The data sheet site for these Integrated products is listed. Information about this potential replacement product can be found at:

(<http://www.cisco.com/en/US/products/ps8965/index.html>).

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the 2:1 bdr Products (Node non-integrated and PII) through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <http://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Integrated 2:1 bdr Products, visit <http://www.cisco.com/en/US/products/ps8965/index.html>, or contact your local account representative.

To request information about the Integrated 2:1 bdr Products, send an e-mail to melvink@cisco.com.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cisco/support/notifications.html>.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.




Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

 Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)