

End-of-Sale and End-of-Life Announcement for the Cisco Lumin Low-Power Transmitters (DLTx)

EOL7700

Cisco announces the end-of-sale and end-of-life dates for the Cisco Lumin Low-Power Transmitters (DLTx). The last day to order the affected product(s) is January 3, 2012. Customers with active service contracts or active warranties will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active service contracts or active product warranties, support will be available for the shown dates as stated in the applicable service contracts or product warranty terms and conditions, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the Cisco Lumin Low-Power Transmitters (DLTx)

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	July 5, 2011
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	January 3, 2012
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	April 2, 2012
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	January 2, 2013
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	January 2, 2013
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	March 30, 2016
Last Date of Support: HW	The last expected date to receive service and support for the product as entitled by applicable service contracts or warranty terms and conditions **. After this date, all support services for the product are unavailable, and the product becomes obsolete. Warranty duration is based on product ship dates; refer to warranty terms and conditions for details.	January 31, 2017

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
4026647	DLT-4,Lumin High Density 1310nm Fwd Tx,1GHz,4dBm Output,SA	See the Product Migration Options section below for detailed information on replacing this product.		
4026649	DLT-6,Lumin High Density 1310nm Fwd Tx,1GHz,6dBm Output,SA	See the Product Migration Options section below for detailed information on replacing this product.		

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
4026651	DLT-8,Lumin High Density 1310nm Fwd Tx,1GHz,8dBm Output,SA	See the Product Migration Options section below for detailed information on replacing this product.		
4026652	DLT-9,Lumin High Density 1310nm Fwd Tx,1GHz,9dBm Output,SA	See the Product Migration Options section below for detailed information on replacing this product.		
4026653	DLT-10,Lumin High Density 1310nm Fwd Tx,1GHz,10dBm Output,SA	See the Product Migration Options section below for detailed information on replacing this product.		
4030634	DLTX-11-PAL,Lumin High Density 1310nm Fwd Tx,11dBm Out,PAL	See the Product Migration Options section below for detailed information on replacing this product.		

Product Migration Options

Customers are encouraged to migrate to the following models of the Cisco Lumin Low-Power Transmitters (product identification numbers): 4038969 DLTX-4 (LUMIN DENSE 1310 TX,4DBM) 4038970 DLTX-6 (LUMIN DENSE 1310 TX,6DBM) 4038971 DLTX-8 (LUMIN DENSE 1310 TX,8DBM) 4038972 DLTX-9 (LUMIN DENSE 1310 TX,9DBM) 4038973 DLTX-10 (LUMIN DENSE 1310 TX,10DBM) Information about these products can be found at: <http://www.cisco.com/en/US/products/ps10139/index.html>.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco Lumin Low-Power Transmitters (DLTx) through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <http://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End-of-Sale date

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to: http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco Lumin Low-Power Transmitters (DLTx), visit http://www.cisco.com/en/US/products/ps10139/products_data_sheets_list.html, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

** For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cisco/support/notifications.html>.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:

http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco Logo are trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1005R)