



## End-of-Sale and End-of-Life Announcement for the Cisco Lumin Optical Transmission Platform

EOL9011

Cisco announces the end-of-sale and end-of-life dates for the Cisco Lumin Optical Transmission Platform. The last day to order the affected product(s) is March 22, 2013. Customers will continue to receive phone support from the Cisco Small Business Support Center (SBSC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active product warranties, support will be available as stated in the product warranty terms and conditions, even if this date exceeds the Last Date of Support shown in Table 1.

**Table 1.** End-of-Life Milestones and Dates for the Cisco Lumin Optical Transmission Platform

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	December 21, 2012
<b>End-of-Sale Date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	March 22, 2013
<b>End of Phone Support Date:</b> <b>HW</b>	The last date to receive phone support as part of the product warranty. After this date, all phone support services for the product are available with additional charges or support fees. In some cases, support may not be available.	March 22, 2014
<b>Last Ship Date:</b> <b>HW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	June 20, 2013
<b>Last Date of Support:</b> <b>HW</b>	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete. Warranty duration is based on product ship dates; refer to warranty terms and conditions for details.	March 31, 2018

HW = Hardware OS SW = Operating System Software App. SW = Application Software

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
1009376	AC Line Cord, Lumin	See the Product Migration Options section below for detailed information on replacing this product.	-	-
4023578	DLC-Blank, Blank Module (Reqd to Fill Chassis Slots)	See the Product Migration Options section below for detailed information on replacing this product.	-	-
4026654	DLTX-11-HP, Lumin High Density 1310nm Fwd Tx, 11dBm Output	See the Product Migration Options section below for detailed information on replacing this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
4026656	DDR, Lumin Dual Return Receiver	See the Product Migration Options section below for detailed information on replacing this product.	-	-
4026658	Lumin, 3RU Shelf, 2/-48VDC Pwr Supply Module	See the Product Migration Options section below for detailed information on replacing this product.	-	-
4027071	External 1RU AC Pwr Supply Subsystem Shelf	See the Product Migration Options section below for detailed information on replacing this product.	-	-
4027073	Lumin, -48VDC Pwr Supply Module	See the Product Migration Options section below for detailed information on replacing this product.	-	-
4027865	Cable, DC Power to Ring Term, 1ft Lumin	See the Product Migration Options section below for detailed information on replacing this product.	-	-
4027866	Cable, DC Power to Ring Term, 2ft Lumin	See the Product Migration Options section below for detailed information on replacing this product.	-	-
4027867	Cable, DC Power to Ring Term, 4ft Lumin	See the Product Migration Options section below for detailed information on replacing this product.	-	-
4030012	Lumin DLL Chassis, PS, w/o ENET Port	See the Product Migration Options section below for detailed information on replacing this product.	-	-
4030423	Blank Front and Rear Cover	See the Product Migration Options section below for detailed information on replacing this product.	-	-
4032832	Lumin DLL Chassis, 2/PS, ENET Port	See the Product Migration Options section below for detailed information on replacing this product.	-	-
4032833	Lumin DLL Chassis, 2/PS, w/o ENET Port	See the Product Migration Options section below for detailed information on replacing this product.	-	-
4033114	Lumin DLL Chassis, PS, ENET Port	See the Product Migration Options section below for detailed information on replacing this product.	-	-
4035287	DLTX-12-HP, Lumin High Density 1310nm Fwd Tx, 12dBm Output	See the Product Migration Options section below for detailed information on replacing this product.	-	-
4035288	DLTX-13-HP, Lumin High Density 1310nm Fwd Tx, 13dBm Output	See the Product Migration Options section below for detailed information on replacing this product.	-	-
4038969	DLTX-4, Lumin Dense 1310nm Tx, 4dBm	See the Product Migration Options section below for detailed information on replacing this product.	-	-
4038970	DLTX-6, Lumin Dense 1310nm Tx, 6dBm	See the Product Migration Options section below for detailed information on replacing this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
4038971	DLTX-8, Lumin Dense 1310nm Tx, 8dBm	See the Product Migration Options section below for detailed information on replacing this product.	-	-
4038972	DLTX-9, Lumin Dense 1310nm Tx, 9dBm	See the Product Migration Options section below for detailed information on replacing this product.	-	-
4038973	DLTX-10, Lumin Dense 1310nm Tx, 10dBm	See the Product Migration Options section below for detailed information on replacing this product.	-	-

## Product Migration Options

Customers are encouraged to migrate to the Cisco Prisma II or Prisma XD platform. Information about this product can be found at: <http://www.cisco.com/en/US/products/ps8863/index.html>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

[http://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html).

## For More Information

For more information about the Cisco Prisma II Products, visit <http://www.cisco.com/en/US/products/ps8863/index.html>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: [http://www.cisco.com/en/US/products/products\\_end-of-life\\_policy.html](http://www.cisco.com/en/US/products/products_end-of-life_policy.html).

\*\* For more information about the Cisco Product Warranties, go to: [http://www.cisco.com/en/US/products/prod\\_warranties\\_listing.html](http://www.cisco.com/en/US/products/prod_warranties_listing.html).

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cisco/support/notifications.html>.

## Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: [http://www.cisco.com/web/feeds/products/end\\_of\\_life\\_rss.xml](http://www.cisco.com/web/feeds/products/end_of_life_rss.xml).

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.




---

Americas Headquarters  
Cisco Systems, Inc.  
San Jose, CA

Asia Pacific Headquarters  
Cisco Systems (USA) Pte. Ltd.  
Singapore

Europe Headquarters  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

 Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)