

# Recommended Microsoft Hot Fixes for Cisco MXE 3500

**September 2010**

**Product Bulletin No. 677836**

## Introduction

This bulletin lists the Microsoft hot fixes that we recommend you install on the Cisco MXE 3500 Media Experience Engine.

## Required Hardware and Software Levels


This bulletin applies to Release 3.0.0 of the Cisco MXE 3500.

## Installation

For each hot fix, click the link to go directly to the Microsoft website and do the following:


1. Read the Microsoft Security Bulletin.
2. Download the hot fix by clicking the link on the Security Bulletin webpage for **Windows Server 2003 Service Pack 2**.
3. Right-click the hot fix.
4. Click **Properties**. The File Property dialog box displays, as shown in Figure 1.

**Figure 1.** File Property Dialog Box



5. Click the **Unblock** button. The Unblock button dims, as shown in Figure 2.  
Or:  
If the Unblock button is not present, click **Cancel**, and install the hot fix by following the installation procedure that Microsoft provides.
6. Click **OK**. The File Property dialog box closes.
7. Install the hot fix by following the installation procedure that Microsoft provides.

**Figure 2.** Hot-Fix Unblocked



## Newly Recommended Hot Fixes

We recommended that you apply the following newly available Microsoft hot fixes to the Cisco MXE 3500, running the applicable versions of software:

- **MS10-062** (Knowledge base Article KB975558)  
<http://www.microsoft.com/technet/security/bulletin/MS10-062.msp>
- **MS10-063** (Knowledge base Article KB2320113)  
<http://www.microsoft.com/technet/security/bulletin/MS10-063.msp>
- **MS10-046** (Knowledge base Article KB2286198)  
<http://www.microsoft.com/technet/security/bulletin/MS10-046.msp>
- **MS10-049** (Knowledge base Article KB980436)  
<http://www.microsoft.com/technet/security/bulletin/MS10-049.msp>
- **MS10-051** (Knowledge base Article KB2079403)  
<http://www.microsoft.com/technet/security/bulletin/MS10-051.msp>
- **MS10-052** (Knowledge base Article KB2115168)  
<http://www.microsoft.com/technet/security/bulletin/MS10-052.msp>

- 
- **MS10-053** (Knowledge base Article KB2183461)  
<http://www.microsoft.com/technet/security/bulletin/MS10-053.msp>
  - **MS10-054** (Knowledge base Article KB982214)  
<http://www.microsoft.com/technet/security/bulletin/MS10-054.msp>
  - **MS10-055** (Knowledge base Article KB982665)  
<http://www.microsoft.com/technet/security/bulletin/MS10-055.msp>
  - **MS10-060** (Knowledge base Article KB2265906)  
<http://www.microsoft.com/technet/security/bulletin/MS10-060.msp>

### Hot Fixes Recommended in Prior Bulletins

July-2010

- None

June-2010

- **MS10-033** (Knowledge base Article KB979902)  
<http://www.microsoft.com/technet/security/bulletin/MS10-033.msp>

May-2010

- None

April-2010

- **MS10-019** (Knowledge base Article KB981210)  
<http://www.microsoft.com/technet/security/Bulletin/MS10-019.msp>
- **MS10-020** (Knowledge base Article KB980232)  
<http://www.microsoft.com/technet/security/Bulletin/MS10-020.msp>
- **MS10-026** (Knowledge base Article KB977816)  
<http://www.microsoft.com/technet/security/Bulletin/MS10-026.msp>

March-2010

- **MS10-006** (Knowledge base Article KB978251)  
<http://www.microsoft.com/technet/security/Bulletin/MS10-006.msp>
- **MS10-007** (Knowledge base Article KB975713)  
<http://www.microsoft.com/technet/security/bulletin/MS10-007.msp>
- **MS10-013** (Knowledge base Article KB977935)  
<http://www.microsoft.com/technet/security/bulletin/MS10-013.msp>

### Hot Fixes Included in Prior Maintenance Releases

None



---

**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV Amsterdam,  
The Netherlands

---

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

---

Cisco and the Cisco Logo are trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1005R)

Printed in USA

C25-677836-00 06/11