

End-of-Sale and End-of-Life Announcement for the Multimedia Stretch Tap Directional Coupler/Equalizer

EOL8881

Cisco announces the end-of-sale and end-of-life dates for the Multimedia Stretch Tap Directional Coupler/Equalizer. The last day to order the affected product(s) is May 6, 2013. Customers with active service contracts or active warranties will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active service contracts or active product warranties, support will be available for the shown dates as stated in the applicable service contracts or product warranty terms and conditions, even if this date exceeds the Last Date of Support shown in Table 1.

Migration depends on the particulars of your network. Please review all information carefully.

Table 1. End-of-Life Milestones and Dates for the Multimedia Stretch Tap Directional Coupler/Equalizer

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	November 5, 2012
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 6, 2013
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	August 4, 2013
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	May 6, 2014
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	May 6, 2014
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	August 1, 2017
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete**. Warranty duration is based on product ship dates; refer to warranty terms and conditions for details.	May 31, 2018

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Please contact your Cisco Sales representative for further information about your migration options.

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
591220	DC/EQ, MM Stretch, 3dB Eq, 0dB DC (Mult=20)	4038221	DC/EQ, MM Stretch, 1GHz, 0dB DC, 3dB EQ (Mult=20)	-
591221	DC/EQ, MM Stretch, 3dB Eq, 4dB DC (Mult=20)	4038222	DC/EQ, MM Stretch, 1GHz, 4dB DC, 3dB EQ (Mult=20)	-
591222	DC/EQ, MM Stretch, 3dB Eq, 7dB DC (Mult=20)	4038223	DC/EQ, MM Stretch, 1GHz, 7dB DC, 3dB EQ (Mult=20)	-
591223	DC/EQ, MM Stretch, 3dB Eq, 10dB DC (Mult=20)	4038224	DC/EQ, MM Stretch, 1 GHz, 10 dB DC, 3 dB EQ (Mult=20)	-
591224	DC/EQ, MM Stretch, 3dB Eq, 13dB DC (Mult=20)	4038225	DC/EQ, MM Stretch, 1 GHz, 13 dB DC, 3 dB EQ (Mult=20)	-
591225	DC/EQ, MM Stretch, 3dB Eq, 16dB DC (Mult=20)	4038226	DC/EQ, MM Stretch, 1 GHz, 16 dB DC, 3 dB EQ (Mult=20)	-
591226	DC/EQ, MM Stretch, 3dB Eq, 19dB DC (Mult=20)	4038227	DC/EQ, MM Stretch, 1 GHz, 19 dB DC, 3 dB EQ (Mult=20)	-
591227	DC/EQ, MM Stretch, 3dB Eq, 22dB DC (Mult=20)	4038228	DC/EQ, MM Stretch, 1 GHz, 22 dB DC, 3 dB EQ (Mult=20)	-
591228	DC/EQ, MM Stretch, 6dB Eq, 0dB DC (Mult=20)	4038229	DC/EQ, MM Stretch, 1 GHz, 0 dB DC, 6 dB EQ (Mult=20)	-
591229	DC/EQ, MM Stretch, 6dB Eq, 4dB DC (Mult=20)	4038230	DC/EQ, MM Stretch, 1 GHz, 4 dB DC, 6 dB EQ (Mult=20)	-
591230	DC/EQ, MM Stretch, 6dB Eq, 7dB DC (Mult=20)	4038231	DC/EQ, MM Stretch, 1 GHz, 7 dB DC, 6 dB EQ (Mult=20)	-
591231	DC/EQ, MM Stretch, 6dB Eq, 10dB DC (Mult=20)	4038232	DC/EQ, MM Stretch, 1 GHz, 10 dB DC, 6 dB EQ (Mult=20)	-
591232	DC/EQ, MM Stretch, 6dB Eq, 13dB DC (Mult=20)	4038233	DC/EQ, MM Stretch, 1 GHz, 13 dB DC, 6 dB EQ (Mult=20)	-
591233	DC/EQ, MM Stretch, 6dB Eq, 16dB DC (Mult=20)	4038234	DC/EQ, MM Stretch, 1 GHz, 16 dB DC, 6 dB EQ (Mult=20)	-
591234	DC/EQ, MM Stretch, 6dB Eq, 19dB DC (Mult=20)	4038235	DC/EQ, MM Stretch, 1 GHz, 19 dB DC, 6 dB EQ (Mult=20)	-
591235	DC/EQ, MM Stretch, 9dB Eq, 0dB DC (Mult=20)	4038236	DC/EQ MM Stretch, 1 GHz, 0 dB DC, 9 dB EQ (Mult=20)	-
591236	DC/EQ, MM Stretch, 9dB Eq, 4dB DC (Mult=20)	4038237	DC/EQ, MM Stretch, 1 GHz, 4 dB DC, 9 dB EQ (Mult=20)	-
591237	DC/EQ, MM Stretch, 9dB Eq, 7dB DC (Mult=20)	4038238	DC/EQ, MM Stretch, 1 GHz, 7 dB DC 9 dB EQ (Mult=20)	-
591238	DC/EQ, MM Stretch, 9dB Eq, 10dB DC (Mult=20)	4038239	DC/EQ, MM Stretch, 1 GHz, 10 dB DC, 9 dB EQ (Mult=20)	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
591239	DC/EQ, MM Stretch, 9dB Eq, 13dB DC (Mult=20)	4038240	DC/EQ, MM Stretch, 1 GHz, 13 dB DC, 9 dB EQ (Mult=20)	-
591240	DC/EQ, MM Stretch, 9dB Eq, 16dB DC (Mult=20)	4038241	DC/EQ, MM Stretch, 1 GHz, 16 dB DC, 9 dB EQ (Mult=20)	-
591241	DC/EQ, MM Stretch, 12dB Eq, 0dB DC (Mult=20)	4038242	DC/EQ, MM Stretch, 1 GHz, 0 dB DC, 12 dB EQ (Mult=20)	-
591242	DC/EQ, MM Stretch, 12dB Eq, 4dB DC (Mult=20)	4038243	DC/EQ, MM Stretch, 1 GHz, 4 dB DC, 12 dB EQ (Mult=20)	-
591243	DC/EQ, MM Stretch, 12dB Eq, 7dB DC (Mult=20)	4038244	DC/EQ, MM Stretch, 1GHz, 7dB DC, 12dB EQ (Mult=20)	-
591244	DC/EQ, MM Stretch, 12dB Eq, 10dB DC (Mult=20)	4038245	DC/EQ, MM Stretch, 1GHz, 10dB DC, 12dB EQ (Mult=20)	-
591245	DC/EQ, MM Stretch, 12dB Eq, 13dB DC (Mult=20)	4038246	DC/EQ, MM Stretch, 1GHz, 13dB DC, 12dB EQ (Mult=20)	-
591246	DC/EQ, MM Stretch, 15dB Eq, 0dB DC (Mult=20)	4038247	DC/EQ, MM Stretch, 1GHz, 0dB DC, 15dB EQ (Mult=20)	-
591247	DC/EQ, MM Stretch, 15dB Eq, 4dB DC (Mult=20)	4038248	DC/EQ, MM Stretch, 1GHz, 4dB DC, 15dB EQ (Mult=20)	-
591248	DC/EQ, MM Stretch, 15dB Eq, 7dB DC (Mult=20)	4038249	DC/EQ, MM Stretch, 1GHz, 7dB DC, 15dB EQ (Mult=20)	-
591249	DC/EQ, MM Stretch, 15dB Eq, 10dB DC (Mult=20)	4038250	DC/EQ, MM Stretch, 1GHz, 10dB DC, 15dB EQ (Mult=20)	-
591250	DC/EQ, MM Stretch, 18dB Eq, 0dB DC (Mult=20)	4038251	DC/EQ, MM Stretch, 1GHz, 0dB DC, 18dB EQ (Mult=20)	-
591251	DC/EQ, MM Stretch, 18dB Eq, 4dB DC (Mult=20)	4038252	DC/EQ, MM Stretch, 1GHz, 4dB DC, 18dB EQ (Mult=20)	-
591252	DC/EQ, MM Stretch, 18dB Eq, 7dB DC (Mult=20)	4038253	DC/EQ, MM Stretch, 1GHz, 7dB DC, 18dB EQ (Mult=20)	-

Product Migration Options

Customers are encouraged to migrate to the Multimedia Stretch Tap Directional Coupler/Equalizer 1GHz.

Information about this product can be found at:

http://www.cisco.com/en/US/prod/collateral/video/ps8806/ps9075/ps9091/product_data_sheet0900aecd806c7a16.pdf.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Multimedia Stretch Tap Directional Coupler/Equalizer through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <http://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Multimedia Stretch Tap Directional Coupler/Equalizer 1GHz, visit

http://www.cisco.com/en/US/prod/collateral/video/ps8806/ps9075/ps9091/product_data_sheet0900aecd806c7a16.pdf, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

** For more information about the Cisco Product Warranties, go to:

http://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cisco/support/notifications.html>.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:

http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)