

End-of-Sale and End-of-Life Announcement for the Cisco Performance Routing Engine 2

EOL7632

Cisco announces the end-of-sale and end-of-life dates for the Cisco Performance Routing Engine 2. The last day to order the affected product(s) is November 11, 2011. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the Cisco Performance Routing Engine 2

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	May 13, 2011
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	November 11, 2011
Last Ship Date: OS SW, HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	February 9, 2012
End of SW Maintenance Releases Date: OS SW, HW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	November 10, 2012
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	November 10, 2012
End of New Service Attachment Date: OS SW, HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	November 10, 2012
End of Service Contract Renewal Date: OS SW, HW	The last date to extend or renew a service contract for the product.	February 6, 2016
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	November 30, 2016

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
ESR-PRE-MEM-FD128	C10000 PRE 128M Flash Disk (default on PRE2)	There is currently no replacement product available for this product.		
ESR-PRE-MEM-FD128=	C10000 PRE 128M FLASH DISK OPTION	There is currently no replacement product available for this product.		
ESR-PRE2	Performance Routing Engine	ESR-PRE4	Performance Routing Engine 4	-
ESR-PRE2/R	Performance Routing Engine, 1GB DRAM, 64MB Flash	ESR-PRE4	Performance Routing Engine 4	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
ESR-PRE2=	Performance Routing Engine	ESR-PRE4=	Performance Routing Engine 4	-
SU12MK9U-12233SCB	Cisco ubr10k-PRE2 Ser IOS DOCSIS 3DES LAWFUL INTERCEPT	SU14MK9U-12233SCB	Cisco ubr10k-PRE4 Ser IOS DOCSIS 3DES LAWFUL INTERCEPT	-
SU12MK9U-12233SCB=	Cisco ubr10k-PRE2 Ser IOS DOCSIS 3DES LAWFUL INTERCEPT	SU14MK9U-12233SCB=	Cisco ubr10k-PRE4 Ser IOS DOCSIS 3DES LAWFUL INTERCEPT	-
SU12MK9U-12233SCC	Cisco ubr10k-PRE2 Ser IOS DOCSIS 3DES LAWFUL INTERCEPT	SU14MK9U-12233SCC	Cisco ubr10k-PRE4 Ser IOS DOCSIS 3DES LAWFUL INTERCEPT	-
SU12MK9U-12233SCC=	Cisco ubr10k-PRE2 Ser IOS DOCSIS 3DES LAWFUL INTERCEPT	SU14MK9U-12233SCC=	Cisco ubr10k-PRE4 Ser IOS DOCSIS 3DES LAWFUL INTERCEPT	-
U10012-1D5X20H-C	UBR10012 with PRE-2, DTCC and 1 MC5X20H card	There is currently no replacement product available for this product.		
U10012-2D5X20H-HA	UBR10012 with 2 PRE-2, 2 DTCC and 2 MC5X20H cards	There is currently no replacement product available for this product.		
UBR10-P2DT5G-HA	Bundle incl. 2 PRE2, 2 DTCC, 2 4-SPA SIP, 2 5x1 GE WAN SPA	There is currently no replacement product available for this product.		
UBR10-P2DT5G-HA=	Bundle incl. 2 PRE2, 2 DTCC, 2 4-SPA SIP, 2 5x1 GE WAN SPA	There is currently no replacement product available for this product.		
UBR10-P2DTG	Bundle incl. 1 PRE2, 1 DTCC, 1 HH-1GE, 1 HH-CARRIER	UBR10-P4DT10G	Bundle incl. 1 PRE4, 1 DTCC, 1 4-SPA SIP, 1 1x10 GE WAN SPA	-
UBR10-P2DTG-HA	bundle incl. 2 PRE2, 2 DTCC, 2 HH-1GE, 1 HH-CARRIER	UBR10-P4DT5G	Bundle incl. 1 PRE4, 1 DTCC+, 1 4-SPA SIP, 1 5x1 GE WAN SPA	-

Product Migration Options

Customers are encouraged to migrate to the Cisco Performance Routing Engine 4. Information about this product can be found at: http://www.cisco.com/en/US/prod/collateral/routers/ps133/data_sheet_c78-460875.html.

Customers can use the Cisco Technology Migration Program (TMP) to trade-in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at <http://www.cisco.com/web/partners/pr11/incentive/tmp/index.html>

Customers may be able to continue to purchase the Cisco Performance Routing Engine 2 through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <http://www.cisco.com/go/eos>

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html

For More Information

For more information about the Cisco Performance Routing Engine 4, visit http://www.cisco.com/en/US/prod/collateral/routers/ps133/data_sheet_c78-460875.html, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:
http://www.cisco.com/en/US/products/products_end-of-life_policy.html

To subscribe to receive end-of-life/end-of-sale information, go to:
<http://www.cisco.com/cisco/support/notifications.html>

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:
http://www.cisco.com/web/feeds/products/end_of_life_rss.xml

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco Logo are trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1005R)