

End-of-Sale and End-of-Life Announcement for the Cisco D9435 ASI to IP Gateway

EOL7559

Cisco announces the end-of-sale and end-of-life dates for the Cisco® D9435 ASI to IP Gateway. The last day to order the affected product(s) is October 28, 2011. Customers with active service contracts or active warranties will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active service contracts or active product warranties, support will be available for the shown dates as stated in the applicable service contracts or product warranty terms and conditions, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the Cisco D9435 ASI to IP Gateway

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	April 29, 2011
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	October 28, 2011
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	January 26, 2012
End of SW Maintenance Releases Date: HW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	October 27, 2012
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	October 27, 2012
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	October 27, 2012
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	January 23, 2016
Last Date of Support: HW	The last expected date to receive service and support for the product as entitled by applicable service contracts or warranty terms and conditions **. After this date, all support services for the product are unavailable, and the product becomes obsolete. Warranty duration is based on product ship dates; refer to warranty terms and conditions for details.	October 31, 2016

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
4023460	D9435 License to Enable 1 ASI Pt (2,3 or 4),UPG Kit	See the Product Migration Options section below for detailed information on replacing this product.		
4023462	D9435 License Bi-dir Functionality (all enabled pts),UPG Kit	See the Product Migration Options section below for detailed information on replacing this product.		

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
4023463	D9435 License to Enable GbE IP,UPG Kit	See the Product Migration Options section below for detailed information on replacing this product.		
D9435.100000000000	D9435 ASI to IP Gateway,1/ASI Port	See the Product Migration Options section below for detailed information on replacing this product.		
D9435.100000100000	D9435 ASI to IP Gateway,1/ASI Port	See the Product Migration Options section below for detailed information on replacing this product.		
D9435.100100000000	D9435 ASI to IP Gateway,1/ASI Port	See the Product Migration Options section below for detailed information on replacing this product.		
D9435.101100000000	D9435,ASI to IP Gateway,1/ASI	See the Product Migration Options section below for detailed information on replacing this product.		
D9435.101100010000	D9435 ASI to IP Gateway,1/ASI Port	See the Product Migration Options section below for detailed information on replacing this product.		
D9435.200000000000	D9435 ASI to IP Gateway	See the Product Migration Options section below for detailed information on replacing this product.		
D9435.200000100000	D9435 ASI to IP Gateway,2/ASI Ports	See the Product Migration Options section below for detailed information on replacing this product.		
D9435.200100000000	D9435 Gateway 2/ASI	See the Product Migration Options section below for detailed information on replacing this product.		
D9435.201000010000	D9435 ASI to IP Gateway,2/ASI Ports	See the Product Migration Options section below for detailed information on replacing this product.		
D9435.201100010000	D9435 ASI to IP Gateway,2/ASI Ports	See the Product Migration Options section below for detailed information on replacing this product.		
D9435.300000000000	D9435 ASI to IP Gateway,3 ASI Pts (100bT,AC)	See the Product Migration Options section below for detailed information on replacing this product.		
D9435.300000100000	D9435 ASI TO IP GATEWAY	See the Product Migration Options section below for detailed information on replacing this product.		
D9435.400000100000	D9435 ASI to IP Gateway,4/ASI Ports	See the Product Migration Options section below for detailed information on replacing this product.		
D9435.401000000000	D9435 ASI to IP Gateway,4/ASI Ports	See the Product Migration Options section below for detailed information on replacing this product.		
D9435.411001010000	D9435 ASI to IP Gateway,4/ASI Ports	See the Product Migration Options section below for detailed information on replacing this product.		

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
D9435.B11011010000	D9435 ASI to IP Gateway	See the Product Migration Options section below for detailed information on replacing this product.		
D9435.B11111000000	D9435 ASI to IP Gateway,Bi-dir 2+2 ASI Ports	See the Product Migration Options section below for detailed information on replacing this product.		

Product Migration Options

Customers are encouraged to migrate to the Cisco D9402 IP to ASI Adapter and Cisco DCM Series D9900/D9901 Digital Content Manager. Information about these products can be found at:

<http://www.cisco.com/en/US/products/ps9828/index.html> and
<http://www.cisco.com/en/US/products/ps9230/index.html>.

Customers can use the Cisco Technology Migration Program (TMP) to trade-in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at <http://www.cisco.com/web/partners/pr11/incentive/tmp/index.html>.

Customers may be able to continue to purchase the Cisco D9435 ASI to IP Gateway through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <http://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End-of-Sale date

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco End-of-Life Policy, go to:
http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

** For more information about the Cisco Product Warranties, go to:
http://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to:
<http://www.cisco.com/cisco/support/notifications.html>.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:
http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco Logo are trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1005R)