

# SG350X, SG550XG: Stack Slave Stuck when Unit is Disconnected then Reconnected

## Date Identified

May 26, 2017

## Date Resolved

September 8, 2017

## Products Affected

Model	Firmware Version	Fixed In
SG350X	2.2.0.X	2.3.5.63
SG550XG	2.3.0.130	2.3.5.63

## Problem Description

In some cases, a unit may not rejoin a stack after a master switchover (from original master to backup) or when the unit is disconnected and then reconnected to stack.

## Resolution

This issue is fixed when you upgrade to the firmware version 2.3.5.63. To upgrade, click [here](#) for instructions.

© 2017 Cisco Systems, Inc. All rights reserved.