

Caveat List

This chapter describes open severity 1 and 2 caveats and select severity 3 caveats:

• The *Open Caveats* sections list open caveats that apply to the current release and may apply to previous releases. A caveat that is open for a prior release and is still unresolved applies to all future releases until it is resolved.

The bug IDs are sorted alphanumerically.



Note

The Caveats section includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a specific caveat you must use the Bug Search Tool.

- Cisco Bug Search, on page 1
- Open Caveats for Cisco 1x2 / Compact Shelf RPD Software 5.3, on page 1
- Resolved Caveats for Cisco 1x2 / Compact Shelf RPD Software 5.3, on page 2

Cisco Bug Search

Cisco Bug Search Tool (BST), the online successor to Bug Toolkit, is designed to improve effectiveness in network risk management and device troubleshooting. You can search for bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. For more details on the tool, see the help page located at http://www.cisco.com/web/applicat/cbsshelp/help.html.

Open Caveats for Cisco 1x2 / Compact Shelf RPD Software 5.3

Caveat ID Number	Description
CSCvk17454	RPHY: LLDP Capabilities flapping between R and R,S
CSCvk58249	RPD exception and can't online when some fileds of PTP configuration are NULL
CSCvm52280	LLDP does not work for RPD daisy-chain or dual-link since LLDP packets are forwarded by RPD

Caveat ID Number	Description
CSCvm84334	RPD will wait for RA with prefix to decide it is a STATEFULL or a STATELESS configuration

Resolved Caveats for Cisco 1x2 / Compact Shelf RPD Software 5.3

Caveat ID Number	Description
CSCvm08583	RPHY: SSH exec-timeout value will lost when RPD reboot
CSCvm08705	Remove and re-add OFDM CH not take effect, have to reboot RPD to have it take effect
CSCvm10789	With RPD V5 Throttle, RF levels shift by 1.5-2.0 dB with removal/add of OFDM channel
CSCvm16313	rpd can't online after ssd upgrade when bootflash is full
CSCvm20444	RPD needs to support Curl requests from iNode to get RPD info and get/set Luoyang MAC Filters
CSCvm20451	DOCS-RPHY-PTP-MIB::docsRphyPtpRpdClockStatusClockState.'IoC.' get incorrect clock state
CSCvm32222	RPD cannot online: vbh0 status is unknown
CSCvm33475	RPHY: Support CW tone together with Docsis or Video in same quad.
CSCvm39154	Incorrect LED indication on the SW versions 5.1 and 5.2
CSCvm69337	RPD - Periodic PTP Sync failure causes late MAPs and Modems Offline