



New and Changed

This chapter contains the following section:

- [New and Changed Information, on page 1](#)

New and Changed Information

The following table provides an overview of the significant changes to this guide for this release. The table does not provide an exhaustive list of all changes made to the guide or of the new features up to this release.

Table 1: New Features and Changed Information for Cisco APIC 5.2(3)

Feature	Description	Where Documented
4x100G breakout support on N9K-C9332D-GX2B	4x100G breakout is now supported on the Cisco N9K-C9332D-GX2B switch's access ports.	Guidelines and Limitations for Dynamic Breakout Ports on Down Links
4x100G breakout support on N9K-C9332D-GX2B	4x100G breakout is now supported on the Cisco N9K-C9332D-GX2B switch's fabric ports.	Guidelines and Limitations for Auto Breakout Ports on Fabric Links
MACsec support on N9K-C9332D-GX2B	MACsec is now supported on the Cisco N9K-C9332D-GX2B switch.	Guidelines and Limitations for MACsec on switches

Table 2: New Features and Changed Information for Cisco APIC 5.2(1)

Feature	Description	Where Documented
4x100G breakout support on N9K-X9716D-GX	4x100G breakout is now supported on the Cisco N9K-X9716D-GX line card fabric ports.	Guidelines and Limitations for Auto Breakout Ports on Fabric Links
MACsec support on N9K-X9716D-GX	MACsec is now supported on the Cisco N9K-X9716D-GX line card.	Guidelines and Limitations for MACsec on switches

