



# New and Changed

This chapter contains the following section:

- [New and Changed Information, on page 1](#)

## New and Changed Information

The following tables provide an overview of the significant changes to the chapters in this guide up to the current release. The table does not provide an exhaustive list of all changes made to the topics or of the new features up to this release.

*Table 1: New Features and Changed Information for Cisco APIC 5.2(1)*

| Feature                                  | Description                                                                         | Where Documented                                                                   |
|------------------------------------------|-------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|
| 4x100G breakout support on N9K-X9716D-GX | 4x100G breakout is now supported on the Cisco N9K-X9716D-GX line card fabric ports. | <a href="#">Guidelines and Limitations for Auto Breakout Ports on Fabric Links</a> |
| MACsec support on N9K-X9716D-GX          | MACsec is now supported on the Cisco N9K-X9716D-GX line card.                       | <a href="#">Guidelines and Limitations for MACsec on switches</a>                  |

