



New and Changed Information

- [New and Changed Information, on page 1](#)

New and Changed Information

This table summarizes the new and changed features for the Cisco HyperFlex Troubleshooting Guide, Release 3.5(x) and tells you where they are documented.

Feature	Description	Date Added	Where Documented
New motherboard replacement information	Added motherboard replacement to list of TAC-assisted-only procedures.	Apr 25, 2019	Common TAC-Assisted Support Topics
New HX release 3.5 book	No new features, minor edits were made due to editing.	Oct 16, 2018	n/a

