



New and Changed Information

- [New and Changed Information, on page 1](#)

New and Changed Information

This table summarizes the new and changed features for the Cisco HyperFlex Troubleshooting Guide, Release 4.5(x) and tells you where they are documented.

Feature	Description	Date Added	Where Documented
Added SRM Recovery Fails with vSphere Cluster Service (vCLS)	Added new troubleshooting action.	April 20, 2021	SRM Recovery Fails with vSphere Cluster Service (vCLS)
Added Quiesce Based Snapshots Fail without an Error Message	Added new troubleshooting action.	February 19, 2021	Quiesce Based Snapshots Fail without an Error Message
Cisco HyperFlex Troubleshooting Reference Guide	First version for Cisco HyperFlex Release 4.5	January 6, 2021	N/A

