



Known Caveats

Table 1: Known Caveats in Smart Licensing (Release 16.11.1a)

Bug ID	Summary
CSCvo48002	Licenses in Eval Expired state coming up in Eval state after reload without doing a write mem.
CSCvo48377	16.11: HSEC license shown 'NOT IN USE' after upgrade from 16.9
CSCvo74870	Need to revert the soft enforcement for MACSEC licenses in SLR mode
CSCvm90638	SLR 1001-X licenses offered also provide 1002-X and non-supported throughput.
CSCvn87329	MACSEC License counts incorrect after SSO in SLR mode
CSCvo64618	Syslog appear when UUT is in registered in CSSM Portal

Table 2: Known Caveats in Smart Licensing (Release 16.10.1a)

Bug ID	Summary
CSCvn15214	Device registered to CSSM losing the registration on upgrade from 16.06.04 CCO SL-mode to 16.10.01a SL-only.
CSCvm63242	IOS_LICENSE_IMAGE_APPLICATION-3-FAILED: license request failed logs on upgrading to 16.10.1a image.
CSCvm81231	DLC status seen as Complete in show plat sw lic dlc inspite of DLC conversion failure on the device.
CSCvn22505	Device registration to Satellite 5.0.1 failing with reason “failure to send HTTP msgs”.

Bug ID	Summary
CSCvn17114	ASR1K: Unable to retrieve the information error on standby RP with ISSU downgrade.
CSCvm77949	Port Licenses are always shown as EVAL RTU though installed from PAK on ASR1001-HX
CSCvm88430	HSEck9 license which was in Authstate is available to use even after the device is deregistered
CSCvn21716	ASR : SW Redundancy and Firewall coming in DLC Path in SL Only mode
CSCvm65937	Licenses go to OOC and then later gets authorized even when tags are available in VA
CSCvn33180	Port Licenses are shown as PaperLicense undershow platform software license dlc output in 16.10.1a image
CSCvn01251	SL to SL-only path: Router hangs when downgrading from 16.10 to 16.6.4 CCO image