



## New and Changed Interface and Hardware Component Features

---

This chapter lists all the features that have been added or modified in this guide. The table also contains references to these feature documentation sections.

- [Interface and Hardware Component Features Added or Modified in IOS XR Release 6.4.x, on page 1](#)

### Interface and Hardware Component Features Added or Modified in IOS XR Release 6.4.x

Feature	Description	Introduced/Changed in Release	Where Documented
ICCP-SM Redundancy Group	Starting from Release 6.4.1, when there is a mismatch in VLAN configuration on PoAs, instead of blocking all primary and secondary VLANs, only unmatched VLANs are blocked.	Release 6.4.1	<a href="#">ICCP-SM Redundancy Group</a>

