



Caveats in Cisco IOS XE Release 3.18.8aSP

This chapter describes open and resolved severity 1 and 2 caveats and select severity 3 caveats:

- The "Open Caveats" sections list open caveats that apply to the current release and may apply to previous releases. A caveat that is open for a prior release and is still unresolved applies to all future releases until it is resolved.
- The "Resolved Caveats" sections list caveats resolved in a specific release, but open in previous releases.

The bug IDs are sorted alphanumerically.



Note The Caveats section includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a specific caveat you must use the Bug Search Tool.

- [Cisco Bug Search Tool, on page 1](#)
- [Open Caveats – Cisco IOS XE Release 3.18.8aSP, on page 1](#)
- [Resolved Caveats – Cisco IOS XE Release 3.18.8aSP, on page 2](#)
- [Resolved Caveats – Cisco IOS XE Release 3.18.8aSP Platform Independent, on page 2](#)

Cisco Bug Search Tool

[Cisco Bug Search Tool](#) (BST), the online successor to Bug Toolkit, is designed to improve effectiveness in network risk management and device troubleshooting. You can search for bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. For more details on the tool, see the help page located at <http://www.cisco.com/web/applicat/cbsshhelp/help.html>

Open Caveats – Cisco IOS XE Release 3.18.8aSP

| Caveat ID Number | Description |
|----------------------------|--|
| CSCva43417 | E1 Interfaces go DOWN on remote alarm (RDI) |
| CSCvm76770 | Unpredictable asymmetry on T1 or E1 interface module |

Resolved Caveats – Cisco IOS XE Release 3.18.8aSP

| Caveat ID Number | Description |
|----------------------------|---|
| CSCvi02398 | SNMP MIB and device configurations do not match |

Resolved Caveats – Cisco IOS XE Release 3.18.8aSP Platform Independent

| Caveat ID Number | Description |
|----------------------------|---|
| CSCvm79556 | RSP3: MSPW VC down after Switchover (Error Local access circuit is not ready for label advertise) |
| CSCvj15469 | Remove crypto group access check |