



New and Changed Information

About this Guide

The information in the new *Cisco MDS 9000 NX-OS IP Services Configuration Guide* previously existed in Part 6: IP Services of the *Cisco MDS 9000 Family CLI Configuration Guide*.

[Table 1](#) includes a brief description of each new feature and the release in which the change occurred, starting from Cisco MDS NX-OS Release 6.2(13).

Table 1 **New and Changed Features**

Feature	Changed in Release
Configuring FCIP Tunnels for Maximum Performance on a Cisco MDS 9250i Switch, page 58	6.2(13)
Changing Link Speed on 10 Gbps IP Storage Interfaces, page 211	6.2(13)

