

Software Advisory Notice

Dear Cisco Customer,

Cisco engineering has identified a software issue with the release that you have selected that may affect your use of this software. Please review the advisory notice here to determine if the issue applies to your environment. Customers are urged to upgrade to the recommended solution image or most current software version.

If you are currently running a release older than Cisco NX-OS Release 6.0(2)A8(3), you must perform an intermediate upgrade to Cisco NX-OS Release 6.0(2)A8(3) image before upgrading to Cisco NX-OS Release 6.0(2)A8(7a). If you do not follow this instruction, the device may not boot or become unusable. See the Software Affected/Solution table that follows for the list of affected images and solution images.

For additional information about what is included in this software, please refer to the Cisco Nexus 3548 Series Release Notes, available at [Cisco Nexus 3000 Series Switches Release Notes](#) page. Release notes are in the Release and General Information section on the product page.

Table of Affected Software and Solution

Software Type	Software Affected Version(s)	Software Solution Version(s)	Availability (mm/dd/yyyy)
Cisco NX-OS Software	Releases older than Cisco NX-OS Release 6.0(2)A8(3)	Cisco NX-OS Release 6.0(2)A8(3)	10/31/2016

Affected Platforms:

Cisco Nexus 3548 Switches

Workaround:

Download and install Cisco NX-OS Release 6.0(2)A8(3).

Disclaimer:

In order to increase network availability, Cisco recommends that you upgrade affected images with the suggested replacement software images. Cisco will discontinue manufacturing shipment

of affected images. Any pending order will be substituted by the replacement software images. PLEASE BE AWARE THAT FAILURE TO UPGRADE THE AFFECTED SOFTWARE MAY RESULT IN NETWORK DOWNTIME. The terms and conditions that governed your rights and obligations and those of Cisco, with respect to the deferred software will apply to the replacement software.

The terms and conditions that governed your rights and obligations and those of Cisco, with respect to the deferred software will apply to the replacement software.

Cisco and the Cisco Logo are trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1005R)