



Service Access Cover Installation Note

WS-X4500-PS01—Service Access Cover

Installing the Replacement Cover

Replace the service access cover (WS-X4500-PS01) over the DC terminals on the power shelf as described in the following steps:



Caution

Turn off the Catalyst 4500 series switch and unplug the power cord or cords providing AC input power before removing or replacing the service access cover.


Step 1

Insert the tabs on the service access cover into the slots to the left of the terminals.

Step 2

Bend the service access cover around the terminal block, allowing the corners to poke through the slots on the cover.

Figure 1 *Installing the Service Access Cover*



137630

Step 3 Insert the tabs on the front of the service access cover into the slots to the right of the terminals.

Related Documentation

This note discusses only the installation of the service access cover. Related information is in the *Installation and Configuration Note for the Catalyst 4500 Series AC Power Shelf* at:

http://www.cisco.com/univercd/cc/td/doc/product/lan/cat4000/hw_doc/78_15068.htm

CCVP, the Cisco logo, and Welcome to the Human Network are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Aironet, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, LightStream, Linksys, MeetingPlace, MGX, Networkers, Networking Academy, Network Registrar, PIX, ProConnect, ScriptShare, SMARTnet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0711R)

Service Access Cover Installation Note
Copyright © 2005 Cisco Systems, Inc. All rights reserved.