



Caveats

- [Cisco Bug Search Tool](#), on page 1
- [Open Caveats in Cisco IOS XE Dublin 17.12.x](#), on page 1
- [Resolved Caveats in Cisco IOS XE Dublin 17.12.3](#), on page 1
- [Resolved Caveats in Cisco IOS XE Dublin 17.12.2](#), on page 2
- [Resolved Caveats in Cisco IOS XE Dublin 17.12.1](#), on page 2

Cisco Bug Search Tool

The Cisco [Bug Search Tool](#) (BST) allows partners and customers to search for software bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. The BST is designed to improve the effectiveness in network risk management and device troubleshooting. The tool has a provision to filter bugs based on credentials to provide external and internal bug views for the search input.

To view the details of a caveat, click on the identifier.

Open Caveats in Cisco IOS XE Dublin 17.12.x

Identifier	Headline
CSCwh35728	Need switch to host macsec support in Sda overlay network
CSCwi69005	C9300 switch unexpectedly reloads due to FNF/SWC causing FED to crash

Resolved Caveats in Cisco IOS XE Dublin 17.12.3

Identifier	Applicable Models	Headline
CSCwi30269	C9200	Port 2228 isn't closed after reload when I2-traceroute is disabled, Security threat
CSCwi62480	C9200	show inventory shows "Unknown uplink module" for FRU uplink module when reload Cat9200

Identifier	Applicable Models	Headline
CSCwi72959	C9200	When removed one FAN other FAN LED goes amber
CSCwh38627	C9200L	C9200L: Stack switch mgmt port reply unknow mac address
CSCwi60084	C9200L	Cat9200L may experience an Unexpected Reload
CSCwi06404	C9200	PKI crash after failing a CRL Fetch

Resolved Caveats in Cisco IOS XE Dublin 17.12.2

Identifier	Applicable Models	Headline
CSCwf99608	C9200CX	Change AUX power value displayed in show env power for Changeup
CSCwf73002	C9200	Unable to remove port security configs under interface via netconf
CSCwf68913	C9200	C9000: Interface link flapping(down/up) occurs at Active Switch after switchover
CSCwh29961	C9200	show stacks: Information of Last System Crash:%Error opening crashinfo:crashinfo_RP_00_00
CSCwf78065	C9200	cat9200: CTS PAC download must fail when FIPS is enabled
CSCwh87343	All models	Cisco IOS XE Software Web UI Privilege Escalation Vulnerability For more information, see Security Advisory: cisco-sa-iosxe-webui-privesc-j22SaA4z .
CSCwh20734	C9200	Crypto PKI-CRL-IO_0 process crash when PKI trustpoint is requested&deleted
CSCwf18420	C9200	LLDP does not announce dynamically assigned VLAN

Resolved Caveats in Cisco IOS XE Dublin 17.12.1

Identifier	Headline
CSCwc41288	C9200L - Input Errors on Uplinks using 1G SFP
CSCwe47724	gbic-invalid error seen when connected CWDM-SFP-1610 and CWDM-SFP-1590 SFPs

Identifier	Headline
CSCwe79864	9200: Incorrect Iout, pout and PS fan rpm speeds in "show env all" CLI

