



Caveats

- [Cisco Bug Search Tool](#), on page 1
- [Open Caveats in Cisco IOS XE Cupertino 17.9.x](#), on page 1
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.5](#), on page 1
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.4a](#), on page 2
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.4](#), on page 2
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.3](#), on page 3
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.2](#), on page 3
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.1](#), on page 3

Cisco Bug Search Tool

The Cisco [Bug Search Tool](#) (BST) allows partners and customers to search for software bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. The BST is designed to improve the effectiveness in network risk management and device troubleshooting. The tool has a provision to filter bugs based on credentials to provide external and internal bug views for the search input.

To view the details of a caveat, click on the identifier.

Open Caveats in Cisco IOS XE Cupertino 17.9.x

Identifier	Headline
CSCwc15574	Mgig Cat9200 incrementing FCS-Err/Rcv-Err from 1Gig connection
CSCwc21676	UTF file filling with constant repm-ipc connect/disconnect msgs

Resolved Caveats in Cisco IOS XE Cupertino 17.9.5

Identifier	Headline
CSCwi30269	Port 2228 isn't closed after reload when l2-traceroute is disabled, Security threat
CSCwf68913	C9000: Interface link flapping(down/up) occurs at active switch after switchover

Identifier	Headline
CSCwh29961	Show stacks: Information of Last System Crash:%Error opening crashinfo:crashinfo_RP_00_00
CSCwe65441	Non-PoE 9200/9200L devices with ARTXXX power supply present in Slot A do not boot after switch power cycle
CSCwf18420	LLDP does not announce dynamically assigned VLAN
CSCwf23122	Catalyst 9200 might reload due to REPM process crash
CSCwe95691	PnP Cat9k sends DHCP Discover with IP Source address 192.168.1.1 instead of 0.0.0.0
CSCwi10405	[NEAT] CISP installs a static MAC address entry pointing to a wrong interface

Resolved Caveats in Cisco IOS XE Cupertino 17.9.4a

Identifier	Headline
CSCwh87343	Cisco IOS XE Software Web UI Privilege Escalation Vulnerability For more information, see Security Advisory: cisco-sa-iosxe-webui-privesc-j22SaA4z .

Resolved Caveats in Cisco IOS XE Cupertino 17.9.4

Identifier	Headline
CSCwe33886	17.9 install oper DB queries returning errors on DB queries to xpath install-oper-hist
CSCwe36743	Segmentation Fault - Crash - SSH - When Changing AAA Group Configs
CSCwe73012	9130/9166 APs are not powering up when connected to Gig port of C9200-CX switch
CSCwe79786	C9200CX: entSensorThresholdValue shows wrong yellow threshold
CSCwe91069	C9200 Unexpected reload upon removing netflow commands
CSCwe89814	Unexpected reboot due to FED process heldown with Netflow
CSCwc41288	C9200L - Input Errors on Uplinks using 1G SFP
CSCwe79864	C9200: Incorrect Iout, pout and PS fan rpm speeds in "show env all" CLI

Resolved Caveats in Cisco IOS XE Cupertino 17.9.3

Identifier	Headline
CSCwd56540	Ignore higher fan speed deviations on 9200

Resolved Caveats in Cisco IOS XE Cupertino 17.9.2

Identifier	Headline
CSCwc84941	Due to signal suppression enabled the map-requests are not sent when below map-cache limit

Resolved Caveats in Cisco IOS XE Cupertino 17.9.1

Identifier	Headline
CSCvz77502	9200l 10G port led not blinking green under speed mode
CSCwa77415	Switch stack shows wrong neighbor info for stack-ports links
CSCwa23654	Memory leak in Inline Power IOSd process when PoE is used
CSCwb18702	CISCO-ENTITY-SENSOR-MIB is returning wrong threshold values for thermal sensors
CSCwa76242	Cat 9200L - 10G Link Flaps at intermittent times when peer is maintained as Nexus 9K
CSCwa41298	remote switch doesn't detect link down when one rx fiber cable is unplugged on 9200L
CSCwa52014	CISCO-ENHANCED-MEMPOOL-MIB not working on C9200 and C9300

