



Caveats

- [Cisco Bug Search Tool](#), on page 1
- [Open Caveats in Cisco IOS XE Cupertino 17.9.x](#), on page 1
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.5](#), on page 1
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.4a](#), on page 2
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.4](#), on page 2
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.3](#), on page 2
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.2](#), on page 3
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.1](#), on page 3

Cisco Bug Search Tool

The Cisco [Bug Search Tool](#) (BST) allows partners and customers to search for software bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. The BST is designed to improve the effectiveness in network risk management and device troubleshooting. The tool has a provision to filter bugs based on credentials to provide external and internal bug views for the search input.

To view the details of a caveat, click on the identifier.

Open Caveats in Cisco IOS XE Cupertino 17.9.x

There are no open caveats in this release.

Resolved Caveats in Cisco IOS XE Cupertino 17.9.5

Identifier	Applicable Models	Headline
CSCwh10596	C9300	High CPU observed in Fed main after switchover
CSCwe35651	C9300	False hotspot temperature alerts indicating RED threshold has been exceeded
CSCwh51416	C9300LM	C9300LM - GLC-TE is not working

Identifier	Applicable Models	Headline
CSCwe95691	C9300	PnP Cat9k sends DHCP Discover with IP Source address 192.168.1.1 instead of 0.0.0.0
CSCwi10405	C9300	[NEAT] CISP installs a static MAC address entry pointing to a wrong interface

Resolved Caveats in Cisco IOS XE Cupertino 17.9.4a

Identifier	Applicable Models	Headline
CSCwh87343	All Models	Cisco IOS XE Software Web UI Privilege Escalation Vulnerability For more information, see Security Advisory: cisco-sa-iosxe-webui-privesc-j22SaA4z .

Resolved Caveats in Cisco IOS XE Cupertino 17.9.4

Identifier	Applicable Models	Headline
CSCwe18993	C9300-24P C9300-48P	PoE devices connected to C9300-24P/48P series of switches losing power and staying in "down" state
CSCwe09745	C9300	Memory leak in Pubd when continuously trying to connect to remote peer
CSCwd56049	C9300	Few C9300-48UN do not link up with Statstrip Glucose Meter
CSCwe33886	C9300	17.9 install oper DB queries returning errors on DB queries to xpath install-oper-hist
CSCwe36743	C9300	Segmentation Fault - Crash - SSH - When Changing AAA Group Configs

Resolved Caveats in Cisco IOS XE Cupertino 17.9.3

Identifier	Applicable Models	Headline
CSCwc95388	9300L	9300L: 1G link is down when connected between 9300L uplink

Identifier	Applicable Models	Headline
CSCwd20481	9300	Command reload cancel fails when the system clock changes to a later time in between "reload in x"
CSCwd23435	9300X	C9300X use SFP-10G-T-X Copper transceiver has random packet loss with 1G speed after OIR
CSCwd28734	9300	Cat9k memory leak in pubd causes switch reload
CSCwd39377	9300	BGP timers not supported after upgrade
CSCwd39892	9300	no ip dhcp excluded-address doesn't work post 17.2.1
CSCwd78924	9300	Cat9300: PoE Imax error detected for PD requesting 30W since 17.3.5+
CSCwd99665	9300L	C9300L-48UXG-4X: TMPFS leak due to excessive logging to debug_logging_file

Resolved Caveats in Cisco IOS XE Cupertino 17.9.2

Identifier	Applicable Models	Headline
CSCwc85671	9300	license boot level command line duplicated if there is no DNA addon license
CSCwc88452	9300	hw-module breakout command not working on C9300-48UN IOS version 17.6.3
CSCwc29733	9300L	C9300L: uplink using GLC-SX-MMD not coming up
CSCwc87761	9300L	C9300L: PWR-C1-350WAC-P power supply may turn off requiring power cable OIR

Resolved Caveats in Cisco IOS XE Cupertino 17.9.1

Identifier	Applicable Models	Headline
CSCwa93776	C9300	Few ip phones connected to c9300-mGig switches unable to link up if "no mdix auto" is configured
CSCwb23060	C9300, C9300X	Interop between 9300x and 9300 not working for Copper 40G cables.
CSCwa06718	C9300L	Link between 9500x/9600X QSA/SFP+ to 9300L 10G doesn't come up after reload
CSCwb44422	C9300X	C9300X-24Y show license usage indicate inconsistency

Identifier	Applicable Models	Headline
CSCwa00143	C9300	C9300 Rcv-Err counter keeps increasing on unused ports