



Caveats

- [Cisco Bug Search Tool](#), on page 1
- [Open Caveats in Cisco IOS XE Cupertino 17.9.x](#), on page 1
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.5](#), on page 1
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.4a](#), on page 2
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.4](#), on page 2
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.3](#), on page 2
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.2](#), on page 2
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.1](#), on page 3

Cisco Bug Search Tool

The Cisco [Bug Search Tool](#) (BST) allows partners and customers to search for software bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. The BST is designed to improve the effectiveness in network risk management and device troubleshooting. The tool has a provision to filter bugs based on credentials to provide external and internal bug views for the search input.

To view the details of a caveat, click on the identifier.

Open Caveats in Cisco IOS XE Cupertino 17.9.x

Identifier	Headline
CSCwd59033	Output drops flapping between 0 and 27487XXXXXXXXX

Resolved Caveats in Cisco IOS XE Cupertino 17.9.5

Identifier	Headline
CSCwh39763	Stby-switch reset due to Notification timer Expired for RF Client: NGMOD HMS RF client(10101)

Identifier	Headline
CSCwe95691	PnP Cat9k sends DHCP Discover with IP Source address 192.168.1.1 instead of 0.0.0.0
CSCwi10405	[NEAT] CISP installs a static MAC address entry pointing to a wrong interface

Resolved Caveats in Cisco IOS XE Cupertino 17.9.4a

Identifier	Headline
CSCwh87343	Cisco IOS XE Software Web UI Privilege Escalation Vulnerability For more information, see Security Advisory: cisco-sa-iosxe-webui-privesc-j22SaA4z .

Resolved Caveats in Cisco IOS XE Cupertino 17.9.4

Identifier	Headline
CSCwe33886	17.9 install oper DB queries returning errors on DB queries to xpath install-oper-hist
CSCwe36743	Segmentation Fault - Crash - SSH - When Changing AAA Group Configs
CSCwe62246	9400-HA: Standby reboots due to crash in MKA process during ISSU

Resolved Caveats in Cisco IOS XE Cupertino 17.9.3

Identifier	Headline
CSCwd07000	C9410 has line cards in "other" status, standby will not fully boot after upgrade or power-cycle.
CSCwb53649	100G: Wrong output for DOM values through snmpwalk

Resolved Caveats in Cisco IOS XE Cupertino 17.9.2

Identifier	Headline
CSCwc35584	Multicast traffic may stop after ISSU or stby reload followed by switchover if stby AppGigE is enabled

Resolved Caveats in Cisco IOS XE Cupertino 17.9.1

There are no resolved caveats in this release.

