



Open issues

- [Open issues in Release 6.0\(1.250198\), on page 1](#)

Open issues in Release 6.0(1.250198)

This section provides a brief description of the open issues.



Note This software release may contain open bugs first identified in other releases. To see additional information, click the bug ID to access the [Cisco Bug Search Tool](#).

Defect ID	Description	Workaround	First Version Affected
CSCwo44245	On UCS FI 6664, Fibre Channel (FC) ports using 64G SFP modules may go into an error-disabled state due to high bit error rates when configured at 16G speed.	Use 16G or 32G SFP modules instead of 64G SFP when configuring the port at 16G speed.	6.0.1.250071

