



HDD Firmware for Release 3.1

This chapter includes the following section:

- [HDD Firmware, on page 1](#)

HDD Firmware

Following table lists the supported HDD models and the firmware versions that can be updated using Host Upgrade Utility (HUU).

Firmware for the following HDDs were updated in Release 3.1(3d):

- AL13SXB30EN—Firmware updated from version 5702 in Release 3.1(3c) to version 5703 in Release 3.1(3d)
- AL13SXB45EN—Firmware updated from version 5702 in Release 3.1(3c) to version CS04 in Release 3.1(3d)
- HUC101812CSS200—Firmware updated from version A703 in Release 3.1(3c) to version AD50 in Release 3.1(3d)
- HUC101812CSS205—Firmware added with version DA01 in Release 3.1(3d)
- HUC101818CS4200—Firmware added with version AD50 in Release 3.1(3d)
- HUC101830CSS205—Firmware added with version DA01 in Release 3.1(3d)
- HUC101860CS4200—Firmware updated from version A703 in Release 3.1(3c) to version AD50 in Release 3.1(3d)
- HUH721010AL4200 —Firmware updated from version A21D in Release 3.1(3c) to version A38K in Release 3.1(3d)
- HUH721010AL5200 —Firmware added with version A38K in Release 3.1(3d)
- HUS726060AL4215 —Firmware added with version D7J0 in Release 3.1(3d)
- MG04SCA20EN —Firmware added with version 5703 in Release 3.1(3d)
- MG04SCA40EN —Firmware added with version 5703 in Release 3.1(3d)
- MG04SCA60EA —Firmware added with version 5703 in Release 3.1(3d)
- MTFDDAK120TCC —Firmware added with version U037 in Release 3.1(3d)

- MTFDDAK1T6TCC —Firmware added with version U037 in Release 3.1(3d)
- MTFDDAK1T9TBY —Firmware added with version U037 in Release 3.1(3d)
- MTFDDAK240TCB —Firmware added with version U037 in Release 3.1(3d)
- MTFDDAK3T8TBY —Firmware added with version U410 in Release 3.1(3d)
- MTFDDAK480TCB —Firmware added with version U037 in Release 3.1(3d)
- MTFDDAK7T6TBY —Firmware added with version U810 in Release 3.1(3d)
- MTFDDAK960TCB —Firmware added with version U037 in Release 3.1(3d)
- MZ6ES400HMGR —Firmware added with version EM17 in Release 3.1(3d)
- MZ7LM1T9HMJP-00003 —Firmware added with version 1F3Q in Release 3.1(3d)
- MZ7LM240HCGR —Firmware updated from version 32F3Q in Release 3.1(3c) to version 3F3Q in Release 3.1(3d)
- MZ7LM240HCGR00003 —Firmware updated from version 32F3Q in Release 3.1(3c) to version 3F3Q in Release 3.1(3d)
- MZ7LM240HMHQ-00003 —Firmware added with version 1F3Q in Release 3.1(3d)
- MZ7LM3T8HCJM —Firmware updated from version 32F3Q in Release 3.1(3c) to version 3F3Q in Release 3.1(3d)
- MZ7LM3T8HCJM00003 —Firmware updated from version 32F3Q in Release 3.1(3c) to version 3F3Q in Release 3.1(3d)
- MZ7LM3T8HMLP-00003 —Firmware added with version 1F3Q in Release 3.1(3d)
- MZ7LM480HMHQ-00003 —Firmware added with version 1F3Q in Release 3.1(3d)
- MZ7LM960HCHP —Firmware updated from version 32F3Q in Release 3.1(3c) to version 3F3Q in Release 3.1(3d)
- MZ7LM960HCHP00003 —Firmware updated from version 32F3Q in Release 3.1(3c) to version 3F3Q in Release 3.1(3d)
- MZ7LM960HMJP-00003 —Firmware added with version 1F3Q in Release 3.1(3d)
- MZIES800HMHP — Firmware added with version EM14 in Release 3.1(3d)
- PX05SMB040 —Firmware added with version 0103 in Release 3.1(3d)
- PX05SMB080 —Firmware added with version 0103 in Release 3.1(3d)
- PX05SMB160 —Firmware added with version 0103 in Release 3.1(3d)
- PX05SRB048 —Firmware added with version 0103 in Release 3.1(3d)
- PX05SRB096 —Firmware added with version 0103 in Release 3.1(3d)
- PX05SRB192 —Firmware added with version 0103 in Release 3.1(3d)
- PX05SRB384 —Firmware added with version 0103 in Release 3.1(3d)
- PX05SVB040 —Firmware added with version 0103 in Release 3.1(3d)

- PX05SVB080 —Firmware added with version 0103 in Release 3.1(3d)
- PX05SVB160 —Firmware added with version 0103 in Release 3.1(3d)
- PX05SVB320 —Firmware added with version 0103 in Release 3.1(3d)
- SSDSC2BB016T6K —Firmware added with version CS01 in Release 3.1(3d)
- SSDSC2BB016T7K —Firmware added with version CS01 in Release 3.1(3d)
- SSDSC2BB120G7K —Firmware added with version CS01 in Release 3.1(3d)
- SSDSC2BB150G7K —Firmware added with version CS01 in Release 3.1(3d)
- SSDSC2BB480G7K —Firmware added with version CS01 in Release 3.1(3d)
- SSDSC2BB960G7K —Firmware added with version CS01 in Release 3.1(3d)
- SSDSC2BX200G4K —Firmware added with version CS01 in Release 3.1(3d)
- SSDSC2BX800G4K —Firmware added with version CS01 in Release 3.1(3d)
- SSDSC2KB038T7K —Firmware added with version CS04 in Release 3.1(3d)
- SSDSC2KB480G7K —Firmware added with version CS04 in Release 3.1(3d)
- SSDSC2KB960G7K —Firmware added with version CS04 in Release 3.1(3d)
- SSDSC2KG019T7K —Firmware added with version CS04 in Release 3.1(3d)
- SSDSC2KG480G7K —Firmware added with version CS04 in Release 3.1(3d)
- SSDSC2KG960G7K —Firmware added with version CS04 in Release 3.1(3d)
- ST1000NM0045 —Firmware added with version N0C2 in Release 3.1(3d)
- ST1800MM0048 —Firmware added with version KF04 in Release 3.1(3d)
- ST2000NM0045 —Firmware added with version N0C2 in Release 3.1(3d)
- ST2000NM0055 —Firmware added with version CS02 in Release 3.1(3d)
- ST300MM0008 —Firmware updated from N003 in Release 3.1(3c) to version N0A4 in Release 3.1(3d)
- ST300MP0006 —Firmware added with version N0B3 in Release 3.1(3d)
- ST4000NM0025 —Firmware added with version N0C2 in Release 3.1(3d)
- ST6000NM0014 —Firmware updated from K005 in Release 3.1(3c) to version K0E5 in Release 3.1(3d)
- ST6000NM0105 —Firmware added with version K0C2 in Release 3.1(3d)
- ST600MM0008 — Firmware updated from K002 in Release 3.1(3c) to version K0A4 in Release 3.1(3d)
- ST600MM0088 — Firmware updated from N003 in Release 3.1(3c) to version N0A4 in Release 3.1(3d)
- ST600MP0006 —Firmware added with version N0B3 in Release 3.1(3d)
- ST600MP0025 —Firmware added with version NF04 in Release 3.1(3d)
- ST900MM0168 — Firmware updated from N003 in Release 3.1(3c) to version N0A4 in Release 3.1(3d)
- ST900MP0006 —Firmware added with version N0B3 in Release 3.1(3d)

- MTFDDAV240TCB — Firmware updated from U037 in Release 3.1(3c) to version U049 in Release 3.1(3d)

Firmware for the following HDDs were updated in Release 3.1(3c):

- SSDSC2KB038T7K—Firmware updated from version CS03 in Release 3.1(3a) to version CS04 in Release 3.1(3c)
- SSDSC2KB480G7K—Firmware updated from version CS03 in Release 3.1(3a) to version CS04 in Release 3.1(3c)
- SSDSC2KB960G7K—Firmware updated from version CS03 in Release 3.1(3a) to version CS04 in Release 3.1(3c)
- SSDSC2KG019T7K—Firmware updated from version CS03 in Release 3.1(3a) to version CS04 in Release 3.1(3c)
- SSDSC2KG480G7K—Firmware updated from version CS03 in Release 3.1(3a) to version CS04 in Release 3.1(3c)
- SSDSC2KG960G7K—Firmware updated from version CS03 in Release 3.1(3a) to version CS04 in Release 3.1(3c)

The following new HDDs were added in Release 3.1(3a) :

- ST600MM0008
- ST300MM0048
- ST600MM0208
- ST600MP0026
- ST1000NM0055
- ST4000NM0035
- ST6000NM0115
- MG04ACA400N
- MG04ACA600E
- HUH721008AL4200
- HUH721008ALE600
- HUC101860CS4200
- HUH721212ALE600
- HUS726060AL4215
- MZ7LM480HMHQ-00003
- SSDSC2BB120G7K
- SSDSC2BB960G7K
- SSDSC2KB480G7K

- SSDSC2KB960G7K
- SSDSC2KB038T7K
- SSDSC2KG480G7K
- SSDSC2KG960G7K
- SSDSC2KG019T7K

Firmware for the following HDDs were updated in Release 3.1(3a):

- ST600MM0208—Firmware updated from version N0A1 in Release 3.1(2b) to version N0B1 in Release 3.1(3a)
- ST300MM0048—Firmware updated from version N0A1 in Release 3.1(2b) to version N0B1 in Release 3.1(3a)
- ST2000NX0433—Firmware updated from version N003 in Release 3.1(2b) to version N0A3 in Release 3.1(3a)
- ST1000NX0453—Firmware updated from version N003 in Release 3.1(2b) to version N0A3 in Release 3.1(3a)
- MTFDDAV960TCB—Firmware updated from version U027 in Release 3.1(2b) to version U037 in Release 3.1(3a)
- MTFDDAV240TCB—Firmware updated from version U027 in Release 3.1(2b) to version U037 in Release 3.1(3a)
- MTFDDAK960TCB—Firmware updated from version U031 in Release 3.1(2b) to version U037 in Release 3.1(3)
- MTFDDAK7T6TBY—Firmware updated from version U802 in Release 3.1(2b) to version U810 in Release 3.1(3a)
- MTFDDAK480TCB—Firmware updated from version U031 in Release 3.1(2b) to version U037 in Release 3.1(3a)
- MTFDDAK3T8TBY—Firmware updated from version U402 in Release 3.1(2b) to version U410 in Release 3.1(3a)
- MTFDDAK240TCB—Firmware updated from version U031 in Release 3.1(2b) to version U037 in Release 3.1(3a)
- MTFDDAK1T6TCC—Firmware updated from version U031 in Release 3.1(2b) to version U037 in Release 3.1(3a)
- MTFDDAK120TCC—Firmware updated from version U031 in Release 3.1(2b) to version U037 in Release 3.1(3a)
- MTFDDAK1T9TBY—Firmware updated from version U031 in Release 3.1(2b) to version U037 in Release 3.1(3a)
- HUH721010AL5200—Firmware updated from version A21D in Release 3.1(2b) to version A38K in Release 3.1(3a)
 - HUH721010AL4200—Firmware updated from version A21D in Release 3.1(2b) to version A38K in Release 3.1(3a)

The following new HDDs were added in Release 3.1(2c):

- ST300MP0006
- ST600MP0006
- ST900MP0006
- PX05SRB048
- PX05SRB096
- PX05SRB192
- PX05SRB384
- PX05SMB040
- PX05SMB080
- PX05SMB160
- PX05SVB040
- PX05SVB080
- PX05SVB160
- PX05SVB320
- SSDSC2BB150G7K
- SSDSC2BB480G7K
- SSDSC2BB016T7K
- MG04SCA20EN
- MG04SCA40EN
- MG04SCA60EA

Firmware for the following HDDs were updated in Release 3.1(2c)

- ST1200MM0088
- S650DC-400FIPS
- S650DC-800FIPS
- S650DC-1600FIPS
- AL13SXB30EN
- AL13SXB60EN
- HUC101818CS4200
- HUC101812CSS200
- ST1800MM0008

Following table lists the supported HDD models and the firmware versions that can be updated using Host Upgrade Utility (HUU).

The following new HDDs were added in Release 3.1(2b):

- MTFDDAK120TCC
- MTFDDAK1T6TCC
- MTFDDAK1T9TBY
- MTFDDAK240TCB
- MTFDDAK3T8TBY
- MTFDDAK480TCB
- MTFDDAK7T6TBY
- MTFDDAK960TCB
- MTFDDAV240TCB
- MTFDDAV960TCB
- HUH721010ALE600

Firmware for the following HDDs were updated in Release 3.1(2b)

- AL14SEB030N—Firmware updated from version 5704 in Release 3.1(1d) to version 5705 in Release 3.1(2b)
- AL14SEB060N—Firmware updated from version 5704 in Release 3.1(1d) to version 5705 in Release 3.1(2b)
- AL14SEB120N—Firmware updated from version 5704 in Release 3.1(1d) to version 5705 in Release 3.1(2b)

Table 1: Supported HDD models and firmware versions

Model	Firmware Version
ST1000NX0453	N0A3
ST2000NX0433	N0A3
ST1800MM0008	K0A4
ST600MM0008	K0A4
ST300MM0048	N0B1
ST600MM0208	N0B1
ST600MP0026	NFB3
ST1000NM0055	CS02
ST4000NM0035	CS02

Model	Firmware Version
ST6000NM0115	ES02
ST600MP0006	N0B3
ST900MP0006	N0B3
SSDSC2BX480G4K	CS01
SSDSC2BX016T4K	CS01
ST1200MM0088	N0A4
AL14SEB030N	5705
AL14SEB060N	5705
AL14SEB120N	5705
AL13SXB30EN	5703
AL13SXB60EN	5703
MG04ACA400N	5702
MG04ACA600E	5701
HUS726020ALS210	A7R4
HUS726040ALS210	A7R4
HUS726020ALA610	T990
HUH721008AL4200	A38K
HUH721010AL4200	A38K
HUH721010AL5200	A38K
HUH721008ALE600	T382
HUC101812CSS200	AD50
HUC101818CS4200	AD50
HUC101860CS4200	AD50
HUH728080AL4200	A7JX
HUS726060AL4210	A7J0
HUH721212ALE600	T3D0
ST1000NX0423	CT03
MTFDDAK120MBP	0013

Model	Firmware Version
MTFDDAK480MBP	0013
MTFDDAK960MBP	0013
MTFDDAK600MBP	0013
MTFDDAK120TCC	U054
MTFDDAK1T6TCC	U054
MTFDDAK1T9TBY	U054
MTFDDAK240TCB	U054
MTFDDAK3T8TBY	U419
MTFDDAK480TCB	U054
MTFDDAK7T6TBY	U819
MTFDDAK960TCB	U054
MTFDDAV240TCB	U054
MTFDDAV960TCB	U054
S650DC-400FIPS	MB18
S650DC-800FIPS	MB18
S650DC-1600FIPS	MB18
ST600MP0025	NF04
ST1800MM0048	KF04
HUC101830CSS205	DA01
HUC101812CSS205	DA01
HUS726040ALS215	D7J7
HUS726060AL4215	D7J0
HUS726060AL5210	A9D0
SSDSC2BX200G4K	CS01
SSDSC2BX800G4K	CS01
MZ7LM240HMHQ-00003	1F3Q
MZ7LM480HMHQ-00003	1F3Q
MZ7LM960HMJP-00003	1F3Q

Model	Firmware Version
MZ7LM1T9HMJP-00003	1F3Q
MZ7LM3T8HMLP-00003	1F3Q
ST1000NM0045	N0C2
ST2000NM0045	N0C2
ST4000NM0025	N0C2
ST2000NM0055	CS02
ST6000NM0105	K0C2
ST300MM0048	N0A1
ST600MM0208	N0A1
PX05SRB048	0103
PX05SRB096	0103
PX05SRB192	0103
PX05SRB384	0103
PX05SMB040	0103
PX05SMB080	0103
PX05SMB160	0103
PX05SVB040	0103
PX05SVB080	0103
PX05SVB160	0103
PX05SVB320	0103
SSDSC2BB120G7K	CS01
SSDSC2BB150G7K	CS01
SSDSC2BB480G7K	CS01
SSDSC2BB960G7K	CS01
SSDSC2BB016T7K	CS01
SSDSC2KB480G7K	CS05
SSDSC2KB960G7K	CS05
SSDSC2KB038T7K	CS05

Model	Firmware Version
SSDSC2KG480G7K	CS05
SSDSC2KG960G7K	CS05
SSDSC2KG019T7K	CS05
MG04SCA20EN	5703
MG04SCA40EN	5703
MG04SCA60EA	5703
HUH721010ALE600	T382
ST300MP0006	N0B3

