



## New and Changed Information

---

- [New and Changed Information](#), on page 1

## New and Changed Information

This section provides information on new feature and changed behavior in Cisco UCS Manager, Release 4.1.

**Table 1: New Features and Changed Behavior in Cisco UCS Manager, Release 4.1(1a)**

Feature	Description	Where Documented
Cisco UCS 64108 Fabric Interconnect	This release introduces Cisco UCS 64108 Fabric Interconnects that support 96 10/25 Gigabit ports in the fabric with 12 40/100 Gigabit uplink ports.	<a href="#">Cisco UCS 64108 Fabric Interconnect</a>

