



New and Changed Information

- [New and Changed Information](#), on page 1

New and Changed Information

This section provides information on new feature and changed behavior in Cisco UCS Manager, Release 4.0(1a).

Table 1: New Features and Changed Behavior in Cisco UCS Manager, Release 4.0(1a)

Feature	Description	Where Documented
Cisco UCS 6454 Fabric Interconnect	This release introduces Cisco UCS 6454 Fabric Interconnect that support 10/25 Gigabit ports in the fabric with 40/100 Gigabit uplink ports.	Unified Storage Ports
Cisco UCS C125 M5 Server	Cisco UCS Manager extends support for all existing features on Cisco UCS C125 M5 Server.	PCH SSD Controller Definition

