



## New and Changed Information

---

- [New and Changed Information for This Release, on page 1](#)

### New and Changed Information for This Release

The following table provides an overview of the significant changes to this guide for Cisco UCS Manager, Release 4.1. The table does not provide an exhaustive list of all changes made to this guide or of all new features in this release.

**Table 1: New Features and Changed Behavior in Cisco UCS Manager, Release 4.1(1)**

Feature	Description	Where Documented
Cisco UCS 64108 Fabric Interconnect	This release introduces Cisco UCS 64108 Fabric Interconnects that support 10/25 Gigabit ports in the fabric with 40/100 Gigabit uplink ports.	<a href="#">Cisco UCS 64108 Fabric Interconnect</a>

