



Release Notes for Cisco D9865 Satellite Receiver Version 2.75

First Published: 2017-03-17

Overview

This document describes the resolved caveats and open caveats in Version 2.75 for the Cisco D9865 Satellite Receiver.

Caveats

This section includes open and resolved caveats for this release. This section includes the following topics.

- [Open Caveats - Version 2.75, on page 1](#)
- [Resolved Caveats - Version 2.75, on page 1](#)

Open Caveats - Version 2.75

There are no open caveats for Version 2.75.

Resolved Caveats - Version 2.75

The following lists a resolved caveat in Version 2.75. The caveat ID can be searched using the Cisco Bug Search Tool (<https://tools.cisco.com/bugsearch>), where you can find details about the caveat.

Bug ID	Description
CSCvc44321	Conditional Access robustness enhancements.

Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, using the Cisco Bug Search Tool (BST), submitting a service request, and gathering additional information, see [What's New in Cisco Product Documentation](#).

To receive new and revised Cisco technical content directly to your desktop, you can subscribe to the [What's New in Cisco Product Documentation RSS feed](#). RSS feeds are a free service.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <http://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2017 Cisco Systems, Inc. All rights reserved.