



Release Notes for Cisco D9865 Satellite Receiver Version 2.90

First Published: 2018-03-27

Overview

This document describes the new features, resolved caveats, and open caveats in Version 2.90 for the Cisco D9865 Satellite Receiver.

New Features

The following lists the new feature for Version 2.90:

- Enhancements to PowerVu robustness.

Caveats

This section includes open and resolved caveats for this release. This section includes the following topics.

- [Open Caveats, on page 1](#)
- [Resolved Caveats, on page 1](#)

Open Caveats

There are no open caveats for Version 2.90.

Resolved Caveats

The following lists a resolved caveat in Version 2.90. The caveat ID can be searched using the Cisco Bug Search Tool (<https://tools.cisco.com/bugsearch>), where you can find details about the caveat.

Bug ID	Description
CSCvi01637	Custom SI Recv mode, with Service List Degraded and NIT enabled, leads to local decode loss.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

© 2018 Cisco Systems, Inc. All rights reserved.