



Release Notes for Cisco Small Business SPA525G2-EU Firmware Version 7.5.6c

First Published: February 5, 2015

Introduction

As with any firmware release, read these release notes before you upgrade the firmware. Cisco also recommends that you back up the configuration before you perform any firmware upgrade.



Note

These Release Notes describe the updates and fixes in version 7.5.6c of the Cisco SPA525G2 firmware.

Related Documentation

Use the following sections to obtain related information.

Cisco Small Business

For more information on Cisco Small Business, see <http://www.cisco.com/smb>

Cisco Small Business Product Documentation

For more information on Cisco Small Business SPA500, see www.cisco.com/go/spa500phones

For more information on Regulatory Compliance and Safety Information for the Cisco SPA300 Series and Cisco SPA500 Series IP Phones, see

http://www.cisco.com/c/dam/en/us/td/docs/voice_ip_comm/csbpipp/ip_phones/regulatory_compliance/guide/rcsi_SPA300_SPA500.pdf



Hardware and Firmware Compatibility

The following matrix describes the hardware and firmware compatibility.

	SN Range	7.5.6c, 7.5.5c, 7.5.6, 7.5.5b	7.5.5 or earlier
EU SKU (128M flash)	NA	Yes	No
Old SKU1 (128M flash)	CCQ18160L03 and after	Yes	No
Old SKU2 (32M flash)	Before CCQ18160L03	Yes	Yes


Note

For EU SKU load firmware 7.5.6c/7.5.5c, the Wi-Fi power is changed to apply to meet EU EN300328 V1.8.1 standard. For all other hardware and firmware combinations, the Wi-Fi power is not changed.


Note

Upon firmware and release note readiness for release 7.5.6c, EU SKUs have not been produced. So EU SKU SN info is NA and it will be updated in next version of the release notes.

New and Changed Feature

Wi-Fi Power

7.5.6c feature set is identical to 7.5.6, except that in EU SKU load firmware 7.5.6c, the Wi-Fi power is changed to apply to meet the EU EN300328 V1.8.1 standard.


Note

Another firmware version, 7.5.5c, exists for the SPA525G2-EU phone. The feature set is identical to 7.5.5b, except that in EU SKU load firmware 7.5.5c, the Wi-Fi power is changed to apply to meet the EU EN300328 V1.8.1 standard.

Installation

This release contains no Installation information.

Caveats

Open Caveats

Identifier	Summary
CSCub46017	If the font size is 12, then the Hebrew character will be cut off from the top. Note The phone does not support font size, 12 for Hebrew language.
CSCub68641	Missing an option to add "+" sign in the numeric input for PAB number entry.
CSCua96505	When a SPA525 phone has 5 Broadsoft shared lines, the SCAC code fails to subscribe each line with the Edgemark router.

Resolved Caveats

There are no resolved caveats for this release

Behavior During Times of Network Congestion

Anything that degrades network performance can affect voice and video quality, and in some cases, can cause a call to drop. Sources of network degradation can include, but are not limited to, the following activities:

- Administrative tasks, such as an internal port scan or security scan
- Attacks that occur on your network, such as a Denial of Service attack

To reduce or eliminate any adverse effects to the devices, schedule administrative network tasks during a time when the devices are not being used or exclude the devices from testing.

Documentation, Service Requests, and Additional Information

For more information on Cisco Small Business Support Community, see <http://www.cisco.com/go/smallbizsupport>

For more information on Cisco Small Business Support and Resources, see <http://www.cisco.com/go/smallbizhelp>

To access the Phone Support Contacts, see http://www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html

For downloading the documents, see <http://www.cisco.com/go/smallbizfirmware>

Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, using the Cisco Bug Search Tool (BST), submitting a service request, and gathering additional information, see *What's New in Cisco Product Documentation* at: <http://www.cisco.com/c/en/us/td/docs/general/whatsnew/whatsnew.html>.

Subscribe to *What's New in Cisco Product Documentation*, which lists all new and revised Cisco technical documentation as an RSS feed and delivers content directly to your desktop using a reader application. The RSS feeds are a free service.

This document is to be used in conjunction with the documents listed in the “[Related Documentation](#)” section.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

© 2015 Cisco Systems, Inc. All rights reserved.