

Cisco Unified Communications Device Package 12.5(1.18198-1) Release Notes

First Published: 2023-07-17

Introduction

Cisco Unified Communications Manager Device Package Release 12.5(1.18198-1) provides database and firmware updates for Cisco Unified Communications Manager 12.5(1).

For information about all released Cisco Unified Communications Manager device packages, see the [Cisco Unified Communications Manager Device Package Compatibility Matrix](#).

For information about how to install Cisco Unified Communications Manager device packages, see the [Cisco Unified Communications Manager Device Package Installation Guide](#).



Caution

Installing the Device Package on the Publisher causes all of the device XML data to be reloaded into the database. This can cause high CPU on the Subscribers while these changes are being processed. It is recommended that Device Package installations occur during a maintenance window to minimize the impact of the database updates.

Cisco Unified Communications Device Package 12.5(1.18198-1)

The Cisco Unified Communications Manager Device Package 12.5(1.18198-1) filename and MD5 are in the following table.

Table 1: Cisco Options Package Filename and MD5

File	MD5
cmterm-devicepack12.5.1.18198-1.cop.sha512	33ee5e2cce47de6775a80debfc4f749c

Use the information in the following table to determine if you must install this device package.

Table 2: Cisco Unified Communications Manager Device Package Release 12.5(1.18198-1)

Device	Bug ID	Headline	Database Update	Firmware Upgrade	Notes
Cisco IP Phone 7800 Series, Cisco IP Phone 8800 Series	CSCwf28215	14.2(1)SR1 SIP phone loads firmware for 7800 and 8800 IP Phones	No	Yes	For more information, see https://bst.cloudapps.cisco.com/bugsearch/bug/CSCwf28215 .

Device	Bug ID	Headline	Database Update	Firmware Upgrade	Notes
Cisco IP Phone 7800 Series, Cisco IP Phone 8800 Series	CSCwe97279	QED files for Cisco 78xx/88xx/7832 phones	Yes	No	For more information, see https://bst.cloudapps.cisco.com/bugsearch/bug/CSCwe97279 .
Cisco Video Phone 8875	CSCwf07956	checkin QED files for 8875 PhoneOS 2.1 to CUCM	Yes	No	For more information, see https://bst.cloudapps.cisco.com/bugsearch/bug/CSCwf07956 .
Cisco Video Phone 8875	CSCwf38525	checkin QED files for 8875 PhoneOS 2.2 to CUCM	Yes	No	For more information, see https://bst.cloudapps.cisco.com/bugsearch/bug/CSCwf38525 .
Cisco Video Phone 8875	CSCwf07954	checkin 2.1.1 firmware files for 8875 IP Phones to CUCM	No	Yes	For more information, see https://bst.cloudapps.cisco.com/bugsearch/bug/CSCwf07954 .
Cisco Room Kit EQX	CSCwf43432	QED files for the Cisco Room Kit EQX product	Yes	No	For more information, see https://bst.cloudapps.cisco.com/bugsearch/bug/CSCwf43432 .
Cisco Room Bar Pro	CSCwe03752	QED files for the Cisco Room Bar Pro product	Yes	No	For more information, see https://bst.cloudapps.cisco.com/bugsearch/bug/CSCwe03752 .

Firmware Table

The Cisco Unified Communications Manager Device Package Release 12.5(1.18198-1) contains loads for the following device releases.



Note The device package also contains configuration files for many Cisco Webex models. If there are any new configuration files for these models, they are listed in the previous table: [Cisco Unified Communications Device Package 12.5\(1.18198-1\), on page 1](#). You can get the latest firmware for these models from the [Download Software](#) page.

Firmware Versions in this Release

Device type	Load name	Version
3905	3905.9-4-1SR3	9.4 (1SR3.0)
3911_3951-sip	3911_3951-sip.8-1-4a	8.1 (4.0)
6608	6608-4.0.0.32-mgcp	4.0 (0.32)
6608cfb	6608cfb-4.0.0.03-sccp	4.0 (0.3)
6608mtp	6608mtp-4.0.0.06-sccp	4.0 (0.6)
6624	6624-4.0.0.13-mgcp	4.0 (0.13)
6901-sccp	6901-sccp.9-3-1-SR2-2	9.3 (1.0)
6901-sip	6901-sip.9-3-1-SR2-3	9.3 (1.0)
6911-sccp	6911-sccp.9-3-1-SR2-3	9.3 (1.0)

6911-sip	6911-sip.9-3-1-SR2-4	9.3(1.0)
6945-SCCP	6945-SCCP-9-4-1-3SR3	9.4(1.3)
6945-SIP	6945-SIP-9-4-1-3SR3	9.4(1.3)
69xx-SCCP	69xx-SCCP-9-4-1-3SR3	9.4(1.3)
69xx-SIP	69xx-SIP-9-4-1-3SR3	9.4(1.3)
7832-sip	7832-sip.14-2-1-0101-26.k4	14.2.1(0101.26)
78xx	78xx.14-2-1-0101-26.k4	14.2.1(0101.26)
7911_7906-sccp	7911_7906-sccp.9-4-2SR3-1	9.4(2SR3.1)
7911_7906-sip	7911_7906-sip.9-4-2SR3-1	9.4(2SR3.1)
7914-sccp	7914-sccp.5-0-4	5.0(4.0)
7915	7915.1-0-4-2	1.0(4.2)
7916	7916.1-0-4-2	1.0(4.2)
7925-sccp	7925-sccp.1-4-8SR1-5.k3	1.4(8SR1.5)
7926-sccp	7926-sccp.1-4-8SR1-5.k3	1.4(8SR1.5)
7931-sccp	7931-sccp.9-4-2SR2-2	9.4(2SR2.2)
7931-sip	7931-sip.9-4-2SR2-2	9.4(2SR2.2)
7936-sccp	7936-sccp.3-3-21	3.3(21.0)
7937	7937-1-4-5-7-SCCP	1.4(5.7)
7940-7960	7940-7960-8.12.00-sip	8.12(00.0)
7940-7960-sccp	7940-7960-sccp.8-1-2SR2	8.1(2SR2.0)
7941_7961-sccp	7941_7961-sccp.9-4-2SR3-1	9.4(2SR3.1)
7941_7961-sip	7941_7961-sip.9-4-2SR3-1	9.4(2SR3.1)
7942_7962-sccp	7942_7962-sccp.9-4-2SR3-1	9.4(2SR3.1)
7942_7962-sip	7942_7962-sip.9-4-2SR3-1	9.4(2SR3.1)
7945_7965-sccp	7945_7965-sccp.9-4-2SR4	9.4(2SR4.0)
7945_7965-sip	7945_7965-sip.9-4-2SR4-3	9.4(2SR4.3)
7975-sccp	7975-sccp.9-4-2SR4	9.4(2SR4.0)
7975-sip	7975-sip.9-4-2SR4	9.4(2SR4.0)
7985	7985-4-1-7-0-sccp	4.1(7.0)
8821-sip	8821-sip.11-0-6SR4-3.k4	11.0(6SR4.3)
8831-sip	8831-sip.10-3-1SR7-2	10.3(1SR7.2)
8832-sip	8832-sip.14-2-1-0101-26.k4	14.2.1(0101.26)
8845_65-sip	8845_65-sip.14-2-1-0101-26.k4	14.2.1(0101.26)
88xx-sip	88xx-sip.14-2-1-0101-26.k4	14.2.1(0101.26)
894x-sccp	894x-sccp.9-4-2SR3-1	9.4(2SR3.1)
894x-sip	894x-sip.9-4-2SR3-1	9.4(2SR3.1)
8961	8961.9-4-2SR4-1.k3	9.4(2SR4.1)
9951	9951.9-4-2SR4-1.k3	9.4(2SR4.1)
9971	9971.9-4-2SR4-1.k3	9.4(2SR4.1)
ata	ata-3.2.4-sccp	3.2(4.0)
ata187	ata187.9-2-3-1	9.2(3.1)
ata190	ata190.1-2-2-003	1.2(2.3)
ATA191	ATA191.12-0-1-0506-010	12.0.1(0506.10)
headset-builtin	headset-builtin.3-1-0001-1.k4	3.1(0001.1)
PHONEOS-8875	PHONEOS-8875.2-1-1-0001-11	2.1.1(0001.11)

