

Cisco Unified Communications Device Package 14.0(1.14056-2) Release Notes

First Published: 2024-04-29

Introduction

Cisco Unified Communications Manager Device Package Release 14.0(1.14056-2) provides database and firmware updates for Cisco Unified Communications Manager 14.

For information about all released Cisco Unified Communications Manager device packages, see the [Cisco Unified Communications Manager Device Package Compatibility Matrix](#).

For information about how to install Cisco Unified Communications Manager device packages, see the [Cisco Unified Communications Manager Device Package Installation Guide](#).



Caution Installing the Device Package on the Publisher causes all of the device XML data to be reloaded into the database. This can cause high CPU on the Subscribers while these changes are being processed. It is recommended that Device Package installations occur during a maintenance window to minimize the impact of the database updates.

Cisco Unified Communications Device Package 14



Caution After applying the device package COP file, make sure that any future full upgrades are to a version that contains the device package fixes natively. Otherwise, some of the functionality added by the device package may be lost following the upgrade. If an upgrade to a version that does not contain the fixes natively is necessary, install the appropriate device package COP file to restore functionality.

The Cisco Unified Communications Manager Device Package 14.0(1.14056-2) filename and MD5 are in the following table.

Table 1: Cisco Options Package Filename and MD5

File	MD5
cmterm-devicepack14.0.1.14056-2.cop.sha512	b6e2232a453631e9bd3d322fc413dc53

Use the information in the following table to determine if you must install this device package.

Table 2: Cisco Unified Communications Manager Device Package Release 14.0(1.14056-2)

Device	Bug ID	Headline	Database Update	Firmware Upgrade	Notes
Desk Phone 9800 Series	CSCwj47899	checkin QED files for 9800 portfolio IP Phones into CUCM	Yes	No	For more information, see https://bst.cloudapps.cisco.com/bugsearch/bug/CSCwj47899 .
Wireless Phone 840	CSCwi04179	1.10(2) QED files for Cisco Wireless Phone 840	Yes	No	For more information, see https://bst.cloudapps.cisco.com/bugsearch/bug/CSCwi04179 .
Wireless Phone 860	CSCwi04180	1.10(2) QED files for Cisco Wireless Phone 860	Yes	No	For more information, see https://bst.cloudapps.cisco.com/bugsearch/bug/CSCwi04180 .
Many Webex Endpoints	CSCwj14266	Update valuespace for MaxTotalSessions in QED/devpack	Yes	No	For more information, see https://bst.cloudapps.cisco.com/bugsearch/bug/CSCwj14266 .
Cisco Board Pro G2	CSCwh93869	QED files for the Cisco Board Pro G2 product	Yes	No	For more information, see https://bst.cloudapps.cisco.com/bugsearch/bug/CSCwh93869 .

Firmware Table

The Cisco Unified Communications Manager Device Package Release 14.0(1.14056-2) contains loads for the following device releases.



Note The device package also contains configuration files for many Cisco Webex models. If there are any new configuration files for these models, they are listed in the previous table: [Cisco Unified Communications Device Package 14, on page 1](#). You can get the latest firmware for these models from the [Download Software](#) page.

Firmware Versions in this Release

Device type	Load name	Version
3905	3905.9-4-1SR4-2	9.4 (1SR4.2)
3911_3951-sip	3911_3951-sip.8-1-4a	8.1 (4.0)
6608	6608-4.0.0.32-mgcp	4.0 (0.32)
6608cfb	6608cfb-4.0.0.03-sccp	4.0 (0.3)
6608mtp	6608mtp-4.0.0.06-sccp	4.0 (0.6)
6624	6624-4.0.0.13-mgcp	4.0 (0.13)
6901-sccp	6901-sccp.9-3-1-SR3-1	9.3 (1.0)
6901-sip	6901-sip.9-3-1-SR3-1	9.3 (1.0)
6911-sccp	6911-sccp.9-3-1-SR2-3	9.3 (1.0)
6911-sip	6911-sip.9-3-1-SR2-4	9.3 (1.0)
6945-SCCP	6945-SCCP-9-4-1-3SR3	9.4 (1.3)
6945-SIP	6945-SIP-9-4-1-3SR3	9.4 (1.3)

69xx-SCCP	69xx-SCCP-9-4-1-3SR3	9.4(1.3)
69xx-SIP	69xx-SIP-9-4-1-3SR3	9.4(1.3)
7832-sip	7832-sip.14-2-1-0201-40.k4	14.2.1(0201.40)
78xx	78xx.14-2-1-0201-40.k4	14.2.1(0201.40)
7911_7906-sccp	7911_7906-sccp.9-4-2SR3-1	9.4(2SR3.1)
7911_7906-sip	7911_7906-sip.9-4-2SR3-1	9.4(2SR3.1)
7914-sccp	7914-sccp.5-0-4	5.0(4.0)
7915	7915.1-0-4-2	1.0(4.2)
7916	7916.1-0-4-2	1.0(4.2)
7925-sccp	7925-sccp.1-4-8SR1-5.k3	1.4(8SR1.5)
7926-sccp	7926-sccp.1-4-8SR1-5.k3	1.4(8SR1.5)
7931-sccp	7931-sccp.9-4-2SR2-2	9.4(2SR2.2)
7931-sip	7931-sip.9-4-2SR2-2	9.4(2SR2.2)
7936-sccp	7936-sccp.3-3-21	3.3(21.0)
7937	7937-1-4-5-7-SCCP	1.4(5.7)
7940-7960	7940-7960-8.12.00-sip	8.12(00.0)
7940-7960-sccp	7940-7960-sccp.8-1-2SR2	8.1(2SR2.0)
7941_7961-sccp	7941_7961-sccp.9-4-2SR3-1	9.4(2SR3.1)
7941_7961-sip	7941_7961-sip.9-4-2SR3-1	9.4(2SR3.1)
7942_7962-sccp	7942_7962-sccp.9-4-2SR3-1	9.4(2SR3.1)
7942_7962-sip	7942_7962-sip.9-4-2SR3-1	9.4(2SR3.1)
7945_7965-sccp	7945_7965-sccp.9-4-2SR3-1	9.4(2SR3.1)
7945_7965-sccp	7945_7965-sccp.9-4-2SR4	9.4(2SR4.0)
7945_7965-sip	7945_7965-sip.9-4-2SR4-3	9.4(2SR4.3)
7975-sccp	7975-sccp.9-4-2SR3-1	9.4(2SR3.1)
7975-sccp	7975-sccp.9-4-2SR4	9.4(2SR4.0)
7975-sip	7975-sip.9-4-2SR4	9.4(2SR4.0)
7985	7985-4-1-7-0-sccp	4.1(7.0)
8821-sip	8821-sip.11-0-6SR5-5.k4	11.0(6SR5.5)
8831-sip	8831-sip.10-3-1SR7-2	10.3(1SR7.2)
8832-sip	8832-sip.14-2-1-0201-40.k4	14.2.1(0201.40)
8845_65-sip	8845_65-sip.14-2-1-0201-40.k4	14.2.1(0201.40)
88xx-sip	88xx-sip.14-2-1-0201-40.k4	14.2.1(0201.40)
894x-sccp	894x-sccp.9-4-2SR3-1	9.4(2SR3.1)
894x-sip	894x-sip.9-4-2SR3-1	9.4(2SR3.1)
8961	8961.9-4-2SR4-1.k3	9.4(2SR4.1)
9951	9951.9-4-2SR4-1.k3	9.4(2SR4.1)
9971	9971.9-4-2SR4-1.k3	9.4(2SR4.1)
ata	ata-3.2.4-sccp	3.2(4.0)
ata187	ata187.9-2-3-1	9.2(3.1)
ata190	ata190.1-2-2-003_SR2-1	1.2(2.3)
ATA191	ATA191.12-0-1-0506-010	12.0.1(0506.10)
headset-builtin	headset-builtin.3-2-0001-1.k4	3.2(0001.1)
PHONEOS-8875	PHONEOS-8875.2-3-1-0001-26	2.3.1(0001.26)

