



Cisco Unified IP Phone 7960G and 7940G Release Notes for Firmware Release 8.1(2) (SCCP)

First Published: August 25, 2009

Last Updated: April 13, 2010

Use these release notes with the Cisco Unified IP Phone 7960G and 7940G running SCCP firmware release 8.1(2).

This firmware release is compatible with Cisco Unified Communications Manager releases 7.1, 7.0, 6.1 and 6.0, Cisco Unified CallManager releases 5.1, 5.0, 4.3, 4.2, 4.1, 4.0, and Cisco CallManager release 3.3.

Contents

These release notes provide the following information:

- [Related Documentation, page 1](#)
- [Installation Notes, page 2](#)
- [Caveats, page 3](#)
- [Obtaining Documentation and Submitting a Service Request, page 4](#)

Related Documentation

Cisco Unified IP Phone Documentation

Refer to publications that are specific to your language, phone model and Cisco Unified Communications Manager release. Navigate from the following documentation URL:

http://www.cisco.com/en/US/products/hw/phones/ps379/tsd_products_support_series_home.html

Cisco Unified Communications Manager Documentation

Refer to the Cisco Unified Communications Manager Documentation Guide and other publications specific to your Cisco Unified Communications Manager release. Navigate from the following URL:



Americas Headquarters:

Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA

© 2009-2010 Cisco Systems, Inc. All rights reserved.

http://www.cisco.com/en/US/products/sw/voicesw/ps556/tsd_products_support_series_home.html

Cisco Unified Communications Manager Business Edition Documentation

Refer to the Cisco Unified Communications Manager Business Edition Documentation Guide and other publications that are specific to your Cisco Unified Communications Manager release. Navigate from the following URL:

http://www.cisco.com/en/US/products/ps7273/tsd_products_support_series_home.html

New and Changed Information

There is no new or changed information for firmware release 8.1(2).

Installation Notes

Before using the Cisco Unified IP Phone 7960G or 7940G with Cisco Unified Communications Manager release 7.1 or earlier, you must install the latest firmware on all Cisco Unified Communications Manager servers in the cluster.



Note

You cannot upgrade to firmware release 8.1(2) directly from firmware release 8.0(10) or an earlier release. You have to upgrade to firmware release 8.1(1) first, then upgrade from release 8.1(1) to release 8.1(2).

To download and install the firmware, follow these steps:

Procedure

-
- Step 1** Go to the following URL:
<http://tools.cisco.com/support/downloads/pub/Redirect.x?mdfid=278875240>.
- Step 2** Log in to the Tools and Resources Download page.
- Step 3** Choose the **IP Telephony** folder by clicking +.
- Step 4** Choose the **IP Phones** folder.
- Step 5** Choose the **Cisco Unified IP Phones 7900 Series** folder.
- Step 6** Choose the **Cisco Unified IP Phone 7960G** link or the **Cisco Unified IP Phone 7940G** link.
- Step 7** Choose the **Skippy Client Control Protocol (SCCP) Software**.
- Step 8** Choose **8.1(2)** from the **Latest Releases** folder.
- Step 9** To download the firmware for the Cisco Unified IP Phone 7960G and 7940G, select one of the following files and follow the prompts:
- For Cisco CallManager 4.3 and earlier:
cmterm-7940-7960-sccp.8-1-2.exe
 - For Cisco Unified CallManager 5.0(1), 5.0(2), and 5.0(3):
cmterm-7940-7960-sccp.8-1-2.cop

- For Cisco Unified CallManager 5.0(4) and later:

cmterm-7940-7960-sccp.8-1-2.cop.sgn

Step 10 Double-click one of the downloadable files in [Step 1](#) and click the Readme hyperlink, under the Additional Information section, which contains installation instructions for the corresponding firmware:

cmterm-7940-7960-sccp.8-1-2-readme.html

Follow the instructions in the Readme file to install the firmware.

Caveats

This section contains these topics:

- [Using Bug Toolkit, page 3](#)
- [Open Caveats, page 3](#)
- [Resolved Caveats, page 4](#)

Using Bug Toolkit

Known problems (bugs) are graded according to severity level. These release notes contain descriptions of:

- All severity level 1 or 2 bugs.
- Significant severity level 3 bugs.

You can search for problems by using the Cisco Software Bug Toolkit.

To access Bug Toolkit, you need the following items:

- Internet connection
- Web browser
- Cisco.com user ID and password

To use the Software Bug Toolkit, follow these steps:

Procedure

- Step 1** To access the Bug Toolkit, go to <http://tools.cisco.com/Support/BugToolKit/action.do?hdnAction=searchBugs>.
- Step 2** Log on with your Cisco.com user ID and password.
- Step 3** To look for information about a specific problem, enter the bug ID number in the “Search for bug ID” field, then click **Go**.
-

Open Caveats

There are no open caveats for firmware release 8.1(2).

Resolved Caveats

Table 1 lists Severity 1, 2 and 3 defects that are resolved for the Cisco Unified IP Phone 7960G and 7940G using the SCCP version of firmware release 8.1(2).

For more information about an individual defect, you can access the online record for the defect by clicking the Identifier or going to the URL shown. You must be a registered Cisco.com user to access this online information.

Because defect status continually changes, be aware that Table 1 reflects a snapshot of the defects that were resolved at the time this report was compiled. For an updated view of resolved defects, access Bug Toolkit as described in the “Using Bug Toolkit” section on page 3.

Table 1 Resolved SCCP Caveats for the Cisco Unified IP Phone 7960G and 7940G

Identifier	Headline and Bug Toolkit Link
CSCsz45786	VoIP capabilities bit is missing during initial boot for Cisco Discovery Protocol (CDP)
CSCta62377	Update copyright year on boot display to 2009

Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, submitting a service request, and gathering additional information, see the monthly *What’s New in Cisco Product Documentation*, which also lists all new and revised Cisco technical documentation, at:

<http://www.cisco.com/en/US/docs/general/whatsnew/whatsnew.html>

Subscribe to the *What’s New in Cisco Product Documentation* as a Really Simple Syndication (RSS) feed and set content to be delivered directly to your desktop using a reader application. The RSS feeds are a free service and Cisco currently supports RSS version 2.0.

CCDE, CCENT, CCSI, Cisco Eos, Cisco Explorer, Cisco HealthPresence, Cisco IronPort, the Cisco logo, Cisco Nurse Connect, Cisco Pulse, Cisco SensorBase, Cisco StackPower, Cisco StadiumVision, Cisco TelePresence, Cisco TrustSec, Cisco Unified Computing System, Cisco WebEx, DCE, Flip Channels, Flip for Good, Flip Mino, Flipshare (Design), Flip Ultra, Flip Video, Flip Video (Design), Instant Broadband, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn, Cisco Capital, Cisco Capital (Design), Cisco:Financed (Stylized), Cisco Store, Flip Gift Card, and One Million Acts of Green are service marks; and Access Registrar, Aironet, AllTouch, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Lumin, Cisco Nexus, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, Continuum, EtherFast, EtherSwitch, Event Center, Explorer, Follow Me Browsing, GainMaker, iLNX, IOS, iPhone, IronPort, the IronPort logo, Laser Link, LightStream, Linksys, MeetingPlace, MeetingPlace Chime Sound, MGX, Networkers, Networking Academy, PCNow, PIX, PowerKEY, PowerPanels, PowerTV, PowerTV (Design), PowerVu, Prisma, ProConnect, ROSA, SenderBase, SMARTnet, Spectrum Expert, StackWise, WebEx, and the WebEx logo are registered trademarks of Cisco and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1002R)

Any Internet Protocol (IP) addresses used in this document are not intended to be actual addresses. Any examples, command display output, and figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses in illustrative content is unintentional and coincidental.

© 2009-2010 Cisco Systems, Inc. All rights reserved.