

Cisco IP Conference Phone 8832 Release Notes for Firmware Release 14.2(1)SR2

November 27, 2023

Contents

Cisco IP Conference Phone 8832 Release Notes for Firmware Release 14.2(1)SR2	3
New and Changed Features	3
Features Available with the Firmware Release	3
Configurable DNS when DHCP is on	3
Caveats	3
View Caveats	3
Cisco IP Phone Firmware Support Policy	3

Cisco IP Conference Phone 8832 Release Notes for Firmware Release 14.2(1)SR2

These release notes support the Cisco IP Phone 8832 and 8832NR running SIP Firmware Release 14.2(1)SR2.

New and Changed Features

Features Available with the Firmware Release

The following sections describe the features available with the Firmware Release.

Configurable DNS when DHCP is on

With this feature enhancement, the end users can modify the DNS address on the phone when DHCP is on. After a network reset in the phone menu, the DNS address will be reset and the phone will then automatically get a DNS address from the DHCP server.

Caveats

View Caveats

We report open and resolved customer-found bugs of severity 1 to 3. You can find details about listed bugs and search for other bugs by using the Cisco Bug Search Tool. For more info on using the Bug Search, see [Bug Search Tool Help](#).

- Use this URL for all caveats:

[https://bst.cloudapps.cisco.com/bugsearch/search?kw=&pf=prdNm&pfVal=284729655&rls=14.2\(1\)SR2&sb=anfr&svr=3nH&bt=custV](https://bst.cloudapps.cisco.com/bugsearch/search?kw=&pf=prdNm&pfVal=284729655&rls=14.2(1)SR2&sb=anfr&svr=3nH&bt=custV)

- Use this URL for all open caveats:

[https://bst.cloudapps.cisco.com/bugsearch/search?kw=&pf=prdNm&pfVal=284729655&rls=14.2\(1\)SR2&sb=af&sts=open&svr=3nH&bt=custV](https://bst.cloudapps.cisco.com/bugsearch/search?kw=&pf=prdNm&pfVal=284729655&rls=14.2(1)SR2&sb=af&sts=open&svr=3nH&bt=custV)

- Use this URL for all resolved caveats:

[https://bst.cloudapps.cisco.com/bugsearch/search?kw=&pf=prdNm&pfVal=284729655&rls=14.2\(1\)SR2&sb=fr&sts=fd&svr=3nH&bt=custV](https://bst.cloudapps.cisco.com/bugsearch/search?kw=&pf=prdNm&pfVal=284729655&rls=14.2(1)SR2&sb=fr&sts=fd&svr=3nH&bt=custV)

Cisco IP Phone Firmware Support Policy

For information on the support policy for phones, see <https://cisco.com/go/phonefirmwaresupport>.

Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)