

Cisco 2900 サービス統合型ルータのパスワード回復手順

目次

[はじめに](#)

[前提条件](#)

[要件](#)

[使用するコンポーネント](#)

[関連製品](#)

[表記法](#)

[ステップバイステップ手順](#)

[パスワード回復手順の例](#)

[関連情報](#)

[はじめに](#)

このドキュメントでは、**enable password** および **enable secret** のパスワードを回復する手順について説明します。これらのパスワードは、特権 EXEC モードおよびコンフィギュレーションモードへのアクセスを保護します。**enable password** のパスワードは回復可能ですが、**enable secret** のパスワードは暗号化されているため、新しいパスワードで置き換える必要があります。**enable secret** のパスワードを置き換えるには、このドキュメントで説明されている手順に従います。

[前提条件](#)

[要件](#)

このドキュメントに関しては個別の要件はありません。

[使用するコンポーネント](#)

このドキュメントの情報は、次のハードウェアのバージョンに基づくものです。

- Cisco 2900 シリーズ サービス統合型ルータ (ISR)

本書の情報は、特定のラボ環境にあるデバイスに基づいて作成されたものです。このドキュメントで使用するすべてのデバイスは、初期 (デフォルト) 設定の状態から起動しています。稼働中のネットワークで作業を行う場合、コマンドの影響について十分に理解したうえで作業してください。

[関連製品](#)

関連製品のパスワードの回復方法については、『[パスワード回復手順](#)』を参照してください。


表記法

ドキュメント表記の詳細は、『[シスコテクニカルティップスの表記法](#)』を参照してください。

ステップバイステップ手順

パスワードを回復するには、次の手順を実行します。

1. ルータの電源を切るか、シャットダウンします。
2. ルータの背面にあるコンパクトフラッシュを取り外します。次の図は、2951 ルータの背面です。



詳細については、『[Cisco 2921 および 2951 ルータの背面パネル スロットおよびコネクタ](#)』を参照してください。

3. ルータの電源を入れます。
4. ルータが ROMmon モードになったら、コンパクトフラッシュを再度挿入します。
5. フラッシュからブートするには、rommon 1> プロンプトで [confreg 0x2142](#) と入力します。この手順により、パスワードが格納されているスタートアップコンフィギュレーションがバイパスされます。
6. rommon 2> プロンプトで **reset** と入力します。ルータがリブートしますが、保存されたコンフィギュレーションは無視されます。
7. セットアップのそれぞれの質問の後に **no** と入力するか、**Ctrl+C** キーを押して初期セットアップ手順をスキップします。
8. Router> プロンプトで **enable** と入力します。これでイネーブルモードになり、Router# プロンプトが表示されます。
9. **configure memory** または **copy startup-config running-config** と入力して、不揮発性 RAM (NVRAM) の内容をメモリにコピーします。**警告**：**copy running-config startup-config** または **write** を入力しないでください。これらのコマンドを使用すると、スタートアップコンフィギュレーションが消去されます。
10. [show running-config](#) コマンドを発行します。**show running-config** コマンドにより、ルータのコンフィギュレーションが表示されます。このコンフィギュレーションでは、**shutdown** コマンドがすべてのインターフェイスに設定されています。つまり、すべてのインターフェイスが現在シャットダウンされています。また、パスワード (イネーブルパスワード、イネーブルシークレット、vty、コンソールパスワード) は、暗号化形式か非暗号化形式のいずれかになっています。非暗号化形式のパスワードは再使用できます。暗号化形式のパスワードは新しいパスワードに変更する必要があります。
11. **configure terminal** と入力します。hostname(config)# プロンプトが表示されます。
12. **enable secret <password>** と入力して、**enable secret** パスワードを変更します。次に、例を示します。

```
hostname(config)#enable secret cisco
```

13. 使用するすべてのインターフェイスに対して `no shutdown` コマンドを発行します。 [show ip interface brief](#) コマンドを発行して、必要なすべてのインターフェイスが `up up` と表示されることを確認します。
14. [config-register](#) `<configuration_register_setting>` と入力します。
`<configuration_register_setting>` の部分には、ステップ 2 で記録した値、または `0x2102` を入力します。次に、例を示します。

```
hostname(config)#config-register 0x2102
```
15. `Ctrl+Z` か `End` キーを押して、コンフィギュレーション モードを終了します。 `hostname#` プロンプトが表示されます。
16. [write memory](#) または `copy running-config startup-config` と入力して、変更を確定します。

[パスワード回復手順の例](#)

このセクションでは、パスワード回復手順の例を示します。この例は、Cisco 2900 シリーズ ISR を使用して作成されています。Cisco 2900 シリーズ ISR を使用していない場合でも、ご使用の製品での作業例として、この出力を利用できます。

```
Router>  
enable  
Password:  
Password:  
Password:  
% Bad secrets
```

```
Router>  
show version  
Cisco IOS Software, C2900 Software (C2900-UNIVERSALK9-M), Version 15.0(1)M1,  
  RELEASE SOFTWARE (fc1)  
Technical Support: http://www.cisco.com/techsupport  
Copyright (c) 1986-2009 by Cisco Systems, Inc.  
Compiled Wed 02-Dec-09 15:23 by prod_rel_team
```

```
ROM: System Bootstrap, Version 15.0(1r)M1, RELEASE SOFTWARE (fc1)
```

```
c2921-CCP-1-xfr uptime is 2 weeks, 22 hours, 15 minutes  
System returned to ROM by reload at 06:06:52 PCTime Mon Apr 2 1900  
System restarted at 06:08:03 PCTime Mon Apr 2 1900  
System image file is "flash:c2900-universalk9-mz.SPA.150-1.M1.bin"  
Last reload reason: Reload Command
```

This product contains cryptographic features and is subject to United States and local country laws governing import, export, transfer and use. Delivery of Cisco cryptographic products does not imply third-party authority to import, export, distribute or use encryption. Importers, exporters, distributors and users are responsible for compliance with U.S. and local country laws. By using this product you agree to comply with applicable laws and regulations. If you are unable to comply with U.S. and local laws, return this product immediately.

A summary of U.S. laws governing Cisco cryptographic products may be found at:
<http://www.cisco.com/wvl/export/crypto/tool/stqrg.html>

If you require further assistance please contact us by sending email to

export@cisco.com.

Cisco CISCO2921/K9 (revision 1.0) with 475136K/49152K bytes of memory.
Processor board ID FHH1230P04Y
1 DSL controller
3 Gigabit Ethernet interfaces
9 terminal lines
1 Virtual Private Network (VPN) Module
1 Cable Modem interface
1 cisco Integrated Service Engine-2(s)
Cisco Foundation 2.2.1 in slot 1
DRAM configuration is 64 bits wide with parity enabled.
255K bytes of non-volatile configuration memory.
248472K bytes of ATA System CompactFlash 0 (Read/Write)
62720K bytes of ATA CompactFlash 1 (Read/Write)

Technology Package License Information for Module:'c2900'

```

-----
Technology      Technology-package      Technology-package
                Current          Type                Next reboot
-----
ipbase          ipbasek9              Permanent          ipbasek9
security        securityk9            Permanent          securityk9
uc              uck9                  Permanent          uck9
data            datak9                Permanent          datak9

```

Configuration register is 0x2102

Router>

!--- Execute Steps 1 through 4 from Step-by-Step Procedure. ! rommon 1 > **confreg 0x2142**

You must reset or power cycle for new config to take effect

rommon 2 > **reset**

System Bootstrap, Version 15.0(1r)M1, RELEASE SOFTWARE (fc1)
Copyright (c) 2009 by cisco Systems, Inc.
TAC:Home:SW:IOS:Specials for info
C2900 platform with 524288 Kbytes of main memory

program load complete, entry point: 0x80008000, size: 0x6fdb4c

Self decompressing the image : #####

[OK]

Restricted Rights Legend

Use, duplication, or disclosure by the Government is subject to restrictions as set forth in subparagraph (c) of the Commercial Computer Software - Restricted Rights clause at FAR sec. 52.227-19 and subparagraph (c) (1) (ii) of the Rights in Technical Data and Computer Software clause at DFARS sec. 252.227-7013.

cisco Systems, Inc.

170 West Tasman Drive
San Jose, California 95134-1706

Cisco IOS Software, C2900 Software (C2900-UNIVERSALK9-M), Version 15.0(1)M1,
RELEASE SOFTWARE (fcl)

Technical Support: <http://www.cisco.com/techsupport>

Copyright (c) 1986-2009 by Cisco Systems, Inc.

Compiled Wed 02-Dec-09 15:23 by prod_rel_team

Cisco CISCO2921/K9 (revision 1.0) with 475136K/49152K bytes of memory.

Processor board ID FHH1230P04Y

1 DSL controller

3 Gigabit Ethernet interfaces

9 terminal lines

1 Virtual Private Network (VPN) Module

1 Cable Modem interface

1 cisco Integrated Service Engine-2(s)

Cisco Foundation 2.2.1 in slot 1

DRAM configuration is 64 bits wide with parity enabled.

255K bytes of non-volatile configuration memory.

248472K bytes of ATA System CompactFlash 0 (Read/Write)

62720K bytes of ATA CompactFlash 1 (Read/Write)

--- System Configuration Dialog ---

Would you like to enter the initial configuration dialog? [yes/no]: n

Press RETURN to get started!

00:00:19: %LINK-3-UPDOWN: Interface BRI0/0, changed state to up

00:00:19: %LINK-3-UPDOWN: Interface Ethernet0/0, changed state to up

00:00:19: %LINK-3-UPDOWN: Interface Ethernet0/1, changed state to up

00:00:19: %LINK-3-UPDOWN: Interface Serial0/0, changed state to down

00:00:19: %LINK-3-UPDOWN: Interface Serial0/1, changed state to down

00:00:20: %LINEPROTO-5-UPDOWN: Line protocol on Interface BRI0/0,
changed state to down

00:00:20: %LINEPROTO-5-UPDOWN: Line protocol on Interface Ethernet0/0,
changed state to up

Router>

00:00:20: %LINEPROTO-5-UPDOWN: Line protocol on Interface Ethernet0/1,
changed state to up

00:00:20: %LINEPROTO-5-UPDOWN: Line protocol on Interface Serial0/0,
changed state to down

00:00:20: %LINEPROTO-5-UPDOWN: Line protocol on Interface Serial0/1,
changed state to down

00:00:50: %SYS-5-RESTART: System restarted --

Cisco IOS Software, C2900 Software (C2900-UNIVERSALK9-M), Version 15.0(1)M1,
RELEASE SOFTWARE (fcl)

Technical Support: <http://www.cisco.com/techsupport>

Copyright (c) 1986-2009 by Cisco Systems, Inc.

Compiled Wed 02-Dec-09 15:23 by prod_rel_team

00:00:50: %LINK-5-CHANGED: Interface BRI0/0,
changed state to administratively down

00:00:52: %LINK-5-CHANGED: Interface Ethernet0/0,
changed state to administratively down

00:00:52: %LINK-5-CHANGED: Interface Serial0/0,
changed state to administratively down

00:00:52: %LINK-5-CHANGED: Interface Ethernet0/1,
changed state to administratively down

00:00:52: %LINK-5-CHANGED: Interface Serial0/1,
changed state to administratively down

00:00:53: %LINEPROTO-5-UPDOWN: Line protocol on Interface Ethernet0/0,
changed state to down

```

00:00:53: %LINEPROTO-5-UPDOWN: Line protocol on Interface Ethernet0/1,
changed state to down
Router>
Router>enable
Router#copy startup-config running-config
Destination filename [running-config]?
1324 bytes copied in 2.35 secs (662 bytes/sec)
Router#
00:01:24: %LINEPROTO-5-UPDOWN: Line protocol on Interface BRI0/0:1,
changed state to down
00:01:24: %LINEPROTO-5-UPDOWN: Line protocol on Interface BRI0/0:2,
changed state to down
Router#configure terminal
Enter configuration commands, one per line. End with CNTL/Z.
Router(config)#enable secret < password >
Router(config)#^Z
00:01:54: %SYS-5-CONFIG_I: Configured from console by console
Router#show ip interface brief

```

Interface	IP-Address	OK?	Method	Status	Protocol
Ethernet0/0	10.200.40.37	YES	TFTP	administratively down	down
Serial0/0	unassigned	YES	TFTP	administratively down	down
BRI0/0	193.251.121.157	YES	unset	administratively down	down
BRI0/0:1	unassigned	YES	unset	administratively down	down
BRI0/0:2	unassigned	YES	unset	administratively down	down
Ethernet0/1	unassigned	YES	TFTP	administratively down	down
Serial0/1	unassigned	YES	TFTP	administratively down	down
Loopback0	193.251.121.157	YES	TFTP	up	up

```

Router#configure terminal
Enter configuration commands, one per line. End with CNTL/Z.
Router(config)#interface Ethernet0/0
Router(config-if)#no shutdown
Router(config-if)#
00:02:14: %LINK-3-UPDOWN: Interface Ethernet0/0, changed state to up
00:02:15: %LINEPROTO-5-UPDOWN: Line protocol on Interface Ethernet0/0,
changed state to up
Router(config-if)#interface BRI0/0
Router(config-if)#no shutdown
Router(config-if)#
00:02:26: %LINK-3-UPDOWN: Interface BRI0/0:1, changed state to down
00:02:26: %LINK-3-UPDOWN: Interface BRI0/0:2, changed state to down
00:02:26: %LINK-3-UPDOWN: Interface BRI0/0, changed state to up
00:02:115964116991: %ISDN-6-LAYER2UP: Layer 2 for Interface BR0/0,
TEI 68 changed to up
Router(config-if)#^Z
Router#
00:02:35: %SYS-5-CONFIG_I: Configured from console by console
Router#copy running-config startup-config
Destination filename [startup-config]?
Building configuration...
[OK]
Router#show version
Cisco IOS Software, C2900 Software (C2900-UNIVERSALK9-M), Version 15.0(1)M1,
RELEASE SOFTWARE (fc1)
Technical Support: http://www.cisco.com/techsupport
Copyright (c) 1986-2009 by Cisco Systems, Inc.
Compiled Wed 02-Dec-09 15:23 by prod_rel_team

ROM: System Bootstrap, Version 15.0(1r)M1, RELEASE SOFTWARE (fc1)

c2921-CCP-1-xfr uptime is 2 weeks, 22 hours, 15 minutes
System returned to ROM by reload at 06:06:52 PCTime Mon Apr 2 1900
System restarted at 06:08:03 PCTime Mon Apr 2 1900
System image file is "flash:c2900-universalk9-mz.SPA.150-1.M1.bin"

```

Last reload reason: Reload Command

Cisco CISCO2921/K9 (revision 1.0) with 475136K/49152K bytes of memory.
Processor board ID FHH1230P04Y
1 DSL controller
3 Gigabit Ethernet interfaces
9 terminal lines
1 Virtual Private Network (VPN) Module
1 Cable Modem interface
1 cisco Integrated Service Engine-2(s)
Cisco Foundation 2.2.1 in slot 1
DRAM configuration is 64 bits wide with parity enabled.
255K bytes of non-volatile configuration memory.
248472K bytes of ATA System CompactFlash 0 (Read/Write)
62720K bytes of ATA CompactFlash 1 (Read/Write)

Configuration register is 0x2102

Router#**configure terminal**

Enter configuration commands, one per line. End with CNTL/Z.

Router(config)#**config-register 0x2102**

Router(config)#^Z

00:03:20: %SYS-5-CONFIG_I: Configured from console by console

Router#**show version**

Cisco IOS Software, C2900 Software (C2900-UNIVERSALK9-M), Version 15.0(1)M1,
RELEASE SOFTWARE (fc1)
Technical Support: <http://www.cisco.com/techsupport>
Copyright (c) 1986-2009 by Cisco Systems, Inc.
Compiled Wed 02-Dec-09 15:23 by prod_rel_team

ROM: System Bootstrap, Version 15.0(1r)M1, RELEASE SOFTWARE (fc1)

c2921-CCP-1-xfr uptime is 2 weeks, 22 hours, 15 minutes
System returned to ROM by reload at 06:06:52 PCTime Mon Apr 2 1900
System restarted at 06:08:03 PCTime Mon Apr 2 1900
System image file is "flash:c2900-universalk9-mz.SPA.150-1.M1.bin"
Last reload reason: Reload Command

Cisco CISCO2921/K9 (revision 1.0) with 475136K/49152K bytes of memory.
Processor board ID FHH1230P04Y
1 DSL controller
3 Gigabit Ethernet interfaces
9 terminal lines
1 Virtual Private Network (VPN) Module
1 Cable Modem interface
1 cisco Integrated Service Engine-2(s)
Cisco Foundation 2.2.1 in slot 1
DRAM configuration is 64 bits wide with parity enabled.
255K bytes of non-volatile configuration memory.
248472K bytes of ATA System CompactFlash 0 (Read/Write)
62720K bytes of ATA CompactFlash 1 (Read/Write)

Configuration register is 0x2142 (will be **0x2102** at next reload)

Router#

注: パスワードの回復機能が無効のときにパスワードを回復するには、「[パスワード回復サービスを実行しない](#)」の「[デバイスの回復](#)」セクションを参照してください。

[関連情報](#)

- [パスワード リカバリ手順](#)
- [コンソールおよび補助ポートに関するケーブル接続ガイド](#)
- [Catalyst スイッチのコンソール ポートに端末を接続する方法](#)
- [Catalyst 2948G-L3、4908G-L3、および 4840G シリーズ スイッチへの端末の接続](#)
- [テクニカル サポートとドキュメント – Cisco Systems](#)