

CSCwf67316(Field Notice 74035)용 APSP(Access Point Service Pack)

목차

이 포에서는 Field Notice 74035에 대한 APSP(Access Point Service Pack) 링크를 제공합니다. 이러한 APSP는 Cisco IOS® XE 17.3.7, 17.6.5 및 17.9.3에만 적용되며 17.3.8, 17.6.6 및 17.9.4 릴리스로 대체됩니다. APSP는 2800, 2800, 4800, 1560, IW6300, ESW6300 AP 시리즈에만 픽스를 제공합니다.

자세한 내용은 다음을 참조하십시오.

[필드 알림 74035](#)

[CSCwf67316: 2800/3800/4800/1560/IW6300은 CAC 시간 이후에 필요한 레벨에서 레이더를 탐지하지 못할 수 있습니다.](#)

릴리스	APSP 이미지	
17.3.7	<p>9800-40: https://software.cisco.com/download/home/286316412/type/286325254/release/17.3.7 이미지 이름: C9800-universalk9_wlc.17.03.07.CSCwf84244.SPA.apsp.bin</p> <p>9800-80: https://software.cisco.com/download/home/286321396/type/286325254/release/17.3.7 이미지 이름: C9800-universalk9_wlc.17.03.07.CSCwf84244.SPA.apsp.bin</p> <p>9800-L: https://software.cisco.com/download/home/286323430/type/286325254/release/17.3.7 이미지 이름: C9800-L-universalk9_wlc.17.03.07.CSCwf84244.SPA.apsp.bin</p> <p>9800-CL: https://software.cisco.com/download/home/286322605/type/286325254/release/17.3.7 이미지 이름: C9800-CL-universalk9.17.03.07.CSCwf84244.SPA.apsp.bin</p> <p>9800-SW(EWC-스위치): https://software.cisco.com/download/home/286313994/type/286325254/release/17.3.7</p>	https://www

	<p>이미지 이름: cat9k_iosxe.17.03.07.CSCwf84244.SPA.apsp.bin</p> <p>EWC C9105: https://software.cisco.com/download/home/286324858/type/286325254/release/17.3.7 이미지 이름: C9800-AP-universalk9.17.03.07.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9115: https://software.cisco.com/download/home/286321056/type/286325254/release/17.3.7 이미지 이름: C9800-AP-universalk9.17.03.07.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9117: https://software.cisco.com/download/home/286321061/type/286325254/release/17.3.7 이미지 이름: C9800-AP-universalk9.17.03.07.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9120: https://software.cisco.com/download/home/286323294/type/286325254/release/17.3.7 이미지 이름: C9800-AP-universalk9.17.03.07.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9124: https://software.cisco.com/download/home/286326614/type/286325254/release/17.3.7 이미지 이름: C9800-AP-universalk9.17.03.07.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9130: https://software.cisco.com/download/home/286323998/type/286325254/release/17.3.7 이미지 이름: C9800-AP-universalk9.17.03.07.CSCwf84244.SPA.apsp.zip</p>
--	---

17.6.5	<p>9800-40: https://software.cisco.com/download/home/286316412/type/286325254/release/17.6.5 이미지 이름: C9800-universalk9_wlc.17.06.05.CSCwf84244.SPA.apsp.bin</p> <p>9800-80: https://software.cisco.com/download/home/286321396/type/286325254/release/17.6.5 이미지 이름: C9800-universalk9_wlc.17.06.05.CSCwf84244.SPA.apsp.bin</p> <p>9800-L: https://software.cisco.com/download/home/286323430/type/286325254/release/17.6.5 이미지 이름: C9800-L-universalk9_wlc.17.06.05.CSCwf84244.SPA.apsp.bin</p> <p>9800-CL: https://software.cisco.com/download/home/286322605/type/286325254/release/17.6.5 이미지 이름: C9800-CL-universalk9.17.06.05.CSCwf84244.SPA.apsp.bin</p> <p>9800-SW(EWC-스위치): https://software.cisco.com/download/home/286313994/type/286325254/release/17.6.5 이미지 이름: cat9k_iosxe.17.06.05.CSCwf84244.SPA.apsp.bin</p>	https://www
--------	---	---------------------------------------

	<p>EWC C9105: https://software.cisco.com/download/home/286324858/type/286325254/release/17.6.5 이미지 이름: C9800-AP-universalk9.17.06.05.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9115: https://software.cisco.com/download/home/286321056/type/286325254/release/17.6.5 이미지 이름: C9800-AP-universalk9.17.06.05.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9117: https://software.cisco.com/download/home/286321061/type/286325254/release/17.6.5 이미지 이름: C9800-AP-universalk9.17.06.05.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9120: https://software.cisco.com/download/home/286323294/type/286325254/release/17.6.5 이미지 이름: C9800-AP-universalk9.17.06.05.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9124: https://software.cisco.com/download/home/286326614/type/286325254/release/17.6.5 이미지 이름: C9800-AP-universalk9.17.06.05.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9130: https://software.cisco.com/download/home/286323998/type/286325254/release/17.6.5 이미지 이름: C9800-AP-universalk9.17.06.05.CSCwf84244.SPA.apsp.zip</p>	
17.9.3	<p>9800-40: https://software.cisco.com/download/home/286316412/type/286325254/release/17.9.3 이미지 이름: C9800-universalk9_wlc.17.09.03.CSCwf84244.SPA.apsp.bin</p> <p>9800-80: https://software.cisco.com/download/home/286321396/type/286325254/release/17.9.3 이미지 이름: C9800-universalk9_wlc.17.09.03.CSCwf84244.SPA.apsp.bin</p> <p>9800-L: https://software.cisco.com/download/home/286323430/type/286325254/release/17.9.3 이미지 이름: C9800-L-universalk9_wlc.17.09.03.CSCwf84244.SPA.apsp.bin</p> <p>9800-CL: https://software.cisco.com/download/home/286322605/type/286325254/release/17.9.3 이미지 이름: C9800-CL-universalk9.17.09.03.CSCwf84244.SPA.apsp.bin</p> <p>9800-SW(EWC-스위치): https://software.cisco.com/download/home/286313994/type/286325254/release/17.9.3 이미지 이름: cat9k_iosxe.17.09.03.CSCwf84244.SPA.apsp.bin</p> <p>EWC C9105: https://software.cisco.com/download/home/286324858/type/286325254/release/17.9.3 이미지 이름: C9800-AP-universalk9.17.09.03.CSCwf84244.SPA.apsp.zip</p>	https://www

EWC C9115:

<https://software.cisco.com/download/home/286321056/type/286325254/release/17.9.3>

이미지 이름: [C9800-AP-universalk9.17.09.03.CSCwf84244.SPA.apsp.zip](#)

EWC C9117:

<https://software.cisco.com/download/home/286321061/type/286325254/release/17.9.3>

이미지 이름: [C9800-AP-universalk9.17.09.03.CSCwf84244.SPA.apsp.zip](#)

EWC C9120:

<https://software.cisco.com/download/home/286323294/type/286325254/release/17.9.3>

이미지 이름: [C9800-AP-universalk9.17.09.03.CSCwf84244.SPA.apsp.zip](#)

EWC C9124:

<https://software.cisco.com/download/home/286326614/type/286325254/release/17.9.3>

이미지 이름: [C9800-AP-universalk9.17.09.03.CSCwf84244.SPA.apsp.zip](#)

EWC C9130:

<https://software.cisco.com/download/home/286323998/type/286325254/release/17.9.3>

이미지 이름: [C9800-AP-universalk9.17.09.03.CSCwf84244.SPA.apsp.zip](#)

이 번역에 관하여

Cisco는 전 세계 사용자에게 다양한 언어로 지원 콘텐츠를 제공하기 위해 기계 번역 기술과 수작업 번역을 병행하여 이 문서를 번역했습니다. 아무리 품질이 높은 기계 번역이라도 전문 번역가의 번역 결과물만큼 정확하지는 않습니다. Cisco Systems, Inc.는 이 같은 번역에 대해 어떠한 책임도 지지 않으며 항상 원본 영문 문서(링크 제공됨)를 참조할 것을 권장합니다.