

Product Bulletin, No. 2025

Cisco IOS Early Deployment Release 12.2(11)YZ

Introduction

This Product Bulletin describes the content and delivery information concerning Cisco IOS[®] software release 12.2(11)YZ. This is a special release that is focused on support for Cisco 7301 Series and the Cisco 7304 Series routers . For more information about the Cisco IOS software release process, please see Product Bulletin #537 at:

http://www.cisco.com/warp/public/cc/pd/iosw/iore/prodlit/537_pp.htm

Before deploying a new software release in a production network, always consult the appropriate product-specific documentation, release notes, and field notices, refer to the online defect tracking system, and perform acceptance testing in your own test environment.

New Features in Cisco IOS Release 12.2(11)YZ

Detailed information about features delivered in Cisco IOS Release 12.2(11)YZ are described in the 12.2(11)YZ release notes:

<http://www.cisco.com/univercd/cc/td/doc/product/software/ios122/122relnt/7000/rn7000yz.htm>

Migration Guide

Release 12.2(11)YZ is parented off of Release 12.2(11)S. Table 1 below identifies the recommended migration path.

Table 1: Cisco IOS 12.2(11)YZ Migration Guide Functionality in This Release	Will Be Available Next in
12.2(11)YZ	12.2(3rd)S

Support

Cisco IOS software release 12.2(11)YZ follows the standard Cisco support policy as indicated in the following link.

<http://www.cisco.com/warp/public/437/27.html>

Product Numbers

Table 2 describes the available feature sets, product ordering codes, image names, and memory requirements for Cisco IOS software Release 12.2(11)YZ.

Table 2: Cisco IOS Release 12.2(11)YZ Feature Sets, Ordering Codes, and Memory Requirements Software Product Description	Image Name	Product Code	Flash	DRAM
Cisco 7300 Series IOS IP PLUS	c7300-is-mz	S73Z-12211YZ	64 MB	128 MB
Cisco 7300 Series IOS ENTERPRISE	c7300-js-mz	S73A-12211YZ	64 MB	128 MB
Cisco 7301 Series IOS IP/FW/IDS IPSEC 3DES	c7301-ik9o3s-mz	S730CHK2-12211YZ	20 MB	128 MB
Cisco 7301 Series IOS IP PLUS IPSEC 3DES	c7301-ik9s-mz	S730CK2-12211YZ	20 MB	128 MB
Cisco 7301 Series IOS IP	c7301-is-mz	S730C-12211YZ	20 MB	128 MB
Cisco 7301 IOS Enterprise/FW/IDS IPSEC 3DES	c7301-jk9o3s-mz	S730AHK2-12211YZ	20 MB	128 MB
Cisco 7301 IOS Enterprise	c7301-js-mz	S730A-12211YZ	20 MB	128 MB

Cisco 7301 IOS SP SSH 3DES	c7301- k9p-mz	S730CHK2- 12211YZ	20 MB	128 MB
Cisco 7301 IOS SERVICE PROVIDER	C7301- p-mz	S730Z- 12211YZ	20MB	128MB

For more detailed information about feature sets, images, and memory recommendations for Cisco IOS Release 12.2(11)YZ, please refer to the release notes at:

<http://www.cisco.com/univercd/cc/td/doc/product/software/ios122/122relnt/7000/rn7000yz.htm>

Download Information

Customers can download Cisco IOS Release 12.2(11)YZ software by using the IOS Upgrade Planner located in the Software Center on <http://www.cisco.com> :

<http://www.cisco.com/public/sw-center/sw-ios.shtml>



Corporate Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA

www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands

www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA

www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
Capital Tower
168 Robinson Road
#22-01 to #29-01
Singapore 068912

www.cisco.com
Tel: +65 317 7777
Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the

Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2002, Cisco Systems, Inc. All rights reserved. CCIP, the Cisco Arrow logo, the Cisco *Powered* Network mark, the Cisco Systems Verified logo, Cisco Unity, Follow Me Browsing, FormShare, Internet Quotient, iQ Breakthrough, iQ Expertise, iQ FastTrack, the iQ logo, iQ Net Readiness Scorecard, Networking Academy, ScriptShare, SMARTnet, TransPath, and Voice LAN are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, Discover All That's Possible, The Fastest Way to Increase Your Internet Quotient, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, Fast Step, GigaStack, IOS, IP/TV, LightStream, MGX, MICA, the Networkers logo, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, SlideCast, StrataView Plus, Stratum, SwitchProbe, TeleRouter, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0206R)